

7030 Ryburn Dr. Millington, TN Phone: (901) 873-5300 Fax: (901) 873-5301 <u>www.gohispeed.com</u>

January 20, 2022

Carl Singleton Big River Steel Osceola, AR

Carl,

The following is a summary of findings from the vibration analysis performed on 1/20/2022 on the Fumes Extraction DFF Exhaust Fan and the Final Pot Cooling Section Zone 2 Fan. Both Units were checked at 100 % speed and 50-75 % speed. No significant vibration was found during our testing.

QualiTest® uses a four step rating system for defects.

<u>Class I:</u> Defect is present, but effect on reliability is not clear; no immediate action is required. Continue to normally monitor.

<u>Class II:</u> Defect (s) present that may cause problem in long term (2-6 months). Repair during normal maintenance scheduling. Continue to monitor.

<u>Class III</u>; Defect (s) present that may cause failure in short term (less than 2 months). This should be addressed as soon as practical, with a high maintenance priority. Increase monitoring frequency.

<u>Class IV</u>; Defect (s) present that makes continued reliability unpredictable, and possibility of secondary damage is high. Repairs should be made ASAP. An unscheduled shutdown should be considered for repairs

Hi-Speed **Industrial Service** tests and inspects industrial machinery and equipment and makes recommendations concerning maintenance and repairs based on its experience in the field of industrial repair and maintenance. The information contained herein is provided as an opinion only, not as a guaranty or warranty of the matters discussed herein.

Summary

Fumes Extraction DFF Exhaust Fan

Spectral data of the motor and fan showed no significant issues to note. There does appear to be a dominant vibration at 1 x rpm in the vertical direction on the motor and fan with slightly higher amplitude in the fan bearing section. This vibration was present at both 75 and 100 % speed. This is likely a structural issue and may be caused by rigid dampeners. Ensure that this unit has the correct rubber dampeners installed under base frame. Rated as a **CLASS I** defect.

Final Pot Cooling Section Zone 2 Fan

This unit had very little vibration at 50, 75, and 100% speed. No issues to note here.

Please note that the following amplitudes were with each unit at 100% speed.

Abbreviated Last Measurement Summary

MEASUREMENT POINT	OVERALL LEVEL	•
FEXDFFEXHF - FUMES EXTRACTION DFF EXH FAN	•	
	OVERALL LEVEL	
MOH - MOTOR OUTBOARD HORIZONTAL		
MOV - MOTOR OUTBOARD VERTICAL	.116 In/Sec	
	.071 In/Sec	
MIV - MOTOR INBOARD VERTICAL	.153 In/Sec	
	.138 In/Sec	.460 G-s
EIA - EQUIPMENT INBOARD AXIAL	.123 In/Sec	.184 G-s
EIH - EQUIPMENT INBOARD HORIZONTAL		
EIV - EQUIPMENT INBOARD VERTICAL	.159 In/Sec	.215 G-s
EOH - EQUIPMENT OUTBOARD HORIZONTAL		
EOV - EQUIPMENT OUTBOARD VERTICAL	.191 In/Sec	.182 G-s
MEASUREMENT POINT	OVERALL LEVEL	HFD / VHFD
FNLPTCLSZ2 - FINAL POT COOL SECT. ZONE 2	(20-Jan-22) OVERALL LEVEL	17 00211-
	.080 In/Sec	
MOV - MOTOR OUTBOARD VERTICAL	.086 In/Sec	
MIH - MOTOR INBOARD HORIZONTAL	•	
MIV - MOTOR INBOARD VERTICAL	.052 In/Sec	
MIA - MOTOR INBOARD AXIAL	.079 In/Sec	.593 G-s

Clarification Of Vibration Units:

Acc --> G-s RMS Vel --> In/Sec PK As always, it has been a pleasure to serve Big River Steel. If there are any comments or questions, do not hesitate to contact us.

Sincerely,

ISO Certified Vibration Analyst, Category III

Kevin W. Maxwell



QualiTest_® Diagnostics

Cell: 901-486-4565

Email: kwilliam@gohispeed.com