



AC Recondition As Found
ARKANSAS INDUSTRIAL MACHINERY
3804 N. NONA ST
NORTH LITTLE ROCK, AR 72118

FolderID: 100379
FormID: 14698399

AC Recondition - Rev. 2

Location: Shop

Serial Number:

Description: 75KW ABB

Hi-Speed Job Number: 100379

Manufacturer: ABB

HP/kW: 75 (kW)

Voltage: 460

Phase: Three

Hz: 60 (Hz)

Service Factor: 1.15

Enclosure: TEFC

J-box Included: Complete

Bearing RTDs: No

Stator RTDs: No

Repair Stage: Teardown Inspection

Heaters: No

Winding Type : Random Wound

Bearing Type: Rolling Element

Priorities Found: ● 2 - High

● 6 - Good

Overall Condition



1. Report Date

2. Nameplate Picture

P21




3. Photos of all six sides of the machine.


P27













4. Describe the Overall Condition of the Equipment as Received
Saturated with oil.

5. Distance from the end of the shaft to the Coupling/Sheave **0 inches**

Initial Mechanical/Electrical



6. Does Shaft Turn Freely? **(No) No**

7. Does Shaft Have Visible Damage? **(Yes) Yes**

P12



8. Assembled Shaft Runout

9. Assembled Shaft End Play

10. Air Gap Variation <10%






11. Lead Condition **(P) Pass**

P32



12. Lead Length **12 Inches**

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

13.	Frame Condition			serviceable
● 14.	Fan Condition			(P) Pass
15.	Broken or Missing Components			
Initial Electrical Inspection				
16.	Insulation Resistance/Megger			0 Megohms
17.	Winding Resistance			
	1-2	1-3	2-3	
● 18.	Perform Surge Test			(NA) Not Applicable
19.	Stator Condition			core damaged and coils require rewind. P39
				
Mechanical Inspection				
20.	Drive End Bearing Number-			NU 213
21.	Drive End Bearing Qty.			1
22.	Drive End Bearing Type			(Roller) Roller Bearing
23.	Drive End Lubrication Type			(Oil) Oil Lubricated
24.	Drive End Bearing Insulation or Grounding Device?			none
25.	Drive End Wavy Washer/Snap-Ring Other Retention Device?			none
26.	Drive End Bearing Condition			complete bearing failure. P43
				



28. Opposite Drive End Bearing Qty.	1
29. Opposite Drive End Bearing Type	(Ball) Ball Bearing
30. Opposite Drive End Lubrication Type	(Grease) Grease Lubricated
31. Opposite Drive End Bearing Insulation or Grounding Device?	none
32. Opposite Drive End Wavy Washer/Snap-Ring Other Retention Device?	none
33. Opposite Drive End Bearing Condition	replace
34. Drive End Seal	destroyed
35. Opposite Drive End Seal	

Rotor Inspection

36. Rotor Type/Material	(Squirrel Aluminum) Squirrel Cage Aluminum Die Cast
37. Growler Test	(Pass) Pass
38. Number of Rotor Bars	
39. Rotor Condition	serviceable
40. List the Parts needed for the Repair Below	
41. Signature of Technician that Disassembled Motor	Terrence. Holland

Mechanical Fits- Rotor

42. Shaft Runout		
43. Rotor Runout		
Drive End Bearing Fit	Rotor Body	Opposite Drive End Bearing
44. Coupling Fit Closest to Bearing Housing		
0 Degrees	90 Degrees	120 Degrees
45. Coupling Fit Closest to the end of the Shaft		
0 Degrees	60 Degrees	120 Degrees

46.	Drive End Bearing Shaft Fit			
	0 Degrees	60 Degrees	120 Degrees	
	2.5598	2.5597	2.5597	
	Pass			
47.	Drive End Bearing Shaft Fit Condition			(P) Pass
48.	Opposite Drive End Bearing Shaft Fit			
	0 Degrees	60 Degrees	120 Degrees	
	2.953	2.9532	2.9531	
49.	Opposite Drive End Bearing Shaft Fit Condition			(P) Pass
50.	Shaft Air Seal Fits			
	Drive End Air Seal	Opposite Drive End Air Seal		
Mechanical Fits- Bearing Housings				
51.	Drive End - Endbell Bearing Fit			
	0 Degrees	60 Degrees	120 Degrees	
	4.7498	4.7499	4.7499	
52.	Drive End - Endbell Bearing Fit Condition			(P) Pass
53.	Opposite Drive End - Endbell Bearing Fit			P18
	0 Degrees	60 Degrees	120 Degrees	
	Excessive wear			
				
54.	Opposite Drive End - Endbell Bearing Fit Condition			(F) Fail P22
				

55. Bearing Cap Condition

P30

Drive End Bearing Cap

Opposite Drive End Bearing Cap

none

pass



56. End Bell Air Seal Fits

Drive End Air Seal

Opposite Drive End Air Seal

57. List Machine Work Needed Below

P37

D.e. Shaft has excessive wear on seal surface spacer.D.e. Housing require sleeve for air seal fit.



58. Technician

Terrenc Holland

Lu 2/11/21

Root Cause of Failure



P6

59. Failure locations

D.e. Bottom center stator core damaged. D.e shoulder for seal surface spacer damaged. Sleeve needed on D.e housing.



60. Root cause of failure

D.e. Bearing race heated up and expanded. This caused a loose fit on the shaft allowing the race to move causing the rotor to drop onto the stator core which took out the windings. Recommend snap ring groove and retainer if repaired.