



AC Recondition As Found

Union Pacific-Vine St 10945

1020 N. Vine Street

North Little Rock, AR

FolderID: 100431
FormID: 14797385

AC Recondition - Rev. 2

Location: Shop

Serial Number: Q2-D15T5728GPE

Description: 50HP SIEMENS 3600RPM 326TS

Hi-Speed Job Number: 100431

Manufacturer: Siemens

Product Number: 1LE22213BA216AA3

Serial Number: Q2-D15T5728GPE

HP/kW: 50 (HP)

RPM: 3535 (RPM)

Frame: 326TS

Voltage: 230 / 460

Current: 110/55

Phase: Three

Hz: 60 (Hz)

Service Factor: 1.15

Enclosure: TEFC

J-box Included: Half

Coupling/Sheave: Coupling

Bearing RTDs: No

Stator RTDs: No

Repair Stage: Teardown Inspection

Heaters: No

Winding Type : Random Wound

Bearing Type: Rolling Element

Priorities Found: ● 3 - High

● 5 - Good

Overall Condition



1. Report Date

2. Nameplate Picture


P21



3. Photos of all six sides of the machine.

P27

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.









4. Describe the Overall Condition of the Equipment as Received
Serviceable

5. Distance from the end of the shaft to the Coupling/Sheave **0.375 inches**

P40



Initial Mechanical/Electrical



6. Does Shaft Turn Freely? **(Yes) Yes**

7. Does Shaft Have Visible Damage? **(No) No**

P12



8. Assembled Shaft Runout **0.001 Inches**

9. Assembled Shaft End Play **inches**

10. Air Gap Variation <10%

11. Lead Condition **(P) Pass**

12. Lead Length **15 Inches**

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

13. Frame Condition

pass

14. Fan Condition

P54



15. Broken or Missing Components


D.E. coupling

P58



Initial Electrical Inspection





17. Winding Resistance

1-2


1-3

2-3

● 18. Perform Surge Test

(P) Pass

P35



19. Stator Condition

pass

P39



Mechanical Inspection



20. Drive End Bearing Number-

6312

P8



21. Drive End Bearing Qty.

1

P16



22. Drive End Bearing Type

(Ball) Ball Bearing

23. Drive End Lubrication Type

(Grease) Grease Lubricated

24. Drive End Bearing Insulation or Grounding Device?

none

25. Drive End Wavy Washer/Snap-Ring Other Retention Device?

none

26. Drive End Bearing Condition

replace



27. Opposite Drive End Bearing Number-

6210

P47

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.



28.	Opposite Drive End Bearing Qty.	1	
29.	Opposite Drive End Bearing Type	(Ball) Ball Bearing	
30.	Opposite Drive End Lubrication Type	(Grease) Grease Lubricated	
31.	Opposite Drive End Bearing Insulation or Grounding Device?	none	
32.	Opposite Drive End Wavy Washer/Snap-Ring Other Retention Device?	yes	P56
			
33.	Opposite Drive End Bearing Condition	replace	
34.	Drive End Seal	lip seal	
35.	Opposite Drive End Seal	none	
Rotor Inspection			






- | | |
|---|------------------|
| 37. Growler Test | (Pass) Pass |
| 38. Number of Rotor Bars | |
| 39. Rotor Condition | pass |
| 40. List the Parts needed for the Repair Below | |
| 41. Signature of Technician that Disassembled Motor | Terrence Holland |

Mechanical Fits- Rotor

- | | |
|--|-----------------------------|
| 42. Shaft Runout | 0.001 inches |
| 43. Rotor Runout | |
| Drive End Bearing Fit | Rotor Body |
| 0 Degrees | 120 Degrees |
| 44. Coupling Fit Closest to Bearing Housing | |
| 0 Degrees | 120 Degrees |
| 45. Coupling Fit Closest to the end of the Shaft | |
| 0 Degrees | 120 Degrees |
| 46. Drive End Bearing Shaft Fit | |
| 0 Degrees | 120 Degrees |
| 2.363 | 2.3629 |
| 47. Drive End Bearing Shaft Fit Condition | (P) Pass |
| 48. Opposite Drive End Bearing Shaft Fit | |
| 0 Degrees | 120 Degrees |
| 1.969 | 1.9692 |
| 49. Opposite Drive End Bearing Shaft Fit Condition | (P) Pass |
| 50. Shaft Air Seal Fits | |
| Drive End Air Seal | Opposite Drive End Air Seal |

Mechanical Fits- Bearing Housings



51.	Drive End - Endbell Bearing Fit		
	0 Degrees	60 Degrees	120 Degrees
	5.1194	5.1196	
	Max allowed is 5.1191		
52.	Drive End - Endbell Bearing Fit Condition		(F) Fail
53.	Opposite Drive End - Endbell Bearing Fit		
	0 Degrees	60 Degrees	120 Degrees
	3.5445	3.5444	3.5444
	Max allowed is 3.5442		
54.	Opposite Drive End - Endbell Bearing Fit Condition		(F) Fail
55.	Bearing Cap Condition		P30
	Drive End Bearing Cap	Opposite Drive End Bearing Cap	
	pass		
<div style="display: flex; justify-content: space-around;">   </div>			
56.	End Bell Air Seal Fits		
	Drive End Air Seal	Opposite Drive End Air Seal	
57.	List Machine Work Needed Below		
	Re-sleeve both end bell housing fits.		
58.	Technician		Terrence Holland
			
Root Cause of Failure			
59.	Failure locations		
	Housing fits		
60.	Root cause of failure		
	Excessive wear		