



AC Recondition As Found

3M-Main Plant (10001)

310 Walter Road

Little Rock, AR 72216

FolderID: 100625
FormID: 15358836

AC Recondition - Rev. 2

Location: MOTOR SHOP LR

Serial Number: OLG094023

Description: 100HP GE 1800RPM 405T

Hi-Speed Job Number: 100625

Manufacturer: GE

Product Number: 5KS405SS2C6D11

Serial Number: OLG094023

HP/kW: 100 (HP)

RPM: 1790 (RPM)

Frame: 405T

Voltage: 460

Current: 113

Phase: Three

Hz: 60 (Hz)

Service Factor: 1.0

Enclosure: TEFC

J-box Included: Complete

Coupling/Sheave: None

Bearing RTDs: No

Stator RTDs: No

Repair Stage: Teardown Inspection

Heaters: No

Winding Type : Random Wound

Bearing Type: Rolling Element

Priorities Found: ● 4 - High

● 2 - Good

Overall Condition



1. Report Date

2. Nameplate Picture

P20



3. Photos of all six sides of the machine.

P27

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.





4. Describe the Overall Condition of the Equipment as Received

Initial Mechanical/Electrical



5. Does Shaft Turn Freely? (No) No
6. Does Shaft Have Visible Damage? (Yes) Yes

P11





7. Assembled Shaft Runout
8. Assembled Shaft End Play
9. Air Gap Variation <10%
10. Lead Condition

P32



- | | |
|---------------------|----------|
| 11. Lead Length | 8 Inches |
| 12. Frame Condition | pass |
| 13. Fan Condition | |

P54




- | |
|----------------------------------|
| 14. Broken or Missing Components |
|----------------------------------|

Initial Electrical Inspection



- | | |
|----------------------------------|--------------|
| 15. Insulation Resistance/Megger | 0.01 Megohms |
| 16. Winding Resistance | |
| 1-2 | 1-3 |
| | 2-3 |
| 17. Perform Surge Test | (F) Fail |
| 18. Number of Stator Slots | |



Mechanical Inspection



20. Drive End Bearing Number-

6316

P8



21. Drive End Bearing Qty.

1

22. Drive End Bearing Type

(Ball) Ball Bearing

23. Drive End Lubrication Type

(Grease) Grease Lubricated

24. Drive End Bearing Insulation or Grounding Device?

none

25. Drive End Wavy Washer/Snap-Ring Other Retention Device?

none

26. Drive End Bearing Condition

cage destroyed

P42



27. Opposite Drive End Bearing Number-

6316

28. Opposite Drive End Bearing Qty.

1

29. Opposite Drive End Bearing Type

(Ball) Ball Bearing

P51



30. Opposite Drive End Lubrication Type

(Grease) Grease Lubricated

31. Opposite Drive End Bearing Insulation or Grounding Device?

none

32. Opposite Drive End Wavy Washer/Snap-Ring Other Retention Device?

yes

P56



33. Opposite Drive End Bearing Condition

replace

34. Drive End Seal

35. Opposite Drive End Seal

Rotor Inspection



Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.



- | | |
|---|------------------|
| 37. Growler Test | (Pass) Pass |
| 38. Number of Rotor Bars | |
| 39. Rotor Condition | pass |
| 40. List the Parts needed for the Repair Below | |
| 41. Signature of Technician that Disassembled Motor | Terrence Holland |




Terrence Holland

Mechanical Fits- Rotor

- | | |
|--|-----------------------------|
| 42. Shaft Runout | 0.002 inches |
| 43. Rotor Runout | |
| Drive End Bearing Fit | Rotor Body |
| 0 Degrees | 120 Degrees |
| 44. Coupling Fit Closest to Bearing Housing | |
| 0 Degrees | 120 Degrees |
| 45. Coupling Fit Closest to the end of the Shaft | |
| 0 Degrees | 120 Degrees |
| 46. Drive End Bearing Shaft Fit | |
| 0 Degrees | 120 Degrees |
| 3.1497 | 3.1498 |
| 47. Drive End Bearing Shaft Fit Condition | (P) Pass |
| 48. Opposite Drive End Bearing Shaft Fit | |
| 0 Degrees | 120 Degrees |
| 2.1498 | 3.145 |
| 49. Opposite Drive End Bearing Shaft Fit Condition | (P) Pass |
| 50. Shaft Air Seal Fits | |
| Drive End Air Seal | Opposite Drive End Air Seal |

Mechanical Fits- Bearing Housings



51.	Drive End - Endbell Bearing Fit		
	0 Degrees	60 Degrees	120 Degrees
	<div> <div></div> Pitted </div>		
52.	Drive End - Endbell Bearing Fit Condition		(F) Fail
53.	Opposite Drive End - Endbell Bearing Fit		
	0 Degrees	60 Degrees	120 Degrees
54.	Opposite Drive End - Endbell Bearing Fit Condition		(F) Fail
	<div> <div></div> Pitted </div>		
55.	Bearing Cap Condition		P30
	Drive End Bearing Cap	Opposite Drive End Bearing Cap	
	pass	pass	
<div>   </div>			
56.	End Bell Air Seal Fits		
	Drive End Air Seal	Opposite Drive End Air Seal	
57.	List Machine Work Needed Below		
	Re-sleeve both end bell housing fits.		
58.	Technician		Terrence Holland
			
Root Cause of Failure			
59.	Failure locations		
	Bottom of stator iron between slots. Both housing fits.		

Coil to coil short between slots caused by D.E bearing cage failure. Bearing grease was hardened and contaminated.

