



AC Recondition As Found

Sage V Foods

5901 SLOAN DRIVE
LITTLE ROCK, AR 72206

FolderID: 100753
FormID: 15663188

AC Recondition - Rev. 2

Location: MOTOR SHOP LR
Serial Number: EF5T46663N-F4-10-01/21
Description: 0.5HP SWECO 1200RPM 143TZX

| | |
|----------------------|------------------------|
| Hi-Speed Job Number: | 100753 |
| Manufacturer: | US Motors/Nidec |
| Serial Number: | EF5T46663N-F4-10-01/21 |
| HP/kW: | 0.5 (HP) |
| RPM: | 1160 (RPM) |
| Frame: | 143TZX |
| Voltage: | 460 |
| Current: | 1.45 |
| Phase: | Three |
| Hz: | 60 (Hz) |
| Service Factor: | 1.00 |
| Enclosure: | TENV |
| J-box Included: | Complete |
| Coupling/Sheave: | None |
| Bearing RTDs: | No |
| Stator RTDs: | No |
| Repair Stage: | Teardown Inspection |
| Heaters: | No |
| Winding Type : | Random Wound |
| Bearing Type: | Rolling Element |

Priorities Found: ● 1 - High ● 5 - Good

Overall Condition



1. Report Date
2. Nameplate Picture

P20



3. Photos of all six sides of the machine.

P27

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.







4. Describe the Overall Condition of the Equipment as Received
Serviceable

Initial Mechanical/Electrical



5. Does Shaft Turn Freely? (No) No
6. Does Shaft Have Visible Damage? (No) No P11



7. Assembled Shaft Runout
8. Assembled Shaft End Play
9. Air Gap Variation <10%



| | |
|----------------------------------|--------|
| 12. Frame Condition | pass |
| 13. Fan Condition | (N) NA |
| 14. Broken or Missing Components | |

Initial Electrical Inspection




| | | |
|------------------------|-----|-----|
| 16. Winding Resistance | | |
| 1-2 | 1-3 | 2-3 |

17. Perform Surge Test

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

| | | | |
|--|--|---|-----|
| 18. | Number of Stator Slots | | |
| 19. | Stator Condition | | |
| Mechanical Inspection | | | |
| 20. | Drive End Bearing Number- | 22308 E/C3 | P8 |
|  | | | |
| 21. | Drive End Bearing Qty. | 1 | |
| 22. | Drive End Bearing Type | (Roller) Roller Bearing | |
| 23. | Drive End Lubrication Type | (Grease) Grease Lubricated | |
| 24. | Drive End Bearing Insulation or Grounding Device? | none | |
| 25. | Drive End Wavy Washer/Snap-Ring Other Retention Device? | | |
| 26. | Drive End Bearing Condition | replace | |
| 27. | Opposite Drive End Bearing Number- | NU 307 ECP/C3 | P47 |
|  | | | |
| 28. | Opposite Drive End Bearing Qty. | 1 | |
| 29. | Opposite Drive End Bearing Type | | |
| 30. | Opposite Drive End Lubrication Type | (Grease) Grease Lubricated | |
| 31. | Opposite Drive End Bearing Insulation or Grounding Device? | none | |
| 32. | Opposite Drive End Wavy Washer/Snap-Ring Other Retention Device? | none | |
| 33. | Opposite Drive End Bearing Condition | replace | |
| 34. | Drive End Seal | National: 340853. s-3188 | |
| 35. | Opposite Drive End Seal | National: 340853. s-3188 | |
| Rotor Inspection | | | |
| 36. | Rotor Type/Material | (Squirrel Aluminum) Squirrel Cage Aluminum Die Cast | |
| 37. | Growler Test | | |

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

| | | | |
|---|---|--------------------------------|----------------------------|
| 38. | Number of Rotor Bars | | |
| 39. | Rotor Condition pass | | |
| 40. | List the Parts needed for the Repair Below <i>2 seals: National: 340853. NU bearing: 307 ECP/C3 & 22308.</i> | | |
| 41. | Signature of Technician that Disassembled Motor | | Terrence Holland |
|  | | | |
| Mechanical Fits- Rotor | | | |
| 42. | Shaft Runout 0.001 inches | | |
| 43. | Rotor Runout | | |
| | Drive End Bearing Fit | Rotor Body | Opposite Drive End Bearing |
| 44. | Coupling Fit Closest to Bearing Housing | | |
| | 0 Degrees | 90 Degrees | 120 Degrees |
| 45. | Coupling Fit Closest to the end of the Shaft | | |
| | 0 Degrees | 60 Degrees | 120 Degrees |
| 46. | Drive End Bearing Shaft Fit | | |
| | 0 Degrees | 60 Degrees | 120 Degrees |
| | 1.5749 | 1.5749 | 1.5749 |
| 47. | Drive End Bearing Shaft Fit Condition (P) Pass | | |
| 48. | Opposite Drive End Bearing Shaft Fit | | |
| | 0 Degrees | 60 Degrees | 120 Degrees |
| | 1.3789 | 1.3789 | 1.3789 |
| 49. | Opposite Drive End Bearing Shaft Fit Condition (P) Pass | | |
| 50. | Shaft Air Seal Fits | | |
| | Drive End Air Seal | Opposite Drive End Air Seal | |
| Mechanical Fits- Bearing Housings | | | |
| 51. | Drive End - Endbell Bearing Fit | | |
| | 0 Degrees | 60 Degrees | 120 Degrees |
| | 3.5419 | 3.5419 | 3.5419 |
| 52. | Drive End - Endbell Bearing Fit Condition (P) Pass | | |
| 53. | Opposite Drive End - Endbell Bearing Fit | | |
| | 0 Degrees | 60 Degrees | 120 Degrees |
| | 3.1497 | 3.1497 | 3.1497 |
| 54. | Opposite Drive End - Endbell Bearing Fit Condition (P) Pass | | |
| 55. | Bearing Cap Condition | | |
| | Drive End Bearing Cap | Opposite Drive End Bearing Cap | |
| 56. | End Bell Air Seal Fits | | |
| | Drive End Air Seal | Opposite Drive End Air Seal | |

57. List Machine Work Needed Below

None

58. Technician

Terrence Holland

A handwritten signature in black ink, appearing to read 'Terrence Holland', is written across the line.

Root Cause of Failure

59. Failure locations

D.E. Bearing locked up from contaminated grease.

60. Root cause of failure

Bearing grease contaminated.