



AC Recondition As Found

Peco Foods

625 S. Allen Street
Batesville, AR 72501

FolderID: 100782
FormID: 15704198

AC Recondition - Rev. 2

Location: Shop

Serial Number: F1807101170

Description: 5HP BALDOR 1800RPM 184JM
MEMPHIS PUMP MPAL-300-500TEBF
184647

Hi-Speed Job Number: 100782

Manufacturer: Baldor

Product Number: EJMM3615T

Spec/ID #: 36H017S268G1

Serial Number: F1807101170

HP/kW: 5 (HP)

RPM: 1750 (RPM)

Frame: 184JM

Voltage: 230 / 460

Current: 13.4/6.7

Phase: Three

Hz: 60 (Hz)

Service Factor: 1.15

Enclosure: TEFC

J-box Included: Complete

Coupling/Sheave: Propeller

Bearing RTDs: No

Stator RTDs: No

Repair Stage: Teardown Inspection

Heaters: No

Winding Type : Random Wound

Bearing Type: Rolling Element

Priorities Found: ● 1 - High ● 7 - Good

Overall Condition



1. Report Date
2. Nameplate Picture

P20



3. Photos of all six sides of the machine.


P27

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.









4. Describe the Overall Condition of the Equipment as Received

Serviceable but rusted

5. Distance from the end of the shaft to the Coupling/Sheave

Initial Mechanical/Electrical



6.	Does Shaft Turn Freely?	(Yes) Yes
7.	Does Shaft Have Visible Damage?	(No) No
8.	Assembled Shaft Runout	0.001 Inches
9.	Assembled Shaft End Play	inches
10.	Air Gap Variation <10%	
11.	Lead Condition	(P) Pass
12.	Lead Length	7 Inches
13.	Frame Condition	pass
14.	Fan Condition	(P) Pass

P55



15. Broken or Missing Components

Initial Electrical Inspection



16. Insulation Resistance/Megger

16000 Megohms

P5



17. Winding Resistance

1-2

1-3

2-3

18. Perform Surge Test

P35



19. Number of Stator Slots

20. Stator Condition

pass

Mechanical Inspection

21. Drive End Bearing Number-

6207 2Z/C3

P8







22. Drive End Bearing Qty.

1

23. Drive End Bearing Type

(Ball) Ball Bearing

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

24.	Drive End Lubrication Type	(Grease) Grease Lubricated	
25.	Drive End Bearing Insulation or Grounding Device?	none	
26.	Drive End Wavy Washer/Snap-Ring Other Retention Device?	spacer goes on after bearing	P39
<div style="display: flex; justify-content: space-around;">   </div>			
27.	Drive End Bearing Condition	replace	
28.	Opposite Drive End Bearing Number-	6205 ZE C3	P48
			
29.	Opposite Drive End Bearing Qty.	1	
30.	Opposite Drive End Bearing Type	(Ball) Ball Bearing	
31.	Opposite Drive End Lubrication Type	(Grease) Grease Lubricated	
32.	Opposite Drive End Bearing Insulation or Grounding Device?	none	
33.	Opposite Drive End Wavy Washer/Snap-Ring Other Retention Device?	yes	P57
			
34.	Opposite Drive End Bearing Condition	Worn	

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.



36. Opposite Drive End Seal

Rotor Inspection

37. Rotor Type/Material (Squirrel Aluminum) Squirrel
Cage Aluminum Die Cast

38. Growler Test (Pass) Pass

39. Number of Rotor Bars

40. Rotor Condition pass

41. List the Parts needed for the Repair Below

P29

Replace Seal, 6207 & 6205 bearings. Need new seal sleeve machined.



42. Signature of Technician that Disassembled Motor

Terrence Holland

Mechanical Fits- Rotor

43. Shaft Runout 0.001 inches

44. Rotor Runout

Drive End Bearing Fit

Rotor Body

Opposite Drive End Bearing

45.	Coupling Fit Closest to Bearing Housing		
	0 Degrees	90 Degrees	120 Degrees
46.	Coupling Fit Closest to the end of the Shaft		
	0 Degrees	60 Degrees	120 Degrees
47.	Drive End Bearing Shaft Fit		
	0 Degrees	60 Degrees	120 Degrees
	1.3782	1.3781	1.3782
48.	Drive End Bearing Shaft Fit Condition		(P) Pass
49.	Opposite Drive End Bearing Shaft Fit		
	0 Degrees	60 Degrees	120 Degrees
	0.9847	0.9848	0.9846
50.	Opposite Drive End Bearing Shaft Fit Condition		(P) Pass
51.	Shaft Air Seal Fits		
	Drive End Air Seal	Opposite Drive End Air Seal	
Mechanical Fits- Bearing Housings			
52.	Drive End - Endbell Bearing Fit		
	0 Degrees	60 Degrees	120 Degrees
	2.835	2.8352	2.8352
53.	Drive End - Endbell Bearing Fit Condition		(P) Pass
54.	Opposite Drive End - Endbell Bearing Fit		
	0 Degrees	60 Degrees	120 Degrees
	2.048	2.048	2.0479
55.	Opposite Drive End - Endbell Bearing Fit Condition		(P) Pass
56.	Bearing Cap Condition		
	Drive End Bearing Cap	Opposite Drive End Bearing Cap	
	pass	n/a	
			
57.	End Bell Air Seal Fits		
	Drive End Air Seal	Opposite Drive End Air Seal	



59. Technician

Terrence Holland

A handwritten signature in black ink, reading "Terrence Holland".

Root Cause of Failure

60. Failure locations

P6

D.E. Seal sleeve worn. Shaft key way wallowed.

61. Root cause of failure

Pump seal failure due to worn seal sleeve.