



Hi-Speed Industrial Service  
7030 Ryburn Dr  
Millington, Tn 38053  
901-873-5300

**AC Repair Arkansas Kraft Division**  
**004458 Green Bay Packaging**  
338 Highway 113 South  
Morrilton, AR 72110

FolderID: 149327  
FormID: 15693621



**AC Recondition - Rev. 2**

Location: Millington Shop

Serial Number:

Hi-Speed Job Number:	149327
Manufacturer:	TECO Westinghouse
Product Number:	TUDP
Spec/ID #:	77B21022
Serial Number:	7803
HP/kW:	150 (HP)
RPM:	3550 (RPM)
Frame:	405TDZ
Voltage:	460
Current:	169 (Amps)
Phase:	Three
Hz:	60 (Hz)
Service Factor:	1.25
Enclosure:	ODP
# of Leads:	6
J-box Included:	Complete
Coupling/Sheave:	Coupling
Date Received:	01/13/2023
Bearing RTDs:	No
Stator RTDs:	No
Repair Stage:	Teardown Inspection
Heaters:	No
Winding Type :	Random Wound
Bearing Type:	Rolling Element

Priorities Found: ● 5 - High ● 3 - Good

**Overall Condition**



- |                      |            |
|----------------------|------------|
| 1. Report Date       | 01/13/2023 |
| 2. Nameplate Picture | P2         |



Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.



## 4. Photos of all six sides of the machine.

P4





5. Describe the Overall Condition of the Equipment as Received

*Windings need to be steamed and baked  
Bore and Bush on both endbells  
Metallization of both ends of the shaft  
New bearings required*

6. Distance from the end of the shaft to the Coupling/Sheave

0.1875 inches

P6



### Prior to Disassembly



7. Does Shaft Turn Freely? (Yes) Yes

8. Does Shaft Have Visible Damage? (No) No

P8




*Rusty*









9. Assembled Shaft Runout 0.002 Inches

10. Perform Open Rotor Check (Pass) Pass

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

11.	Assembled Shaft End Play	0.008 inches	
● 12.	Lead Condition	(P) Pass	
13.	Lead Length	Inches	P13
			
14.	Frame Condition	Good	
15.	Perform a Foot Flatness Test on the Front Feet		
	General	General	
	0	0.003	
16.	Perform a Foot Flatness Test on the Back Feet		
	General	General	
	0	0.002	
17.	Fan Condition	(N) NA	
18.	Is air gap measurement consistent within 10% on all sides?	(No Provisions) No Provisions available for Measurement	
19.	Broken or Missing Components	None	
Initial Electrical Inspection			
● 20.	Perform PDMA Test	(P) Pass	P23
			
21.	Insulation Resistance	25.5	
22.	Polarization Index	7.14	
23.	Winding Resistance		
	1-2	1-3	2-3
	.06940	.06930	.06940
24.	Number of Stator Slots	48	

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

25.	Stator Condition	Good	
	 Needs through cleaning		
<b>Mechanical Inspection</b>			
26.	Drive End Bearing Number-	6314Z C3	P29
			
27.	Drive End Bearing Qty.	1	
28.	Drive End Bearing Type	(Ball) Ball Bearing	
29.	Drive End Lubrication Type	(Grease) Grease Lubricated	
30.	Drive End Bearing Insulation or Grounding Device?	None	
31.	Drive End Wavy Washer/Snap-Ring Other Retention Device?	Snap Ring	P34
	 Spacer behind snap ring		
 			
32.	Drive End Bearing Condition	Good	
33.	Opposite Drive End Bearing Number-	6312Z C3	
34.	Opposite Drive End Bearing Qty.	1	
35.	Opposite Drive End Bearing Type	(Ball) Ball Bearing	
36.	Opposite Drive End Lubrication Type	(Grease) Grease Lubricated	
37.	Opposite Drive End Bearing Insulation or Grounding Device?	None	
38.	Opposite Drive End Wavy Washer/Snap-Ring Other Retention Device?	None	
39.	Opposite Drive End Bearing Condition	Good	
40.	Drive End Seal	Present	P43

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.





41. Opposite Drive End Seal None

### Rotor Inspection

42. Rotor Type/Material (Aluminum Bar) Aluminum Barred Rotor

43. Growler Test (Pass) Pass

44. Number of Rotor Bars 38

45. Rotor Condition Good

46. List the Parts needed for the Repair Below

*Grease tubes NPT  
1/8" x 4 1/2".  
1/8" x 3".  
2 1/8" x 3/4" coupling  
6314Z  
6312z  
314 bushing  
312 bushing  
Drive end inpro seal. See picture for part number.*

47. Signature of Technician that Disassembled Motor Brandon Woodard

### Mechanical Fits- Rotor



48. Shaft Runout 0.001 inches

49. Rotor Runout

Drive End Bearing Fit	Rotor Body	Opposite Drive End Bearing
0.001	0.002	0.001

50. Coupling Fit Closest to Bearing Housing

0 Degrees	90 Degrees	120 Degrees
2.124	2.124	2.124


51. Coupling Fit Closest to the end of the Shaft

0 Degrees	60 Degrees	120 Degrees
2.123	2.123	2.123

## 52. Drive End Bearing Shaft Fit

0 Degrees	60 Degrees	120 Degrees
2.7558	2.7558	2.7558

- 70mm=2.7559. Tolerance is 2.7560-2.7565. Outside of tolerance and requires machining. Shows signs of previous repair.



## 53. Drive End Bearing Shaft Fit Condition

(F) Fail

## 54. Opposite Drive End Bearing Shaft Fit

P65

0 Degrees	60 Degrees	120 Degrees
3.3621	3.3621	3.3621

- 60mm=2.3622. Tolerance is 3.3626-3.3634. Outside of tolerance and requires machining. Shows signs of previous repair.



## 55. Opposite Drive End Bearing Shaft Fit Condition

(F) Fail

## 56. Shaft Air Seal Fits

Drive End Air Seal	Opposite Drive End Air Seal
N/A	N/A

## Mechanical Fits- Bearing Housings





## 57. Drive End - Endbell Bearing Fit

0 Degrees	60 Degrees	120 Degrees
5.9072	5.9072	5.9074

- 150mm=5.9055. Tolerance is 5.9055-5.9065. Outside of tolerance and requires bore and bush

## 58. Drive End - Endbell Bearing Fit Condition

(F) Fail

59.	Opposite Drive End - Endbell Bearing Fit		
	0 Degrees	60 Degrees	120 Degrees
	5.1121	5.112	5.112
	130mm=5.1181. Tolerance is 5.1181-5.1191. Outside of tolerance and requires bore and bush		
60.	Opposite Drive End - Endbell Bearing Fit Condition		(F) Fail
61.	Bearing Cap Condition		
	Drive End Bearing Cap	Opposite Drive End Bearing Cap	
	Good		
	DE has bushing.		
			
DE			
62.	End Bell Air Seal Fits		
	Drive End Air Seal	Opposite Drive End Air Seal	
	N/A	N/A	
63.	List Machine Work Needed Below		
	Metallize and machine both ends of rotor. Both end bells need bore and bush.		
64.	Technician		Brandon Woodard
			
Root Cause of Failure			
65.	Failure locations		
	Dry Bearings		
66.	Root cause of failure		
	Improper bearing lubrication		