



Hi-Speed Industrial Service
7030 Ryburn Dr
Millington, Tn 38053
901-873-5300

AC Repair Arkansas Kraft Division
004458 Green Bay Packaging
338 Highway 113 South
Morrilton, AR 72110

FolderID: 149327
FormID: 15693621



AC Recondition - Rev. 2

Location: Millington Shop

Serial Number:

Hi-Speed Job Number:	149327
Manufacturer:	TECO Westinghouse
Product Number:	TUDP
Spec/ID #:	77B21022
Serial Number:	7803
HP/kW:	150 (HP)
RPM:	3550 (RPM)
Frame:	405TDZ
Voltage:	460
Current:	169 (Amps)
Phase:	Three
Hz:	60 (Hz)
Service Factor:	1.25
Enclosure:	ODP
# of Leads:	6
J-box Included:	Complete
Coupling/Sheave:	Coupling
Date Received:	01/13/2023
Bearing RTDs:	No
Stator RTDs:	No
Repair Stage:	Final
Rewind:	No
Shaft Machined Fit Repairs Required:	Yes
Bearing Housing Machined Fit Repairs Required:	Yes
Heaters:	No
Winding Type :	Random Wound
Bearing Type:	Rolling Element

Priorities Found: ● 5 - High ● 9 - Good

Overall Condition



1. Report Date

01/13/2023

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

2. Nameplate Picture

P2



3. Record Green Bay Packaging Motor Tag

M0052

P3



4. Photos of all six sides of the machine.

P4





5. Describe the Overall Condition of the Equipment as Received

*Windings need to be steamed and baked
Bore and Bush on both endbells
Metallization of both ends of the shaft
New bearings required*

6. Distance from the end of the shaft to the Coupling/Sheave

0.1875 inches

P6



Prior to Disassembly



7. Does Shaft Turn Freely?

(Yes) Yes

8. Does Shaft Have Visible Damage?

(No) No


P8

 Rusty




	9. Assembled Shaft Runout	0.002 Inches	
	10. Perform Open Rotor Check	(Pass) Pass	
	11. Assembled Shaft End Play	0.008 inches	
	12. Lead Condition	(P) Pass	
	13. Lead Length	Inches	P13



	14. Frame Condition	Good	
	15. Perform a Foot Flatness Test on the Front Feet		
	General	General	
	0	0.003	
	16. Perform a Foot Flatness Test on the Back Feet		
	General	General	
	0	0.002	
	17. Fan Condition	(N) NA	
	18. Is air gap measurement consistent within 10% on all sides?	(No Provisions) No Provisions available for Measurement	
	19. Broken or Missing Components	None	
Initial Electrical Inspection			

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.



21. Insulation Resistance **25.5**

22. Polarization Index **7.14**

23. Winding Resistance

1-2	1-3	2-3
.06940	.06930	.06940

24. Number of Stator Slots **48**

25. Stator Condition **Good**

Needs through cleaning

Mechanical Inspection



26. Drive End Bearing Number- **6314Z C3**

P28



27. Drive End Bearing Qty. **1**

28. Drive End Bearing Type **(Ball) Ball Bearing**

29. Drive End Lubrication Type **(Grease) Grease Lubricated**

30. Drive End Bearing Insulation or Grounding Device? **None**

31. Drive End Wavy Washer/Snap-Ring Other Retention Device?

Snap Ring

P33

Spacer behind snap ring



32. Drive End Bearing Condition

Good

33. Opposite Drive End Bearing Number-

6312Z C3

34. Opposite Drive End Bearing Qty.

1

35. Opposite Drive End Bearing Type

(Ball) Ball Bearing

36. Opposite Drive End Lubrication Type

(Grease) Grease Lubricated

37. Opposite Drive End Bearing Insulation or Grounding Device?

None

38. Opposite Drive End Wavy Washer/Snap-Ring Other Retention Device?

None

39. Opposite Drive End Bearing Condition

Good

40. Drive End Seal

Present

P42



41. Opposite Drive End Seal

None

Rotor Inspection

42. Rotor Type/Material

(Aluminum Bar) Aluminum
Barred Rotor

43. Growler Test

(Pass) Pass

44. Number of Rotor Bars

38

45. Rotor Condition

Good

46. List the Parts needed for the Repair Below

Grease tubes NPT

1/8" x 4 1/2".

1/8" x 3".

2- 1/8" x 3/4" coupling

6314Z

6312z

314 bushing

312 bushing

Drive end inpro seal. See picture for part number.

47. Signature of Technician that Disassembled Motor

Brandon Woodard



Mechanical Fits- Rotor



48. Shaft Runout **0.001 inches**

49. Rotor Runout

Drive End Bearing Fit

Rotor Body

Opposite Drive End Bearing

0.001

0.002

0.001

50. Coupling Fit Closest to Bearing Housing

0 Degrees

90 Degrees

120 Degrees

2.124

2.124

2.124

51. Coupling Fit Closest to the end of the Shaft

0 Degrees

60 Degrees

120 Degrees

2.123

2.123

2.123

52. Drive End Bearing Shaft Fit

P54

0 Degrees

60 Degrees

120 Degrees


2.7558

2.7558

2.7558



70mm=2.7559. Tolerance is 2.7560-2.7565. Outside of tolerance and requires machining. Shows signs of previous repair.



53. Drive End Bearing Shaft Fit Condition

(F) Fail

54. Opposite Drive End Bearing Shaft Fit

0 Degrees	60 Degrees	120 Degrees
3.3621	3.3621	3.3621

- 60mm=2.3622. Tolerance is 3.3626-3.3634. Outside of tolerance and requires machining. Shows signs of previous repair.



55. Opposite Drive End Bearing Shaft Fit Condition **(F) Fail**

56. Shaft Air Seal Fits

Drive End Air Seal	Opposite Drive End Air Seal
N/A	N/A

Mechanical Fits- Bearing Housings

57. Drive End - Endbell Bearing Fit

0 Degrees	60 Degrees	120 Degrees
5.9072	5.9072	5.9074

- 150mm=5.9055. Tolerance is 5.9055-5.9065. Outside of tolerance and requires bore and bush

58. Drive End - Endbell Bearing Fit Condition **(F) Fail**

59. Opposite Drive End - Endbell Bearing Fit

0 Degrees	60 Degrees	120 Degrees
5.1198	5.1198	5.1198

- 130mm=5.1181. Tolerance is 5.1181-5.1191. Outside of tolerance and requires bore and bush

60. Opposite Drive End - Endbell Bearing Fit Condition **(F) Fail**

Drive End Bearing Cap

Opposite Drive End Bearing Cap

Good *DE has bushing.*

DE

62. End Bell Air Seal Fits

Drive End Air Seal

Opposite Drive End Air Seal

N/A**N/A**

63. List Machine Work Needed Below

Metallize and machine both ends of rotor. Both end bells need bore and bush.

64. Technician

Brandon Woodard**Dynamic Balance Report**

65. Rotor Weight and Balance Grade

Rotor Weight

Balance Grade

230**ISO 1940-1 G 1.0**

66. Initial Balance Readings

Drive End

Opposite Drive End

0.695**0.229**

Balance Certificate
18612023118000308
Hi-Speed Industrial
6912 Limbrey Road
Contact Phone

Rotor: 1500P-A2
Customer: A4-089
P.O. Number: 149327
Comments:

Left Radius = 4.0 in
Right Radius = 4.0 in
Dimension A = 7.5 in
B = 16.5 in

Balancing Speed: 495 RPM
Service Speed: 3000 RPM

	Left	Right
Initial:	0.695 @ 162° +18.1 in @ 180° +0.000 @ 270°	0.229 @ 157° +14.9 in @ 180° +0.176 @ 270°
Final:	0.083 @ 162° +4.4 in @ 180° +0.176 @ 270°	0.057 @ 157° +0.3 in @ 180° +0.000 @ 270°

Tolerance: 5.10 in @ Left 5.175 in @ Right in Tolerance

Rotor Mass: 230.0 lb

Operator: Brandon Woodard
Checked By: Nigel Hill
Signature: _____
Balancing Equipment
Instrument: Model 255 Balancing Computer, 1 Mode S/N: 1003281
Machine: S/N: 1234-abcd

67. Final Balance Readings

Drive End

Opposite Drive End

0.083**0.057**

68. Technician

Brandon Woodard
Root Cause of Failure

69. Failure locations

Dry Bearings

70. Root cause of failure

*Improper bearing lubrication***Mechanical Fits- Rotor - Post Repair**

71. Shaft Runout Post Repair

0.0005 inches

72. Rotor Runout Post Repair

Drive End Bearing Fit

Rotor Body

Opposite Drive End Bearing

0.001**0.001****0.001**

73. Coupling Fit Closest to Bearing Housing Post Repair

0 Degrees

90 Degrees

120 Degrees

Did not need repair

74. Coupling Fit Closest to the end of the Shaft Post Repair

0 Degrees

60 Degrees

120 Degrees

Did not need repair

75. Drive End Bearing Shaft Fit Post Repair




0 Degrees

60 Degrees

120 Degrees

This fit did not require repair.

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

76.	Opposite Drive End Bearing Shaft Fit Post Repair		
	0 Degrees	60 Degrees	120 Degrees
	3.3632	3.3633	3.3632
77.	Shaft Air Seal Fits Post Repair		
	Drive End Air Seal	Opposite Drive End Air Seal	
	Did not need repair		
Mechanical Fits- Bearing Housings - Post Repair			
78.	Drive End - Endbell Bearing Fit Post Repair		
	0 Degrees	60 Degrees	120 Degrees
	5.9064	5.9064	5.9064
79.	Opposite Drive End - Endbell Bearing Fit Post Repair		
	0 Degrees	60 Degrees	120 Degrees
	5.1182	5.1182	5.1182
80.	Bearing Cap Condition Post Repair		
	Drive End Bearing Cap	Opposite Drive End Bearing Cap	
81.	End Bell Air Seal Fits Post Repair		
	Drive End Air Seal	Opposite Drive End Air Seal	
	Did not need repair		
82.	End Bell Repair Sign-off		Roger Ventrini
Assembly			



Temp(°C)	21.1	
IR Temp Com...	Thermoplastic	None
Resist Status	PASS	No Test
Bal L1 (Ohms)		
Bal L2 (Ohms)		
Bal L3 (Ohms)		
L1-L2 (Ohms)	0.0712 Corr: 0...	
L2-L3 (Ohms)	0.0720 Corr: 0...	
L3-L1 (Ohms)	0.0720 Corr: 0...	
Max Delta R %	1.047	
Coil 1 (Ohms)	0.0356 Corr: 0...	
Coil 2 (Ohms)	0.0356 Corr: 0...	
Coil 3 (Ohms)	0.0364 Corr: 0...	
Nameplate	Application	Results Summary

Test Date	1/20/2023	1/20/2023
Test Time	4:32:08 PM	4:26:19 PM
L3-L1 (Ohms)	0.0720 Corr: 0...	
Max Delta R %	1.047	
Coil 1 (Ohms)	0.0356 Corr: 0...	
Coil 2 (Ohms)	0.0356 Corr: 0...	
Coil 3 (Ohms)	0.0364 Corr: 0...	
Microshun Stat...	PASS	No Test
Volts (V)	499	
I(uA)	0.0024	
Resist	208904	
At 40°C	56407	
P1 Status	No Test	No Test
Volts (V)		
F1A Revin		
Nameplate	Application	Results Summary
		Surge

85. Assembled Shaft Endplay **0.001 inches**

86. Assembled Shaft Runout **0.001 inches**

87. Test Run Voltage P106

Volts	Volts	Volts
460.8	459.5	460.1



88. Test Run Amperage P107

Amps	Amps	Amps
35.57	33.49	34.35



89. Drive End Vibration Readings - Inches Per Second P108

Horizontal	Vertical	Axial
------------	----------	-------


Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.



Horizontal

Vertical

Axial



91. Ambient Temperature - Fahrenheit

68.90000000000001

92. Drive End Bearing Temps - Fahrenheit

5 Minutes

10 Minutes

15 Minutes

70

74

80

93. Drive End Bearing Temps - Fahrenheit 20-30 Minutes

20 Minutes

25 Minutes

30 Minutes

86

87

87

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

94.	Drive End Bearing Temps - Fahrenheit 35-45 Minutes		
	35 Minutes	40 Minutes	45 Minutes
	87	87	87
95.	Drive End Bearing Temps - Fahrenheit 50-60 Minutes		
	50 Minutes	55 Minutes	60 Minutes
	87	86	86
96.	Opposite Drive End Bearing Temps - Fahrenheit		
	5 Minutes	10 Minutes	15 Minutes
	75	80	85
97.	Opposite Drive End Bearing Temps - Fahrenheit 20-30 Minutes		
	20 Minutes	25 Minutes	30 Minutes
	87	87	86
98.	Opposite Drive End Bearing Temps - Fahrenheit 35-45 Minutes		
	35 Minutes	40 Minutes	45 Minutes
	86	86	85
99.	Opposite Drive End Bearing Temps - Fahrenheit 50-60 Minutes		
	50 Minutes	55 Minutes	60 Minutes
	85	85	84
100.	Final Test Run Sign-off		Nigel Hill
101.	Document Final Condition with Pictures after paint		P124



Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.




102. Final Pics and QC Review

Nigel Hill

Report Title M-0052
Submitted By JESS WHITE
Create Date 01/25/23 10:52 AM
Asset Name M-0052
Description 150HP AC Motor



Date: 01/13/23 12:51 PM **Test:** Polarization Index Test



Test: Polarization Index
Section: Stator

Test Date	01/13/23
Test Time	12:51 PM
Test Location	Not Assigned
Tester Serial	5095
MTap ID	
	Baseline
Voltage	500
Duration	600
D/A Ratio	1.605
Polar. Index	7.166

Test: AC Standard
Section: Stator

Test Date	01/13/23	01/13/23	01/13/23
Test Time	12:51 PM	10:03 AM	10:28 AM
Test Location	Not Assigned	Motor Leads	Not Assigned
Tester Serial	5095	5095	5095
MTap ID			
	Baseline		
Frequency	1200	1200	1200
Charge Time	600	600	60
Voltage	500	500	500
Motor Temp	20	20	40
Measured Mohm	101.91	76967.30	76204.48
Corrected Mohm	25.50	19200.00	76204.48
pF Ph 1 to Ground	16300	10800	10700
ohm Ph 1 to 2	0.06940	0.07080	0.07080
ohm Ph 2 to 3	0.06930	0.07070	0.07070
ohm Ph 3 to 1	0.06940	0.07080	0.07080
mH Ph 1 to 2	2.386	2.889	2.792
mH Ph 2 to 3	2.670	2.332	2.517
mH Ph 3 to 1	2.562	2.513	2.571
Average Inductance	2.539	2.511	2.627
% Res. Imbalance	0.10	0.09	0.09
% Ind. Imbalance	6.04	7.23	6.29


Remarks:

THIS TEST WAS PREFORMED PRE-RECONDITION. ALL TESTS PASS

Report Title M-0052
Submitted By JESS WHITE
Create Date 01/25/23 10:52 AM
Asset Name M-0052
Description 150HP AC Motor



Date: 01/25/23 10:03 AM **Test:** Polarization Index Test



Test: Polarization Index
Section: Stator

Test Date	01/13/23	01/25/23
Test Time	12:51 PM	10:03 AM
Test Location	Not Assigned	Motor Leads
Tester Serial	5095	5095
MTap ID		
	Baseline	
Voltage	500	500
Duration	600	600
D/A Ratio	1.605	1.610
Polar. Index	7.166	N/C

Test: AC Standard
Section: Stator

Test Date	01/13/23	01/13/23	01/13/23
Test Time	12:51 PM	10:03 AM	10:28 AM
Test Location	Not Assigned	Motor Leads	Not Assigned
Tester Serial	5095	5095	5095
MTap ID			
	Baseline		
Frequency	1200	1200	1200
Charge Time	600	600	60
Voltage	500	500	500
Motor Temp	20	20	40
Measured Mohm	101.91	76967.30	76204.48
Corrected Mohm	25.50	19200.00	76204.48
pF Ph 1 to Ground	16300	10800	10700
ohm Ph 1 to 2	0.06940	0.07080	0.07080
ohm Ph 2 to 3	0.06930	0.07070	0.07070
ohm Ph 3 to 1	0.06940	0.07080	0.07080
mH Ph 1 to 2	2.386	2.889	2.792
mH Ph 2 to 3	2.670	2.332	2.517
mH Ph 3 to 1	2.562	2.513	2.571
Average Inductance	2.539	2.511	2.627
% Res. Imbalance	0.10	0.09	0.09
% Ind. Imbalance	6.04	7.23	6.29

Remarks:

TEST WAS PREFORMED AFTER RECONDITION AND ASSEMBLY. INCREASED INDUCTIVE IMBALANCE IS DUE TO THE INFLUNCE OF THE INSTALLED ROTOR.