



## AC Recondition As Found

Hiland Dairy (10126)

6901 I-30

Little Rock, AR 72209

FolderID: 100749  
FormID: 15649884

### AC Recondition - Rev. 2

Location: MOTOR SHOP LR  
Serial Number: W08 473295F  
Description: 30KW ATB 1800RPM 200L

Hi-Speed Job Number:	100749
Manufacturer:	Other
Product Number:	3113762-2
Serial Number:	W08 473295F
HP/kW:	30 (kW)
RPM:	1780 (RPM)
Frame:	200L
Voltage:	460
Current:	56
Phase:	Three
Hz:	60 (Hz)
Enclosure:	TEFC
J-box Included:	Complete
Coupling/Sheave:	None
Bearing RTDs:	No
Stator RTDs:	No
Repair Stage:	Final
Heaters:	No
Winding Type :	Random Wound
Bearing Type:	Rolling Element

Priorities Found: ● 6 - High ● 2 - Good

### Overall Condition



1. Report Date
2. Nameplate Picture


P20



Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.








N





3.	Photos of all six sides of the machine.	
4.	Describe the Overall Condition of the Equipment as Received	
	<i>Serviceable</i>	
<b>Initial Mechanical/Electrical</b>		
5.	Does Shaft Turn Freely?	(No) No
	<i>Resolved: (2/15/2023)</i>	
6.	Does Shaft Have Visible Damage?	(No) No
7.	Assembled Shaft Runout	
8.	Assembled Shaft End Play	
9.	Air Gap Variation <10%	

# 1-6 delta.



11. Lead Length
12. Frame Condition

pass



14. Broken or Missing Components
- Fan cover mount bolts. One connection block lead wire mount bolt.

Initial Electrical Inspection

15. Insulation Resistance/Megger
16. Winding Resistance

1-2

1-3

2-3



17. Perform Surge Test	(F) Fail	P35
Resolved: (2/15/2023)		
		
18. Number of Stator Slots		
19. Stator Condition	rewind stator	
<b>Mechanical Inspection</b>		
20. Drive End Bearing Brand		
21. Drive End Bearing Number-	6212 2Z	
22. Drive End Bearing Qty.	1	
23. Drive End Bearing Type	(Ball) Ball Bearing	
24. Drive End Lubrication Type	(Grease) Grease Lubricated	
25. Drive End Bearing Insulation or Grounding Device?	none	
26. Drive End Wavy Washer/Snap-Ring Other Retention Device?	yes, 2ea.	P39



27. Drive End Bearing Condition	total cage and bearing failure.	
28. Opposite Drive End Bearing Brand		
29. Opposite Drive End Bearing Number-	6212 2Z	



- |  |                            |
|--|----------------------------|
| 31. Opposite Drive End Bearing Type                                  | (Ball) Ball Bearing        |
| 32. Opposite Drive End Lubrication Type                              | (Grease) Grease Lubricated |
| 33. Opposite Drive End Bearing Insulation or Grounding Device?       | none                       |
| 34. Opposite Drive End Wavy Washer/Snap-Ring Other Retention Device? | none                       |
| 35. Opposite Drive End Bearing Condition                             | replace                    |
| 36. Drive End Seal   | none                       |
| 37. Opposite Drive End Seal  | none                       |

**Rotor Inspection**

- |                         |  |
|-------------------------|--|
| 38. Rotor Type/Material | (Squirrel Aluminum) Squirrel<br>Cage Aluminum Die Cast |
|-------------------------|--|

P3



- |  |                  |
|--|------------------|
| 39. Growler Test   | (Pass) Pass      |
| 40. Number of Rotor Bars   |                  |
| 41. Rotor Condition  | pass             |
| 42. List the Parts needed for the Repair Below<br><i>Re-sleeve both end bell housing fits. Machine both shaft bearing journals. Rewind Stator.</i> |                  |
| 43. Signature of Technician that Disassembled Motor  | Terrence Holland |

**Mechanical Fits- Rotor**

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

44. Shaft Runout			
45. Rotor Runout			
	Drive End Bearing Fit	Rotor Body	Opposite Drive End Bearing
46. Coupling Fit Closest to Bearing Housing			
	0 Degrees	90 Degrees	120 Degrees
47. Coupling Fit Closest to the end of the Shaft			
	0 Degrees	60 Degrees	120 Degrees
48. Drive End Bearing Shaft Fit			P40
	0 Degrees	60 Degrees	120 Degrees
<div> <div></div> <div>Excessive wear.</div> </div> 			
<div> <div></div> <div>49. Drive End Bearing Shaft Fit Condition</div> <div>Resolved: (2/15/2023)</div> </div> 		(F) Fail	P45
50. Opposite Drive End Bearing Shaft Fit			
	0 Degrees	60 Degrees	120 Degrees
	2.3621	2.362	2.3622
<div> <div></div> <div>51. Opposite Drive End Bearing Shaft Fit Condition</div> <div>Out of tolerance.</div> </div>		(F) Fail	



## 52. Shaft Air Seal Fits

Drive End Air Seal

Opposite Drive End Air Seal

## Mechanical Fits- Bearing Housings



## 53. Drive End - Endbell Bearing Fit

0 Degrees

60 Degrees

120 Degrees

*Excessive wear.*

## 54. Drive End - Endbell Bearing Fit Condition

**(F) Fail**

P10



## 55. Opposite Drive End - Endbell Bearing Fit

P17

0 Degrees

60 Degrees

120 Degrees

*Excessive wear.*



## 57. Bearing Cap Condition

Drive End Bearing Cap

Opposite Drive End Bearing Cap

none

none

## 58. End Bell Air Seal Fits

Drive End Air Seal

Opposite Drive End Air Seal

## 59. List Machine Work Needed Below

*Re-sleeve both housing fits. Machine both shaft bearing journals.*

## 60. Technician

Terrence Holland

## Dynamic Balance Report



## 61. Rotor Weight and Balance Grade

Rotor Weight

Balance Grade


## 62. Initial Balance Readings

Drive End

Opposite Drive End

Drive End

Opposite Drive End



64. Technician

**Rewind**

65. Core Test Results - Watts loss per Pound

Pre-Burnout

Post Burnout

66. Core Hot Spot Test

Pre-Burnout

Post-Burnout

67. Post Rewind Electrical Test- Insulation Resistance

68. Post Rewind Polarization Index

69. Post Rewind Winding Resistance

1-2

1-3

2-3

70. Post Rewind Surge Test

71. Post Rewind Hi-Pot

72. Technician

**Root Cause of Failure**

73. Failure locations

*Windings shorted on drive end. Both housing fits bad. Both shaft fits bad.*

74. Root cause of failure

*Drive end bearing cage failure from improper lubrication caused total bearing failure. Shrapnel from bearing shorted stator coils.***Mechanical Fits- Rotor - Post Repair**

75. Shaft Runout Post Repair

76. Rotor Runout Post Repair

Drive End Bearing Fit

Rotor Body

Opposite Drive End Bearing

77. Coupling Fit Closest to Bearing Housing Post Repair

0 Degrees

90 Degrees

120 Degrees

78. Coupling Fit Closest to the end of the Shaft Post Repair

0 Degrees

60 Degrees

120 Degrees



## 79. Drive End Bearing Shaft Fit Post Repair

P400

0 Degrees

60 Degrees

120 Degrees

2.3627

2.3627

2.3627



## 80. Opposite Drive End Bearing Shaft Fit Post Repair

P500

0 Degrees

60 Degrees

120 Degrees

2.3625

2.3625

2.3624



## 81. Shaft Air Seal Fits Post Repair

Drive End Air Seal

Opposite Drive End Air Seal

## 82. Shaft Repair Sign-off

**Mechanical Fits- Bearing Housings - Post Repair**

## 83. Drive End - Endbell Bearing Fit Post Repair

P0

0 Degrees

60 Degrees

120 Degrees

4.331

4.3312

4.3311



## 84. Opposite Drive End - Endbell Bearing Fit Post Repair

P100

0 Degrees

60 Degrees

120 Degrees

4.3312

4.3312

4.3311



## 85. Bearing Cap Condition Post Repair

Drive End Bearing Cap

Opposite Drive End Bearing Cap

## 86. End Bell Air Seal Fits Post Repair

Drive End Air Seal

Opposite Drive End Air Seal

## 87. End Bell Repair Sign-off


## Assembly



88. QC Check All Parts for Cleanliness Prior to Assembly

89. Photograph All Major Components prior to assembly

P0









90. Final Insulation Resistance Test

91. Assembled Shaft Endplay

92. Assembled Shaft Runout

93. Test Run Voltage

Volts

Volts

Volts

94. Test Run Amperage

Amps

Amps

Amps

95. Drive End Vibration Readings - Inches Per Second

Horizontal

Vertical

Axial

96. Opposite Drive End Vibration Readings - Inches Per Second

Horizontal

Vertical

Axial

97. Ambient Temperature - Fahrenheit

98. Drive End Bearing Temps - Fahrenheit

5 Minutes

10 Minutes

15 Minutes

99. Opposite Drive End Bearing Temps - Fahrenheit

5 Minutes

10 Minutes

15 Minutes

100. Document Final Condition with Pictures after paint

P2200



Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.



101. Final Pics and QC Review

**Terrence Holland**

*[Handwritten signature]* *[Handwritten signature]*