



Hi-Speed Industrial Service  
7030 Ryburn Dr  
Millington, Tn 38053  
901-873-5300

## AC Recondition As Found

**MOST INC (00473501)**  
355 JAMES LAWRENCE RD  
JACKSON, TN 38301

FolderID: 148585  
FormID: 14976091



### AC Recondition - Rev. 2

Location: Plant  
Serial Number: 1041037915  
Description: HORIZONTAL AC MOTOR

Hi-Speed Job Number:	148585
Manufacturer:	WEG
Spec/ID #:	MODEL MGP80
Serial Number:	1041037915
HP/kW:	1000 (HP)
RPM:	713 (RPM)
Voltage:	4160
Current:	134.1 (Amps)
Phase:	Three
Hz:	60 (Hz)
Service Factor:	1.15
# of Leads:	3
J-box Included:	Complete
Coupling/Sheave:	Coupling
Date Received:	10/18/2022
Bearing RTDs:	Yes
Stator RTDs:	Yes
Repair Stage:	Final
Rewind:	No
Shaft Machined Fit Repairs Required:	No
Bearing Housing Machined Fit Repairs Required:	No
Heaters:	Yes
Winding Type :	Form Coil
Bearing Type:	Rolling Element

Priorities Found: 1 - High 9 - Good


### Overall Condition



1. Report Date

11/02/2022


P1



Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.



3. Photos of all six sides of the machine.





4. Describe the Overall Condition of the Equipment as Received

*Fair, frame has had tabs welded on it to secure what appears to be the hood in the past. Coupling is in poor condition due to impacting from hammering. We highly suggest replacement of coupling, it is included in the quote. The stator failed the surge test. It is possible for a motor to fail the surge test though running. However, it is a warning sign that a failure will likely occur soon. Stator rewind is highly recommended.*



5. Distance from the end of the shaft to the Coupling/Sheave

-0.375 inches

P5

⚠ *Coupling protruding 3/8". Coupling was damaged when received. Coupler was beat on with a big hammer which bent flange and has visible damage on inside diameter. Coupling needs replaced.*







Initial Mechanical/Electrical



● 6. Does Shaft Turn Freely?

(Yes) Yes

7.	Does Shaft Have Visible Damage?	(Yes) Yes	P7
<div>Does not require any repair.</div> <div></div> <div>Slight grinder marks on coupler end of shaft. No repair necessary.</div>			
8.	Assembled Shaft Runout	0.0003 Inches	P8
<div><div></div><div></div></div> <div>Grinder marks on end of shaft.</div>			
9.	Assembled Shaft End Play	0.002 inches	P11
10.	Air Gap Variation <10%	Pass	
11.	Lead Condition	(P) Pass	
<div></div>			
12.	Lead Length	32 Inches	P12
<div>Lugged with 3/8 hole 32" from jbox mount plate</div>			

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.



13. Stator Temperature Detector Rating and Function

Quantity	Rating	Quantity Passed
9	100 ohms	10
Order 10 RTDs		

14. Bearing Temperature Detector Rating and Function

P14

Quantity	Rating	Quantity Passed
2	100	2
RTD on each end		



Drive end RTD plastic cracked



Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.



15. Frame Condition

Good

16. Fan Condition

(P) Pass

P16



17. Heater Quantity, Ratings

P17

Quantity

Volts/Watts

Pass/Fail

2

120/595



18. Broken or Missing Components

P18

*End bell bolt holes need chased with tap M20x2.5. Two end bell bolts need replaced. M20x2.5 x 75mm. Missing 12 of 16 bolts for electrical panel cover.*




Correct metric bolt on top, wrong standard bold on bottom.

Initial Electrical Inspection


19. Insulation Resistance/Megger

2918 Megohms

P19



20. Winding Resistance			P20
1-2	1-3	2-3	
.283	.283	.282	




21. Perform Surge Test

(F) Fail


P21

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.







Before wash and bake



Before wash and bake



After wash and bake



After wash and bake

22. Number of Stator Slots	90 Gigohms
23. Stator Condition	fail surge test

Mechanical Inspection

□



- |   |                            |
|---|----------------------------|
| 25. Drive End Bearing Qty.                                  | 1                          |
| 26. Drive End Bearing Type                                  | (Other) Other              |
| 27. Drive End Lubrication Type                              | (Grease) Grease Lubricated |
| 28. Drive End Bearing Insulation or Grounding Device?       | None                       |
| 29. Drive End Wavy Washer/Snap-Ring Other Retention Device? | Yes                        |



30. Drive End Bearing Condition

Good working condition

31. Opposite Drive End Bearing Number-

6322C3

P33



4 springs on inner bearing cap

32. Opposite Drive End Bearing Qty.

1





- |  |                            |
|--|----------------------------|
| 34. Opposite Drive End Lubrication Type                              | (Grease) Grease Lubricated |
| 35. Opposite Drive End Bearing Insulation or Grounding Device?       | None                       |
| 36. Opposite Drive End Wavy Washer/Snap-Ring Other Retention Device? | Yes                        |
| 37. Opposite Drive End Bearing Condition                             | Good working condition     |
| 38. Drive End Seal   | None                       |
| 39. Opposite Drive End Seal  | None                       |

**Rotor Inspection**

- |                         |                                     |
|-------------------------|-------------------------------------|
| 40. Rotor Type/Material | (Copper Barred) Copper Barred Rotor |
|-------------------------|-------------------------------------|



- |   |                 |
|---|-----------------|
| 41. Growler Test  | (Pass) Pass     |
| 42. Number of Rotor Bars  | 112             |
| 43. Rotor Condition   | Good            |
| 44. List the Parts needed for the Repair Below<br>1-6322C3 Bearing<br>1-22228 CC/W33<br>2 M20x2.5 x75mm bolts |                 |
| 45. Signature of Technician that Disassembled Motor   | Brandon Woodard |

**Mechanical Fits- Rotor**

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

46.	Shaft Runout			.001	
47.	Rotor Runout				
	Drive End Bearing Fit	Rotor Body	Opposite Drive End Bearing		
	.0002	.003	.0001		
48.	Coupling Fit Closest to Bearing Housing				P50
	0 Degrees	90 Degrees	120 Degrees		
	5.1248	5.1248	5.1249		
					
49.	Coupling Fit Closest to the end of the Shaft				
	0 Degrees	60 Degrees	120 Degrees		
	5.1248	5.1247	5.1248		
50.	Drive End Bearing Shaft Fit				P52
	0 Degrees	60 Degrees	120 Degrees		
	5.5133	5.5133	5.5135		
	<div>140mm=5.5118. Tolerance is 5.5129-5.5139 within tolerance</div>				
					
51.	Drive End Bearing Shaft Fit Condition			(P) Pass	
	<div>140mm=5.5118. Tolerance is 5.5129-5.5139 within tolerance</div>				

## 52. Opposite Drive End Bearing Shaft Fit

0 Degrees	60 Degrees	120 Degrees
<b>4.331</b>	<b>4.3311</b>	<b>4.3331</b>

110mm=4.3307. Tolerance is 4.3312-4.3318 .0001 out of tolerance press fit recommend no machine work



## 53. Opposite Drive End Bearing Shaft Fit Condition

(P) Pass

110mm=4.3307. Tolerance is 4.3312-4.3318 .0001 out of tolerance press fit recommend no machine work

## 54. Shaft Air Seal Fits

Drive End Air Seal	Opposite Drive End Air Seal
<b>Pass</b>	<b>Pass</b>

## Mechanical Fits- Bearing Housings



## 55. Drive End - Endbell Bearing Fit

P57

0 Degrees	60 Degrees	120 Degrees
<b>9.8432</b>	<b>9.8432</b>	<b>9.8433</b>

250mm=9.8425. Tolerance is 9.8425-9.8436 within tolerance



## 56. Drive End - Endbell Bearing Fit Condition

(P) Pass

250mm=9.8425. Tolerance is 9.8425-9.8436 within tolerance



## 57. Opposite Drive End - Endbell Bearing Fit

0 Degrees	60 Degrees	120 Degrees
<b>9.4498</b>	<b>9.4496</b>	<b>9.4496</b>

240mm=9.4488. Tolerance is 9.4488-9.4499 within tolerance



## 58. Opposite Drive End - Endbell Bearing Fit Condition

**(P) Pass**

240mm=9.4488. Tolerance is 9.4488-9.4499 within tolerance

## 59. Bearing Cap Condition

Drive End Bearing Cap	Opposite Drive End Bearing Cap
<b>good</b>	<b>good</b>

## 60. End Bell Air Seal Fits

Drive End Air Seal	Opposite Drive End Air Seal
<b>Pass</b>	<b>Pass</b>

## 61. List Machine Work Needed Below

*None*

## 62. Technician

**Brandon Woodard**
**Dynamic Balance Report**

## 63. Rotor Weight and Balance Grade

Rotor Weight	Balance Grade
<b>4330 Lbs</b>	<b>API 610-11</b>

## 64. Initial Balance Readings

Drive End	Opposite Drive End
<b>1.56 mils</b>	<b>1.80 mils</b>

## 65. Final Balance Readings

Drive End	Opposite Drive End
<b>.078 mils</b>	<b>.115 mils</b>

R. Cordova

## Root Cause of Failure

### 67. Failure locations

**STATOR FAILED SURGE TESTING**

### 68. Root cause of failure


*Coupling failed due to impacting. Winding failure is likely attributable to voltage spikes caused by transient voltage often times attributed to switching of other high voltage devices, and or lightning. Age/Temperature is also a possible factor in the winding degradation.*

## Assembly




### 69. Photograph All Major Components prior to assembly

P71












#### 70. Final Insulation Resistance Test

**3769 Megohms**

P72

- 3769 Mohms @ 12kV
- >1000 Mohms @500v after assembly



71. Assembled Shaft Endplay **0.001 inches**

72. Assembled Shaft Runout **0.0005 inches**

73. Test Run Voltage P75

Volts	Volts	Volts
4169	4160	4164



74. Test Run Amperage P76

Amps	Amps	Amps
56.78	56.74	55.63




75. Drive End Vibration Readings - Inches Per Second

Horizontal	Vertical	Axial
0.046	0.024	0.08599999999999999

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.




76. Opposite Drive End Vibration Readings - Inches Per Second			
Horizontal		Vertical	Axial
0.038		0.026	0.078
77. Ambient Temperature - Fahrenheit			68
78. Drive End Bearing Temps - Fahrenheit			
5 Minutes		10 Minutes	15 Minutes
88		99	
79. Opposite Drive End Bearing Temps - Fahrenheit			
5 Minutes		10 Minutes	15 Minutes
82		86	
80. Stator Temperatures- Fahrenheit			
5 Minutes		10 Minutes	15 Minutes
77		81	
81. Final Test Run Sign-off			Brandon Woodard
			

82. Document Final Condition with Pictures after paint

P84





## P85

[illegible]

Page 22 of 22