



Hi-Speed Industrial Service
7030 Ryburn Dr
Millington, Tn 38053
901-873-5300

AC Recondition As Found

KTG USA (0003468)

400 Mahannah Ave.

Memphis, TN 38107

FolderID: 149550
FormID: 15972549



AC Recondition - Rev. 2

Location: Default

Serial Number:

Hi-Speed Job Number:	149550
Manufacturer:	Toshiba
Product Number:	02250101-109R00
Serial Number:	991110765
HP/kW:	75 (HP)
RPM:	1775 (RPM)
Frame:	365TSC
Voltage:	230 / 460
Current:	178/89 (Amps)
Phase:	Three
Hz:	60 (Hz)
Service Factor:	1.2
Enclosure:	DP
# of Leads:	12
J-box Included:	Half
Coupling/Sheave:	Coupling
Date Received:	02/13/2023
Bearing RTDs:	No
Stator RTDs:	No
Repair Stage:	Final
Rewind:	No
Shaft Machined Fit Repairs Required:	No
Bearing Housing Machined Fit Repairs Required:	Yes
Heaters:	No
Winding Type :	Random Wound
Bearing Type:	Rolling Element

Priorities Found: ● 5 - High ● 4 - Good

Overall Condition



1. Report Date

02/14/2023

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

Printed on 3/1/2023

Powered by [INSPECTALL](#)

Page 1 of 18

2. Nameplate Picture


P2



3. Photos of all six sides of the machine.

P3





4. Describe the Overall Condition of the Equipment as Received

Good condition needs end bells bore and bush.

5. Distance from the end of the shaft to the Coupling/Sheave

0.25 inches

P5



Initial Mechanical/Electrical



6.	Does Shaft Turn Freely?	(Yes) Yes
7.	Does Shaft Have Visible Damage?	(No) No
8.	Assembled Shaft Runout	0.001 Inches
9.	Assembled Shaft End Play	0.098 inches
10.	Air Gap Variation <10%	no Provisions To Measure
11.	Lead Condition	(P) Pass
	Missing lead # tags	

12. Lead Length

8 Inches

P12



13. Frame Condition

good

14. Fan Condition

(N) NA

15. Broken or Missing Components


P18

*Missing top bolt of c face***Initial Electrical Inspection**

16. Insulation Resistance/Megger

1107 Megohms

P19



17. Winding Resistance

P20

1-2


1-3

2-3

.0636

.0637


.0636



18. Perform Surge Test

(P) Pass

P21



19. Number of Stator Slots

48 Megohms

20. Stator Condition

good

P23

 Iron needs cleaned


Mechanical Inspection



21. Drive End Bearing Brand

NTN

P24



22. Drive End Bearing Number-

6313C3 Z

P25



23. Drive End Bearing Qty.

1

24. Drive End Bearing Type

(Ball) Ball Bearing

25. Drive End Lubrication Type

(Grease) Grease Lubricated

26. Drive End Bearing Insulation or Grounding Device?

none

27. Drive End Wavy Washer/Snap-Ring Other Retention Device?

none

28. Drive End Bearing Condition

normal wear

P31




29. Opposite Drive End Bearing Brand

NTN

P32

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.



30. Opposite Drive End Bearing Number-

6313C3 Z

P33



31. Opposite Drive End Bearing Qty.

1

32. Opposite Drive End Bearing Type

(Ball) Ball Bearing

33. Opposite Drive End Lubrication Type

(Grease) Grease Lubricated

34. Opposite Drive End Bearing Insulation or Grounding Device?

none

35. Opposite Drive End Wavy Washer/Snap-Ring Other Retention Device?

wavy washer

P38



36. Opposite Drive End Bearing Condition

normal wear

P39



37. Drive End Seal

none

38. Opposite Drive End Seal

cap on end bell

Rotor Inspection



39. Rotor Type/Material

(Squirrel Aluminum) Squirrel
Cage Aluminum Die Cast

P50



40. Growler Test

(Pass) Pass

41. Number of Rotor Bars

40

42. Rotor Condition

good

43. List the Parts needed for the Repair Below

2-6313

2-313 bushings

44. Signature of Technician that Disassembled Motor

Brandon Woodard

Mechanical Fits- Rotor



45. Shaft Runout

0.001 inches

46. Coupling Fit Closest to Bearing Housing

P58

0 Degrees	90 Degrees	120 Degrees
1.875	1.875	1.875



47. Coupling Fit Closest to the end of the Shaft

0 Degrees	60 Degrees	120 Degrees
1.875	1.875	1.875

48. Drive End Bearing Shaft Fit

P60

0 Degrees	60 Degrees	120 Degrees
2.5591	2.5591	2.5591

65mm=2.5690. Tolerance is 2.55912-2.5697. .0001 under tolerance recommend no machine work



49. Drive End Bearing Shaft Fit Condition

(F) Fail

50. Opposite Drive End Bearing Shaft Fit

0 Degrees	60 Degrees	120 Degrees
2.5591	2.559	2.5591

65mm=2.5690. Tolerance is 2.55912-2.5697. .0001 under tolerance recommend no machine work



51. Opposite Drive End Bearing Shaft Fit Condition (F) Fail

52. Shaft Air Seal Fits

Drive End Air Seal	Opposite Drive End Air Seal
good	good

Mechanical Fits- Bearing Housings



P65

53. Drive End - Endbell Bearing Fit

0 Degrees	60 Degrees	120 Degrees
5.5135	5.5135	5.5135

140mm=5.5118. Tolerance is 5.5118-5.5128. .0007 out of tolerance recommend bore and bush



54. Drive End - Endbell Bearing Fit Condition (F) Fail

55. Opposite Drive End - Endbell Bearing Fit

0 Degrees

60 Degrees


120 Degrees

5.5134

5.5134

5.5134

140mm=5.5118. Tolerance is 5.5118-5.5128. .0006 out of tolerance recommend bore and bush

56. Opposite Drive End - Endbell Bearing Fit Condition **(F) Fail**

57. Bearing Cap Condition

Drive End Bearing Cap

Opposite Drive End Bearing Cap

good**good**

58. End Bell Air Seal Fits

Drive End Air Seal

Opposite Drive End Air Seal

good**good**

59. List Machine Work Needed Below

Bore and bush both end bells

60. Technician

Brandon Woodard
Dynamic Balance Report

61. Rotor Weight and Balance Grade

Rotor Weight

Balance Grade

180**ISO 1940-1 G1**

Drive End

Opposite Drive End



Drive End

Opposite Drive End



Root Cause of Failure

65. Failure locations

66. Root cause of failure

Mechanical Fits- Bearing Housings - Post Repair



0 Degrees

60 Degrees

120 Degrees

5.5123

5.5123

5.5123



0 Degrees

60 Degrees

120 Degrees

5.5122

5.5122

5.5122



69. Bearing Cap Condition Post Repair

Drive End Bearing Cap

Opposite Drive End Bearing Cap

70. End Bell Air Seal Fits Post Repair

Drive End Air Seal

Opposite Drive End Air Seal

71. End Bell Repair Sign-off

Roger Ventrini

A handwritten signature in black ink, consisting of a stylized 'R' followed by a checkmark-like stroke.

Assembly



72. Photograph All Major Components prior to assembly

P0





73.	Final Insulation Resistance Test	1000 Megohms	
74.	Assembled Shaft Endplay	0.001 inches	
75.	Assembled Shaft Runout	0.001 inches	
76.	Test Run Voltage		P400
	Volts	Volts	Volts

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.



77. Test Run Amperage

P500

Amps	Amps	Amps
------	------	------



78. Drive End Vibration Readings - Inches Per Second

Horizontal	Vertical	Axial
0.038	0.034	0.045

79. Opposite Drive End Vibration Readings - Inches Per Second

Horizontal	Vertical	Axial
0.023	0.04	0.038

80. Ambient Temperature - Fahrenheit	69
--------------------------------------	----

81. Drive End Bearing Temps - Fahrenheit

5 Minutes	10 Minutes	15 Minutes
90	92	94

82. Opposite Drive End Bearing Temps - Fahrenheit

5 Minutes	10 Minutes	15 Minutes
82	83	86

83. Final Test Run Sign-off	Brandon Woodard
-----------------------------	-----------------

84. Document Final Condition with Pictures after paint

ready to ship

P2200

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.



85. Final Pics and QC Review

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.