



Hi-Speed Industrial Service  
7030 Ryburn Dr  
Millington, Tn 38053  
901-873-5300

## AC Recondition As Found

Hi-Speed Industrial Service

7030 Ryburn Drive

MILLINGTON, Tennessee 38053

FolderID: 149639  
FormID: 16058734



### AC Recondition - Rev. 2

Location: Millington Motor Shop

Serial Number:

Hi-Speed Job Number: 149639

Phase: Three

Enclosure: TEFC

# of Leads: 9

J-box Included: Half

Coupling/Sheave: None

Date Received: 02/24/2023

Bearing RTDs: No

Stator RTDs: Yes

Repair Stage: Teardown Inspection

Heaters: No

Winding Type : Random Wound

Bearing Type: Rolling Element

Priorities Found: ● 3 - High ● 6 - Good

### Overall Condition



1. Report Date **02/24/2023**

2. Nameplate Picture **no nameplate**

3. Photos of all six sides of the machine.

P3



Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.





4. Describe the Overall Condition of the Equipment as Received  
*Dirty, needs new lugs , wrong grease in endbells*

#### Initial Mechanical/Electrical



5. Does Shaft Turn Freely?	(Yes) Yes
6. Does Shaft Have Visible Damage?	(No) No
7. Assembled Shaft Runout	0.001 Inches
8. Assembled Shaft End Play	0.001 inches
9. Air Gap Variation <10%	no provisions for measurement

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.



*Lugs need to be cleaned up or re lugged*



11. Lead Length

8 Inches

12. Stator Temperature Detector Rating and Function

Quantity	Rating	Quantity Passed
1	.6	1

13. Frame Condition

good

14. Fan Condition

(F) Fail

P16



15. Broken or Missing Components


yes

*Fan broken*

Initial Electrical Inspection









1-2

1-3

2-3



## Mechanical Inspection











23. Drive End Bearing Qty.	1	
24. Drive End Bearing Type	(Ball) Ball Bearing	
25. Drive End Lubrication Type	(Grease) Grease Lubricated	P28
Wrong grease		



Shields on

26. Drive End Bearing Insulation or Grounding Device?	none present	
27. Drive End Wavy Washer/Snap-Ring Other Retention Device?	none present	
28. Drive End Bearing Condition	worn wrong grease	
29. Opposite Drive End Bearing Brand	koyo	P32





30. Opposite Drive End Bearing Number-

6311ZC3

P33



31. Opposite Drive End Bearing Qty.

1

32. Opposite Drive End Bearing Type

(Ball) Ball Bearing

33. Opposite Drive End Lubrication Type

(Grease) Grease Lubricated

P36

Wrong grease



34. Opposite Drive End Bearing Insulation or Grounding Device?

none present

35. Opposite Drive End Wavy Washer/Snap-Ring Other Retention Device?

wavy washer

P38



36. Opposite Drive End Bearing Condition

worn

P39

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.





- |                             |              |
|-----------------------------|--------------|
| 37. Drive End Seal          | none present |
| 38. Opposite Drive End Seal | none present |

### Rotor Inspection

- |   |  |
|---|--|
| 39. Rotor Type/Material   | (Squirrel Aluminum) Squirrel<br>Cage Aluminum Die Cast |
| 40. Growler Test  | (Pass) Pass  |
| 41. Number of Rotor Bars  | 40   |
| 42. Rotor Condition   | acceptable   |
| 43. List the Parts needed for the Repair Below<br>(1)6312-2z/C3GJN<br>(1)6311ZC3<br>Fan |  |

- |   |              |
|---|--------------|
| 44. Signature of Technician that Disassembled Motor | Brian Goines |
|---|--------------|

### Mechanical Fits- Rotor

- |                  |               |
|------------------|---------------|
| 45. Shaft Runout | 0.0005 inches |
|------------------|---------------|






P56



- |                       |            |                            |
|-----------------------|------------|----------------------------|
| 46. Rotor Runout      |            |                            |
| Drive End Bearing Fit | Rotor Body | Opposite Drive End Bearing |
| 0.001                 | 0.002      | 0.002                      |



47.	Coupling Fit Closest to Bearing Housing			
	0 Degrees	90 Degrees	120 Degrees	
	2.1248	2.1248	2.1248	
48.	Coupling Fit Closest to the end of the Shaft			
	0 Degrees	60 Degrees	120 Degrees	
	2.1248	2.1248	2.1248	
49.	Drive End Bearing Shaft Fit			P60
	0 Degrees	60 Degrees	120 Degrees	
	2.3631	2.3631	2.3631	
	60mm=2.3622. Tolerance is 2.3623-2.3628. .0003 oversized recommend no machine work			
	<div><div></div><div></div></div>			
50.	Drive End Bearing Shaft Fit Condition			(F) Fail
51.	Opposite Drive End Bearing Shaft Fit			
	0 Degrees	60 Degrees	120 Degrees	
	2.166	2.166	2.166	
	55mm=2.1653. Tolerance is 2.1655-2.1660			
52.	Opposite Drive End Bearing Shaft Fit Condition			(P) Pass
53.	Shaft Air Seal Fits			
	Drive End Air Seal	Opposite Drive End Air Seal		
	good	good		
Mechanical Fits- Bearing Housings				
54.	Drive End - Endbell Bearing Fit			
	0 Degrees	60 Degrees	120 Degrees	
	5.1192	5.1192	5.1192	
	130mm=5.1181. Tolerance is 5.1181-5.1191. .0001 outside of tolerance recommend no machine work			
55.	Drive End - Endbell Bearing Fit Condition			(F) Fail



## 56. Opposite Drive End - Endbell Bearing Fit

0 Degrees

60 Degrees

120 Degrees

4.725

4.725

4.7251

120mm=4.7244. Tolerance is 4.7244-4.7253



## 57. Opposite Drive End - Endbell Bearing Fit Condition

(P) Pass

## 58. Bearing Cap Condition

Drive End Bearing Cap

Opposite Drive End Bearing Cap

none

none

## 59. End Bell Air Seal Fits

Drive End Air Seal

Opposite Drive End Air Seal

good

good

## 60. List Machine Work Needed Below

None

## 61. Technician

Brandon Woodard

## Root Cause of Failure

## 62. Failure locations

## 63. Root cause of failure