




**INCA Presswood Sardis, MS**  
**2023 Electrical Infrared Survey Report**



All electrical panels were scanned using a  **FLIR** T865 infrared camera. The following report only contains defects that were found during the survey. Below is our classification system for each defect included in this report. If there are any questions or comments, please feel free to contact us at any time.



employs a three-tier defect rating system:

**CLASS I:** A defect or defects are present that are likely to cause a problem in the long term (2-6 months). Should be addressed in the normal course of maintenance scheduling.

**CLASS II:** A defect or defects are present that are likely to cause a failure in the short term (less than 2 months). Should be addressed as soon as practical, on a high maintenance priority. Consideration should be given to increase monitoring frequency.

**CLASS III:** A defect or defects are present that make continued component reliability unpredictable and likelihood of secondary damage is high. Consideration should be given to an unscheduled shutdown to correct.



*tests and inspects industrial machinery and equipment and makes recommendations concerning maintenance and repairs based on its experience in the field of industrial repair and maintenance. The information contained herein is provided as an opinion only, not as a guaranty or warranty of the matters discussed herein.*

## Component

Contactor/Breaker



## Equipment/Bucket ID

Glue Kitchen 04 PNL 01



## Measurements

<b>Li1</b>	
Max	106.6 °F
Avg	82.0 °F
Min	74.4 °F
Sp1	96.5 °F



## Fault

Weak contactor/breaker

## Defect Rating

CLASS I

## Recommendations

IR image shows this component to likely have internal issues. Replace as time allows.

### Component

Connections



### Equipment/Bucket ID

Hydraulic Pump Panel 1-3



### Measurements

<b>Sp2</b>	143.0 °F
<b>Li1</b>	
Max	142.5 °F
Avg	106.3 °F
Min	94.0 °F
<b>Sp1</b>	136.4 °F



### Fault

Faulty connections

### Defect Rating

**CLASS I**

### Recommendations


Load side connections appear to have some issues. Check connections, ensuring a clean/tight connection.

**Component**

Lead connection



**Equipment/Bucket ID**

Hydraulic Pump 4 Panel



**Measurements**

Sp2	119.1 °F
Sp3	123.1 °F
Li1	
Max	129.2 °F
Avg	87.2 °F
Min	77.7 °F
Sp1	132.1 °F



**Fault**

Faulty connections

**Defect Rating**

**CLASS I**

**Recommendations**

Load side has connection issue (Sp1). Load side (top side) also has a small lead wire that appears to have a connection issue (Sp2). Inspect connections, ensuring a tight, clean connection.




## Component

Jumper leads


## Equipment/Bucket ID

Hammer Mill Control Panel



## Measurements

Sp2	144.6 °F
Sp3	140.8 °F
Li1	
Max	144.3 °F
Avg	98.1 °F
Min	79.7 °F
Li2	
Max	124.0 °F
Avg	93.5 °F
Min	75.6 °F
Sp1	140.2 °F



## Fault

Overloaded circuit

## Defect Rating

CLASS I

## Recommendations

The jumper leads going from contactor to breaker appear to be undersized for the operating current. It is recommended to replace these leads with the proper sized wire. Ensure all connections are clean and tight.



## Summary

File name	Created	Maximum temp.	Page number
FLIR0457.jpg	3/16/2023 2:04:07 AM	109.3 °F	3
FLIR0459.jpg	3/16/2023 2:08:37 AM	149.7 °F	4
FLIR0461.jpg	3/16/2023 2:09:33 AM	134.6 °F	5
FLIR0463.jpg	3/16/2023 2:22:21 AM	152.0 °F	6



This concludes our survey report. Please feel free to contact us at any time for question or comments.

Thank you for your business,

*Kerion W. Maxwell*



ITC Certified Level II Infrared  
Thermographer

(901) 486-4565

[kwilliam@gohispeed.com](mailto:kwilliam@gohispeed.com)