

0

FolderID: 102456



## **AC Inspection as Found** Kimberly Clark (10176-KCM)

500 Murphy Dr. Maumelle, AR 72113

Serial Number:

AC Inspection - Rev. 2

MOTOR SHOP LR Location:

Description: 150HP GE 1800RPM 449T

RKG173045

FormID: 19281272

Manufacturer:	GE
Product Number:	5KAF44933229AP
Serial Number:	RKG173045
HP/kW:	150 (HP)
RPM:	1790 (RPM)
Frame:	449T
Voltage:	460
Current:	161
Phase:	Three
Hz:	60 (Hz)
Service Factor:	1.15
Enclosure:	TEFC
J-box Included:	Complete
Coupling/Sheave:	None

No

No

Final

102456

**Hi-Speed Job Number:** 

**Bearing RTDs:** 

Stator RTDs:

Repair Stage:

Heaters: No Winding Type: Random Wound **Bearing Type:** Rolling Element

Priorities Found: 3 - High



5 - Good

## **Overall Condition**

Report Date







Photos of all six sides of the machine.

P45

























4. Describe the Overall Condition of the Equipment as Received Serviceable

Initia	Initial Mechanical/Electrical			
<b>5</b> .	Does Shaft Turn Freely?	(No) No		
6.	Does the shaft require T.I.R in Lathe to identify additional repairs?			
7.	Does Shaft Have Visible Damage?	(Yes) Yes		
8.	Assembled Shaft Runout	Inches		
9.	Assembled Shaft End Play	inches		
10	. Air Gap Variation <10%			





12.	Lead Length	7 Inches	
13.	Does it have Lugs?, If so what is the Stud Size?		
14.	Lead Numbers	1-3	
15.	Frame Condition	pas	
16.	Fan Condition	(P) Pass	P100








17. Broken or Missing Components

**Initial Electrical Inspection** 




P19

P57



Winding Resistance

1-2 1-3 2-3




Perform Surge Test





(P) Pass





**FAG** 

21.	Number of Stator Slots	72	
22.	Stator Condition	pass	
23.	Stator Thermistors/Ohms		
24.	Stator Overloads/Ohms	.1	
Mecha	Mechanical Inspection		Ō

26. Drive End Bearing Number- NU 318-E-XL-M1-C3 P33

Motor to be engineered for a 318 ball bearing instead of a NU 318.



25. Drive End Bearing Brand

27.	Drive End Bearing Qty.	1	
28.	Drive End Bearing Type	(Roller) Roller Bearing	
29. [	Drive End Lubrication Type	(Grease) Grease Lubricated	



31. Drive End Wavy Washer/Snap-Ring Other Retention Device?

none

destroyed

P78



33. Opposite Drive End Bearing Brand

**Drive End Bearing Condition** 

**FAG** 

P86



34. Opposite Drive End Bearing Number-

P92





35. Opposite Drive End	Bearing Qty.	1	
36. Opposite Drive End	Bearing Type	(Ball) Ball Bearing	
37. Opposite Drive End	Lubrication Type	(Grease) Grease Lubricated	
38. Opposite Drive End	Bearing Insulation or Grounding Device?	none	
39. Opposite Drive End	Wavy Washer/Snap-Ring Other Retention Device?	snap ring	
40. Opposite Drive End	Bearing Condition	replace	
41. Drive End Seal			
42. Opposite Drive End	Seal		

+2. Opposite Brive Eria

## **Rotor Inspection**

0

43. Rotor Type/Material

(Squirrel Aluminum) Squirrel Cage Aluminum Die Cast P3



44.	Growler Test	(Pass) Pass	
45.	Number of Rotor Bars	58	
46.	Rotor Condition		

47. List the Parts needed for the Repair Below

Good, needs new shaft.

New shaft, and new DE bearing cap. Sleeve DE housing and shaft opening. Replace plastic fan with metal one. Replace aegis ring, shaft diameter 4.1875. Drill and tap ODE fan cover mount bolt hole. Motor needs to be converted from using a 318 NU to a 318 ball bearing.

48. Signature of Technician that Disassembled Motor

Terrence Holland

Tomas Holland

Mecha	nical Fits- Rotor			ō
49.	Shaft Runout		inches	
-	New shaft needed.			
50.	Rotor Runout			
	Drive End Bearing Fit	Rotor Body	Opposite Drive End Bearing	
51.	Coupling Fit Closest to Bearing H	ousing		
	0 Degrees	90 Degrees	120 Degrees	
52.	Coupling Fit Closest to the end of	the Shaft		
	0 Degrees	60 Degrees	120 Degrees	
53.	Drive End Bearing Shaft Fit			P69
	0 Degrees	60 Degrees	120 Degrees	



54.	Prive End Bearing Shaft Fit Condition			(F) Fail
55.	Opposite Drive End Bearing Shaf	t Fit		
	0 Degrees	60 Degrees	120 Degrees	
	3.5431	3.543	3.5431	
56.	Opposite Drive End Bearing Shaf	t Fit Condition		(P) Pass
57.	Shaft Air Seal Fits			
	Drive End Air Seal	Opposite Drive End Air Seal		

## **Mechanical Fits- Bearing Housings**

58.	Drive End - Endbell Bearing Fit		
	0 Degrees	60 Degrees	120 Degrees

Lip worn in.

<b>5</b> 9.	Drive End - Endbell Bearing Fit Co	ondition	(F) Fail
60	Opposite Drive End - Endbell Bea	ring Fit	
00.	0 Degrees	60 Degrees	120 Degrees
	7.4811	7.4812	7.4812
<b>6</b> 1.	Opposite Drive End - Endbell Bea		(P) Pass
62.	Bearing Cap Condition	Ting Fit Condition	(F) Fa55
02.		Opposite Drive End Booring Con	
	Drive End Bearing Cap	Opposite Drive End Bearing Cap	
	fail  D.E bearing cap stuck on shaft.	pass	
63.	End Bell Air Seal Fits		
63.		Opposite Drive Fred Air Cool	
	Drive End Air Seal	Opposite Drive End Air Seal	
64.	List Machine Work Needed Below Recommend new shaft. Sleeve D.E ODE housing fan cover mount bolt.	housing, shaft opening. Repair D.E bea	
65.	Technician		Terrence Holland
	7 21	lland	
/-	The state of the s	U .	
D = =4 0	laves of Fallons		
	ause of Failure		
66.	Failure locations  D.E housing and shaft-fits.		
67.			
67.	Wrong bearing for application and	contaminated lubrication	
Dynam	nic Balance Report	contaminated fubrication.	
•	•		
68.	Rotor Weight and Balance Grade	Balance Grade	
	Rotor Weight	balance Grade	
69.	Initial Balance Readings		
	Drive End	Opposite Drive End	
70.	Final Balance Readings		
	Drive End	Opposite Drive End	
71.	Technician		
Rewind	t		
72.	Core Test Results - Watts loss pe	r Pound	
	Pre-Burnout	Post Burnout	
73.	Core Hot Spot Test		
	Pre-Burnout	Post-Burnout	
74.	Post Rewind Electrical Test- Insul	ation Resistance	

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

75. Post Rewind Polarization Index

76	Post Rewind Winding Resistance			
7 0.	1-2	1-3	2-3	
	1 2		2.0	
77.	Post Rewind Surge Test			
78.	Post Rewind Hi-Pot			
79.	Technician			
	inical Fits- Rotor - Post Repair			
80.	•			
81.			0 5 . 5 . 5 .	
	Drive End Bearing Fit	Rotor Body	Opposite Drive End Bearing	
	0 1 5 0 1			
82.	Coupling Fit Closest to Bearing Ho	• •		
	0 Degrees	90 Degrees	120 Degrees	
83.	Coupling Fit Closest to the end of	·		
	0 Degrees	60 Degrees	120 Degrees	
84.	Drive End Bearing Shaft Fit Post F	Repair		
	0 Degrees	60 Degrees	120 Degrees	
85.	Opposite Drive End Bearing Shaft	Fit Post Repair		
	0 Degrees	60 Degrees	120 Degrees	
86.	Shaft Air Seal Fits Post Repair			
	Drive End Air Seal	Opposite Drive End Air Seal		
87.	Shaft Repair Sign-off			
Mecha	nical Fits- Bearing Housings -	Post Repair		
88.	Drive End - Endbell Bearing Fit Po	ost Repair		
	0 Degrees	60 Degrees	120 Degrees	
89.	Opposite Drive End - Endbell Bea	ring Fit Post Repair		
	0 Degrees	60 Degrees	120 Degrees	
90.	Bearing Cap Condition Post Repa	ir		
	Drive End Bearing Cap	Opposite Drive End Bearing Cap		
91.	End Bell Air Seal Fits Post Repair			
	Drive End Air Seal	Opposite Drive End Air Seal		
92.	End Bell Repair Sign-off			
Assem	nbly			
93.	QC Check All Parts for Cleanlines	s Prior to Assembly		
94.	Photograph All Major Components	s prior to assembly		
95.	Final Insulation Resistance Test			
96.	Assembled Shaft Endplay			
97.	Assembled Shaft Runout			

98.	Test Run Voltage			
	Volts	Volts	Volts	
99.	Test Run Amperage			
	Amps	Amps	Amps	
100.	Drive End Vibration Readings - Inches Per Second			
	Horizontal	Vertical	Axial	
101.	Opposite Drive End Vibration Readings - Inches Per Second			
	Horizontal	Vertical	Axial	
102.	Ambient Temperature - Fahrenheit			
103.	Drive End Bearing Temps - Fahrenheit			
	5 Minutes	10 Minutes	15 Minutes	
104.	Opposite Drive End Bearing Temps - Fahrenheit			
	5 Minutes	10 Minutes	15 Minutes	
105.	Document Final Condition with Pictures after paint			
106.	Final Pics and QC Review			

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.