

Hi-Speed Industrial Service 7030 Ryburn Dr Millington, Tn 38053 901-873-5300

> FolderID: 102570 FormID: 19554932

AC Inspection as Found

Rogers Group (01189502) 1032 Hwy 5 Cabot, AR 72023

AC	Insi	pection	- Rev.	2
,,,		30011011		_

Location: Shop Serial Number: 990301870

Description: 200HP 1175RPM TOSHIBA

Hi-Speed Job Number:	102570
Manufacturer:	Toshiba
Spec/ID #:	C2006FLF4BMO
Serial Number:	990301870
HP/kW:	200 (HP)
RPM:	1175 (RPM)
Frame:	505 UZ
Voltage:	460
Current:	234 (Amps)
Phase:	Three
Hz:	60 (Hz)
Service Factor:	1.15
Enclosure:	TEFC
# of Leads:	12
J-box Included:	None
Coupling/Sheave:	None
Repair Stage:	Final
Heaters:	No
Bearing Type:	Rolling Element

Priorities Found: 1 - High







Overall Condition

0

Report Date







Photos of all six sides of the machine.





P45




































4. Describe the Overall Condition of the Equipment as Received Serviceable

Initial Mechanical/Electrical



5. Does Shaft Turn Freely?

(Yes) Yes

6. Does the shaft require T.I.R in Lathe to identify additional repairs?



Does Shaft Have Visible Damage?

8.	Assembled Shaft Runout		
9.	Assembled Shaft End Play		
10.	Air Gap Variation <10%		
11.	Lead Condition	(P) Pass	
12.	Lead Length	13.5 Inches	P87



13.	Does it have Lugs?, If so what is	the Stud Size?	(No) No	•
14.	Lead Numbers		1-12	
-	10,4,8,2 9,5,11,3 7,1,12,6			
15.	Stator Temperature Detector Rat	ing and Function		
	Quantity	Rating	Quantity Passed	
16.	Bearing Temperature Detector R	ating and Function		
	Quantity	Rating	Quantity Passed	
17.	Frame Condition		pass	
18.	Fan Condition		(P) Pass	P115



19. Broken or Missing Components

Initial Electrical Inspection


Megohms

0

P8








21. Winding Resistance P20


1-2 1-3 2-3



22. Perform Surge Test (P) Pass P57







72 23. Number of Stator Slots

24. Stator Condition pass

25. Stator Thermistors/Ohms

26. Stator Overloads/Ohms

Mechanical Inspection

27. Drive End Bearing Brand

28.



Drive End Bearing Number-P32 **NU 322R**



29. Drive End Bearing Qty.

1

0

Koyo



31.	Drive End Lubrication Type	(Grease) Grease Lubricated	
32.	Drive End Bearing Insulation or Grounding Device?	none	
33.	Drive End Wavy Washer/Snap-Ring Other Retention Device?	none	
34.	Drive End Bearing Condition	replace	
35.	Opposite Drive End Bearing Brand	Koyo	
36.	Opposite Drive End Bearing Number-	6318	P99







37.	Opposite Drive End Bearing Qty.	1	
38.	Opposite Drive End Bearing Type	(Ball) Ball Bearing	P106



39.	Opposite Drive End Lubrication T	уре	(Grease) Grease Lubricated	
40.	Opposite Drive End Bearing Insul	ation or Grounding Device?	none	
41.	Opposite Drive End Wavy Washe	r/Snap-Ring Other Retention Device?	snap ring	
42.	Opposite Drive End Bearing Cond	lition	replace	
43.	Drive End Seal		yes	
-	Needs new o ring			
44.	Opposite Drive End Seal		yes	
-	Needs new o ring			
Rotor	Inspection			
45.	Rotor Type/Material		(Squirrel Aluminum) Squirrel Cage Aluminum Die Cast	
46.	Growler Test		(Pass) Pass	
47.	Number of Rotor Bars		60	
48.	Rotor Condition		pass	
49.	List the Parts needed for the Repa	air Below		
50.	Signature of Technician that Disas	ssembled Motor		
Mecha	nical Fits- Rotor			
51.	Shaft Runout		0.003 inches	
52.	Rotor Runout			
	Drive End Bearing Fit	Rotor Body	Opposite Drive End Bearing	
53.	Coupling Fit Closest to Bearing H	ousing		
	0 Degrees	90 Degrees	120 Degrees	
54.	Coupling Fit Closest to the end of	the Shaft		
	0 Degrees	60 Degrees	120 Degrees	
55.	Drive End Bearing Shaft Fit			
	0 Degrees	60 Degrees	120 Degrees	
	4.3341	4.3341	4.3339	
56.	Drive End Bearing Shaft Fit Cond	ition	(P) Pass	
57.	Opposite Drive End Bearing Shafe	t Fit		
	0 Degrees	60 Degrees	120 Degrees	
	3.5441	3.5442	3.5437	
58.	Opposite Drive End Bearing Shafe	t Fit Condition	(P) Pass	

	59.	Shaft Air Seal Fits				
		Drive End Air Seal	Opposite Drive End Air Seal			
Me	cha	nical Fits- Bearing Housings				0
	60.	Drive End - Endbell Bearing Fit				
		0 Degrees	60 Degrees	120 Degrees		
		9.4496	9.4496	9.4498		
	61.	9.4496 Drive End - Endbell Bearing Fit Co	******	9.4498	(P) Pass	
_	61. 62.		ondition	9.4498	(P) Pass	
_		Drive End - Endbell Bearing Fit C	ondition	9.4498 120 Degrees	(P) Pass	
_		Drive End - Endbell Bearing Fit Coopposite Drive End - Endbell Bear	ondition aring Fit		(P) Pass	
_		Drive End - Endbell Bearing Fit Coopposite Drive End - Endbell Bear	ondition aring Fit		(P) Pass	

64. Bearing Cap Condition

Drive End Bearing Cap Opposite Drive End Bearing Cap

pass pass







P52



65. End Bell Air Seal Fits

Drive End Air Seal Opposite Drive End Air Seal

66. List Machine Work Needed Below

Fan cover mount bolts need to be drilled and tapped from broken off bolts.

67. Technician Terrence Holland



Root Cause of Failure

68. Failure locations

Stator housing had water inside and ODE housing fit.

69. Root cause of failure P18

Excessive amounts of water inside the stator and contaminated grease on both ends





Dynamic Balance Report

70. Rotor Weight and Balance Grade

Rotor Weight Balance Grade

71. Initial Balance Readings

Drive End Opposite Drive End

72. Final Balance Readings

Drive End Opposite Drive End

73. Technician

Rewind

74. Core Test Results - Watts loss per Pound

Pre-Burnout Post Burnout

75. Core Hot Spot Test

Pre-Burnout Post-Burnout

- 76. Post Rewind Electrical Test-Insulation Resistance
- 77. Post Rewind Polarization Index
- 78. Post Rewind Winding Resistance

1-2 1-3 2-3

79. Post Rewind Surge Test

80.	Post Rewind Hi-Pot			
81.	Technician			
	nical Fits- Rotor - Post Repair			
82.	Shaft Runout Post Repair			
	Rotor Runout Post Repair			
00.	Drive End Bearing Fit	Rotor Body	Opposite Drive End Bearing	
	Drive End Dearing Fit	Rotor Body	Opposite Drive Life Bearing	
84.	Coupling Fit Closest to Bearing Ho	ousing Post Repair		
01.	0 Degrees	90 Degrees	120 Degrees	
	o Dogroos	oo begrees	120 Dog1003	
85.	Coupling Fit Closest to the end of	the Shaft Post Repair		
	0 Degrees	60 Degrees	120 Degrees	
			1 19	
86.	Drive End Bearing Shaft Fit Post F	Repair		
	0 Degrees	60 Degrees	120 Degrees	
	Ü	3	ŭ	
87.	Opposite Drive End Bearing Shaft	Fit Post Repair		
	0 Degrees	60 Degrees	120 Degrees	
		-		
88.	Shaft Air Seal Fits Post Repair			
	Drive End Air Seal	Opposite Drive End Air Seal		
89.	Shaft Repair Sign-off			
Mechai	nical Fits- Bearing Housings -	Post Repair		
90.	Drive End - Endbell Bearing Fit Po	ost Repair		
	0 Degrees	60 Degrees	120 Degrees	
91.	Opposite Drive End - Endbell Bear	ring Fit Post Repair		
	0 Degrees	60 Degrees	120 Degrees	
92.	Bearing Cap Condition Post Repa			
	Drive End Bearing Cap	Opposite Drive End Bearing Cap		
93.	End Bell Air Seal Fits Post Repair			
	Drive End Air Seal	Opposite Drive End Air Seal		
0.4	End Dall Dag sig Olega "			
94.	End Bell Repair Sign-off			
Assem	-	- Drien to Assembly		
95.	QC Check All Parts for Cleanlines	•		
96.	Photograph All Major Components Final Insulation Resistance Test	s prior to assembly		
97.				
98. 99.	Assembled Shaft Endplay Assembled Shaft Runout			
	Test Run Voltage			
100.	Volts	Volts	Volts	
	VUILO	VOILS	VUILO	

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

101.	Test Run Amperage			
	Amps	Amps	Amps	
102.	Drive End Vibration Readings - In	ches Per Second		
	Horizontal	Vertical	Axial	
103.	Opposite Drive End Vibration Rea	adings - Inches Per Second		
	Horizontal	Vertical	Axial	
104.	Ambient Temperature - Fahrenhe	it		
105.	Drive End Bearing Temps - Fahre	enheit		
	5 Minutes	10 Minutes	15 Minutes	
106.	Opposite Drive End Bearing Tem	ps - Fahrenheit		
	5 Minutes	10 Minutes	15 Minutes	
107.	Stator Temperatures- Fahrenheit			
	5 Minutes	10 Minutes	15 Minutes	
108.	Document Final Condition with Pi	ctures after paint		
109.	Final Pics and QC Review			

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.