



AC Inspection as Found

Rogers Group (01189502)

1032 Hwy 5
Cabot, AR 72023

FolderID: 102570
FormID: 19554932

AC Inspection - Rev. 2

Location: Shop

Serial Number: 990301870

Description: 200HP 1175RPM TOSHIBA

Hi-Speed Job Number: 102570

Manufacturer: Toshiba

Spec/ID #: C2006FLF4BMO

Serial Number: 990301870

HP/kW: 200 (HP)

RPM: 1175 (RPM)

Frame: 505 UZ

Voltage: 460

Current: 234 (Amps)

Phase: Three

Hz: 60 (Hz)

Service Factor: 1.15

Enclosure: TEFC

of Leads: 12

J-box Included: None

Coupling/Sheave: None

Repair Stage: Final

Heaters: No

Bearing Type: Rolling Element

Priorities Found: 2 - High

11 - Good

Overall Condition



1. Report Date

2. Nameplate Picture

P37



3. Photos of all six sides of the machine.

P45











4. Describe the Overall Condition of the Equipment as Received
Serviceable

Initial Mechanical/Electrical



- | | | |
|---|--|------------------|
| ● | 5. Does Shaft Turn Freely? | (Yes) Yes |
| ● | 6. Does the shaft require T.I.R in Lathe to identify additional repairs? | (No) No |

7.	Does Shaft Have Visible Damage?	(No) No	P26
			
8.	Assembled Shaft Runout	0.002 Inches	
9.	Assembled Shaft End Play	0 inches	
10.	Air Gap Variation <10%		
	Na		
11.	Lead Condition	(P) Pass	
12.	Lead Length	13.5 Inches	P87
			
13.	Does it have Lugs?, If so what is the Stud Size?	(No) No	
14.	Lead Numbers	1-12	
	10,4,8,2 9,5,11,3 7,1,12,6		
15.	Stator Temperature Detector Rating and Function		
	Quantity	Rating	Quantity Passed
	Na		
16.	Bearing Temperature Detector Rating and Function		
	Quantity	Rating	Quantity Passed
	Na		
17.	Frame Condition	pass	
18.	Fan Condition	(P) Pass	P115

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.



19. Broken or Missing Components

Initial Electrical Inspection



20. Insulation Resistance/Megger

Megohms

P8



182570		3	
Data		Tests	Trending
Time	Test ID	Test	Result
1/5/2024 10:40	400V w/o...	T...	PASS
8/22/2023 8:35...	400V w/o...	T...	PASS
8/22/2023 8:23...	400V w/o...	T...	PASS
Test Date: 1/5/2024 8/22/2023 8/22/2023			
Test Time: 10:40:26 AM 8:35:40 AM 8:23:28 AM			
Temp Status: Tested Tested No Test			
Temp (°C): 32.8 21.1			
IR Temp Com.: Thermoplastic Thermoplastic None			
Test Status: PASS PASS No Test			
Bal L1 (Ohms)			
Bal L2 (Ohms)			
Bal L3 (Ohms)			
L1-L2 (Ohms): 0.0298 Core B... 0.0348 Core B...			
L2-L3 (Ohms): 0.0255 Core B... 0.0348 Core B...			
L3-L1 (Ohms): 0.0250 Core B... 0.0348 Core B...			
Max Delta R %: 2.985 0.193			
Cable 1 (Ohms): 0.0081 Core B... 0.0022 Core B...			
Cable 2 (Ohms): 0.0081 Core B... 0.0022 Core B...			
Template Application Results Summary Surge PI Step-Ramp Voltage			

21. Winding Resistance

P20

1-2

1-3

2-3




182570		3	
Data		Tests	Trending
Time	Test ID	Test	Result
1/5/2024 10:40	400V w/o...	T...	PASS
8/22/2023 8:35...	400V w/o...	T...	PASS
8/22/2023 8:23...	400V w/o...	T...	PASS
Test Date: 1/5/2024 8/22/2023 8/22/2023			
Test Time: 10:40:26 AM 8:35:40 AM 8:23:28 AM			
Megohm Stat: PASS PASS No Test			
Volts (V): 498 491			
I (uA): 0.2071 0.0387			
Resist: 2405 12676			
At 40°C: 728 3422			
PI Status: No Test No Test No Test			
Volts (V):			
DIA Ratio:			
PI Ratio:			
DC Status: No Test PASS No Test			
Test Type: Step Voltage			
Volts (V): 1990			
PI-AI: 0.1188			
Template Application Results Summary Surge PI Step-Ramp Voltage			

22. Perform Surge Test

(P) Pass

P57

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.



23.	Number of Stator Slots	72
24.	Stator Condition	pass
25.	Stator Thermistors/Ohms	
	Na	
26.	Stator Overloads/Ohms	
	Na	

Mechanical Inspection

27.	Drive End Bearing Brand	Koyo	
28.	Drive End Bearing Number-	NU 322R	P32



29.	Drive End Bearing Qty.	1
-----	------------------------	---

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.



31. Drive End Lubrication Type

(Grease) Grease Lubricated

32. Drive End Bearing Insulation or Grounding Device?

none

33. Drive End Wavy Washer/Snap-Ring Other Retention Device?

none

34. Drive End Bearing Condition

replace

35. Opposite Drive End Bearing Brand

Koyo

36. Opposite Drive End Bearing Number-

6318

P99



37. Opposite Drive End Bearing Qty.


1

38. Opposite Drive End Bearing Type

(Ball) Ball Bearing

P106



39.	Opposite Drive End Lubrication Type	(Grease) Grease Lubricated
40.	Opposite Drive End Bearing Insulation or Grounding Device?	none
41.	Opposite Drive End Wavy Washer/Snap-Ring Other Retention Device?	snap ring
42.	Opposite Drive End Bearing Condition	replace
43.	Drive End Seal	yes
	<i>Needs new o ring</i>	
44.	Opposite Drive End Seal	yes
	<i>Needs new o ring</i>	
Rotor Inspection		
45.	Rotor Type/Material	(Squirrel Aluminum) Squirrel Cage Aluminum Die Cast
46.	Growler Test	(Pass) Pass
47.	Number of Rotor Bars	60
48.	Rotor Condition	pass
49.	List the Parts needed for the Repair Below	
	<i>New fan cover bearings and recondition.</i>	
50.	Signature of Technician that Disassembled Motor	Terrence Holland
		
Mechanical Fits- Rotor		
51.	Shaft Runout	0.003 inches
52.	Rotor Runout	
	Drive End Bearing Fit	Rotor Body
		Opposite Drive End Bearing
	<i>Na</i>	
53.	Coupling Fit Closest to Bearing Housing	
	0 Degrees	90 Degrees
		120 Degrees
	<i>Na</i>	

54.	Coupling Fit Closest to the end of the Shaft			
	0 Degrees	60 Degrees	120 Degrees	
	<div>Na</div>			
55.	Drive End Bearing Shaft Fit			
	0 Degrees	60 Degrees	120 Degrees	
	4.3341	4.3341	4.3339	
<div></div>	56.	Drive End Bearing Shaft Fit Condition		(P) Pass
	57.	Opposite Drive End Bearing Shaft Fit		
		0 Degrees	60 Degrees	120 Degrees
		3.5441	3.5442	3.5437
<div></div>	58.	Opposite Drive End Bearing Shaft Fit Condition		(P) Pass
	59.	Shaft Air Seal Fits		
		Drive End Air Seal	Opposite Drive End Air Seal	
	<div>Na</div>			
Mechanical Fits- Bearing Housings <div></div>				
60.	Drive End - Endbell Bearing Fit			
	0 Degrees	60 Degrees	120 Degrees	
	9.4496	9.4496	9.4498	
<div></div>	61.	Drive End - Endbell Bearing Fit Condition		(P) Pass
	62.	Opposite Drive End - Endbell Bearing Fit		
		0 Degrees	60 Degrees	120 Degrees
	<div>Bad due to groove worn in fit.</div>			
<div></div>	63.	Opposite Drive End - Endbell Bearing Fit Condition		(F) Fail

64. Bearing Cap Condition

Drive End Bearing Cap
pass

Opposite Drive End Bearing Cap
pass



65. End Bell Air Seal Fits

Drive End Air Seal

Opposite Drive End Air Seal

66. List Machine Work Needed Below

Fan cover mount bolts need to be drilled and tapped from broken off bolts.

67. Technician

Terrence Holland

Root Cause of Failure



68. Failure locations

Stator housing had water inside and ODE housing fit.

Excessive amounts of water inside the stator and contaminated grease on both ends



Dynamic Balance Report




70. Rotor Weight and Balance Grade

Rotor Weight	Balance Grade
--------------	---------------

71. Initial Balance Readings

P11

Drive End	Opposite Drive End
1.22	1.18



72. Final Balance Readings

Drive End	Opposite Drive End
.43	.07

73. Technician

Terrence Holland

Rewind

74. Core Test Results - Watts loss per Pound

Pre-Burnout	Post Burnout
-------------	--------------

Na

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

75.	Core Hot Spot Test		
	Pre-Burnout	Post-Burnout	
	Na		
76.	Post Rewind Electrical Test- Insulation Resistance		Megohms
	Na		
77.	Post Rewind Polarization Index		Polarization Index
	Na		
78.	Post Rewind Winding Resistance		
	1-2	1-3	2-3
	Na		
79.	Post Rewind Surge Test		
	Na		
80.	Post Rewind Hi-Pot		micro-amps
	Na		
81.	Technician		Terrence Holland
			
Mechanical Fits- Rotor - Post Repair			
82.	Shaft Runout Post Repair		inches
83.	Rotor Runout Post Repair		
	Drive End Bearing Fit	Rotor Body	Opposite Drive End Bearing
84.	Coupling Fit Closest to Bearing Housing Post Repair		
	0 Degrees	90 Degrees	120 Degrees
85.	Coupling Fit Closest to the end of the Shaft Post Repair		
	0 Degrees	60 Degrees	120 Degrees
86.	Drive End Bearing Shaft Fit Post Repair		
	0 Degrees	60 Degrees	120 Degrees
87.	Opposite Drive End Bearing Shaft Fit Post Repair		
	0 Degrees	60 Degrees	120 Degrees
88.	Shaft Air Seal Fits Post Repair		
	Drive End Air Seal	Opposite Drive End Air Seal	
89.	Shaft Repair Sign-off		
Mechanical Fits- Bearing Housings - Post Repair			
90.	Drive End - Endbell Bearing Fit Post Repair		
	0 Degrees	60 Degrees	120 Degrees

91. Opposite Drive End - Endbell Bearing Fit Post Repair

0 Degrees

60 Degrees

120 Degrees

92. Bearing Cap Condition Post Repair

Drive End Bearing Cap

Opposite Drive End Bearing Cap

93. End Bell Air Seal Fits Post Repair

Drive End Air Seal

Opposite Drive End Air Seal

94. End Bell Repair Sign-off

Assembly



95. QC Check All Parts for Cleanliness Prior to Assembly


Terrence Holland

96. Photograph All Major Components prior to assembly

P17








97. Final Insulation Resistance Test

Megohms

P31



98. Assembled Shaft Endplay inches

99. Assembled Shaft Runout 0.002 inches

100. Test Run Voltage P56

Volts	Volts	Volts
458	458	459



101. Test Run Amperage		
Amps	Amps	Amps
61.4	60.9	61.2

102. Drive End Vibration Readings - Inches Per Second P73


Horizontal	Vertical	Axial
------------	----------	-------



Horizontal

Vertical

Axial



104. Ambient Temperature - Fahrenheit

105. Drive End Bearing Temps - Fahrenheit

5 Minutes

10 Minutes

15 Minutes

106. Opposite Drive End Bearing Temps - Fahrenheit

5 Minutes

10 Minutes

15 Minutes

107. Stator Temperatures- Fahrenheit

5 Minutes

10 Minutes

15 Minutes

108. Document Final Condition with Pictures after paint

109. Final Pics and QC Review

Terrence Holland

P131

Witness: RWR



