



AC Inspection as Found

acme brick

22145 US- 67

Malvern, AR 72104

FolderID: 102739
FormID: 19984342

AC Inspection - Rev. 2

Location: MOTOR SHOP LR

Serial Number: A2104132051

Description: 150HP BALDOR 1190RPM

Hi-Speed Job Number:	102739
Manufacturer:	Baldor
Product Number:	CAT: ECR91506TR-4
Spec/ID #:	P44G1811
Serial Number:	A2104132051
HP/kW:	150 (HP)
RPM:	1190 (RPM)
Frame:	447T
Voltage:	460
Current:	180 (Amps)
Phase:	Three
Hz:	60 (Hz)
Service Factor:	1.15
Enclosure:	TEFC
# of Leads:	6
J-box Included:	None
Coupling/Sheave:	None
Date Received:	04/09/2024
Bearing RTDs:	No
Stator RTDs:	No
Repair Stage:	Final
Rewind:	Yes
Shaft Machined Fit Repairs Required:	No
Bearing Housing Machined Fit Repairs Required:	Yes
Heaters:	No
Winding Type :	Random Wound
Bearing Type:	Rolling Element

Priorities Found: 6 - High 4 - Good

Overall Condition



1. Report Date












4. Describe the Overall Condition of the Equipment as Received
Serviceable

Initial Mechanical/Electrical



5. Does Shaft Turn Freely?	(N) No
6. Does the shaft require T.I.R in Lathe to identify additional repairs?	(No) No
7. Does Shaft Have Visible Damage?	(No) No
8. Assembled Shaft Runout	Inches
Na	
9. Assembled Shaft End Play	inches
Na	
10. Air Gap Variation <10%	na



12. Lead Length	35 Inches	
13. Does it have Lugs?, If so what is the Stud Size?	(No) No	
14. Lead Numbers	1,2,3	
 2 of each.		
15. Frame Condition	pass	
16. Fan Condition	(F) Fail	P115
 3 ea. blades broken.		



17. Broken or Missing Components	broken bolt on ode housing needs drill and tap.	P122
 Fan blade needs replaced.		

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.



Initial Electrical Inspection



18. Insulation Resistance/Megger

Megohms

P8

Na



19. Winding Resistance

1-2

1-3

2-3

Na

20. Perform Surge Test	(F) Fail
21. Number of Stator Slots	90
22. Stator Condition	rewind
23. Stator Thermistors/Ohms	na
24. Stator Overloads/Ohms	na

Mechanical Inspection



25. Drive End Bearing Brand	FAG
26. Drive End Bearing Number-	NU 222-E-XL-TVP2-C3
27. Drive End Bearing Qty.	1
28. Drive End Bearing Type	(Roller) Roller Bearing
29. Drive End Lubrication Type	(Grease) Grease Lubricated
30. Drive End Bearing Insulation or Grounding Device?	

Na

31. Drive End Wavy Washer/Snap-Ring Other Retention Device?

snap ring

P77



32. Drive End Bearing Condition

replace

33. Opposite Drive End Bearing Brand

FAG

34. Opposite Drive End Bearing Number-

6318-2Z/C3

P99



35. Opposite Drive End Bearing Qty.

1

36. Opposite Drive End Bearing Type

(Ball) Ball Bearing

37. Opposite Drive End Lubrication Type

(Grease) Grease Lubricated

38. Opposite Drive End Bearing Insulation or Grounding Device?

none

39. Opposite Drive End Wavy Washer/Snap-Ring Other Retention Device?

none

40. Opposite Drive End Bearing Condition

replace

41. Drive End Seal




42. Opposite Drive End Seal

VA-90

P123

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.



Rotor Inspection			
43. Rotor Type/Material	(Squirrel Aluminum) Squirrel Cage Aluminum Die Cast		P3
			
44. Growler Test	(Pass) Pass		
45. Number of Rotor Bars	71		
46. Rotor Condition	pass		P41
			
47. List the Parts needed for the Repair Below	<i>Replace bearings, rewind stator. Stator core requires core test due to damage from rotor drop. Fan blade has 3 broken blades. Re-sleeve both housing fits.</i>		

48. Signature of Technician that Disassembled Motor

Terrence Holland


Mechanical Fits- Rotor49. Shaft Runout **0.002 inches**

50. Rotor Runout

Drive End Bearing Fit

Rotor Body

Opposite Drive End Bearing

51. Coupling Fit Closest to Bearing Housing

0 Degrees

90 Degrees

120 Degrees


 Na

52. Coupling Fit Closest to the end of the Shaft

0 Degrees

60 Degrees

120 Degrees

 A

53. Drive End Bearing Shaft Fit

0 Degrees

60 Degrees

120 Degrees


4.3318**4.3317****4.3317**
 54. Drive End Bearing Shaft Fit Condition **(P) Pass**

55. Opposite Drive End Bearing Shaft Fit

0 Degrees

60 Degrees

120 Degrees

3.5436**3.5435****3.5434**
 56. Opposite Drive End Bearing Shaft Fit Condition **(P) Pass**

57. Shaft Air Seal Fits

Drive End Air Seal

Opposite Drive End Air Seal

 Na
Mechanical Fits- Bearing Housings

58. Drive End - Endbell Bearing Fit

0 Degrees

60 Degrees

120 Degrees

7.8754**7.8755****7.8755**



Excessive pitting and wear.



63. End Bell Air Seal Fits

Drive End Air Seal

Opposite Drive End Air Seal

64. List Machine Work Needed Below

Sleeve both housing fits.

65. Technician

Terrence Holland

A handwritten signature in black ink, appearing to read 'T. Holland', is written across the line for item 65.

Root Cause of Failure



66. Failure locations

NU, D.E. bearing suffered catastrophic failure from contaminated hardened grease. This caused the rotor to drop onto the stator core and windings resulting in shorted windings and a damaged core. Both housing fits show excessive wear and requires re-sleeve.



67. Root cause of failure

Contaminated hardened grease, resulting in premature DE bearing failure.

Dynamic Balance Report

68. Rotor Weight and Balance Grade

Rotor Weight

Balance Grade

69.	Initial Balance Readings		
	Drive End	Opposite Drive End	
70.	Final Balance Readings		
	Drive End	Opposite Drive End	
71.	Technician		
Rewind			
72.	Core Test Results - Watts loss per Pound		
	Pre-Burnout	Post Burnout	
73.	Core Hot Spot Test		
	Pre-Burnout	Post-Burnout	
74.	Post Rewind Electrical Test- Insulation Resistance		
75.	Post Rewind Polarization Index		
76.	Post Rewind Winding Resistance		
	1-2	1-3	2-3
77.	Post Rewind Surge Test		
78.	Post Rewind Hi-Pot		
79.	Technician		
Mechanical Fits- Bearing Housings - Post Repair			
80.	Drive End - Endbell Bearing Fit Post Repair		
	0 Degrees	60 Degrees	120 Degrees
81.	Opposite Drive End - Endbell Bearing Fit Post Repair		
	0 Degrees	60 Degrees	120 Degrees
82.	Bearing Cap Condition Post Repair		
	Drive End Bearing Cap	Opposite Drive End Bearing Cap	
83.	End Bell Air Seal Fits Post Repair		
	Drive End Air Seal	Opposite Drive End Air Seal	
84.	End Bell Repair Sign-off		
Assembly			
85.	QC Check All Parts for Cleanliness Prior to Assembly		
86.	Photograph All Major Components prior to assembly		
87.	Final Insulation Resistance Test		
88.	Assembled Shaft Endplay		
89.	Assembled Shaft Runout		
90.	Test Run Voltage		
	Volts	Volts	Volts
91.	Test Run Amperage		
	Amps	Amps	Amps

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

92.	Drive End Vibration Readings - Inches Per Second		
	Horizontal	Vertical	Axial
93.	Opposite Drive End Vibration Readings - Inches Per Second		
	Horizontal	Vertical	Axial
94.	Ambient Temperature - Fahrenheit		
95.	Drive End Bearing Temps - Fahrenheit		
	5 Minutes	10 Minutes	15 Minutes
96.	Opposite Drive End Bearing Temps - Fahrenheit		
	5 Minutes	10 Minutes	15 Minutes
97.	Document Final Condition with Pictures after paint		
98.	Final Pics and QC Review		