



AC Inspection as Found

acme brick

22145 US- 67

Malvern, AR 72104

FolderID: 102740
FormID: 19984372

AC Inspection - Rev. 2

Location: MOTOR SHOP LR
Serial Number: Q2-E15T5803GPE 1
Description: 150HP SIEMENS 1190RPM

Hi-Speed Job Number: 102740
Manufacturer: Siemens
Spec/ID #: PART: 1LE22214CC312A
Serial Number: Q2-E15T5803GPE
HP/kW: 150 (HP)
RPM: 1190 (RPM)
Frame: 447T
Voltage: 460
Phase: Three
Hz: 60 (Hz)
Service Factor: 1.15
Enclosure: TEFC
Repair Stage: Final
Winding Type : Random Wound
Bearing Type: Rolling Element

Priorities Found: ● 3 - High ● 6 - Good

Overall Condition



- Report Date
- Nameplate Picture

P37



- Photos of all six sides of the machine.

P45

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.





4. Describe the Overall Condition of the Equipment as Received

Partially disassembled

5. Distance from the end of the shaft to the Coupling/Sheave

inches

Na

Initial Mechanical/Electrical



6. Does Shaft Turn Freely?

(NA) Not Applicable

Na

7. Does the shaft require T.I.R in Lathe to identify additional repairs?

(No) No

8. Does Shaft Have Visible Damage?

(No) No

9. Assembled Shaft Runout

Inches

Unable to check due to partial disassembly by customer.

10. Assembled Shaft End Play

inches

Na

11. Air Gap Variation <10%

Na

One lead cut very short. Also several leads have insulation cut and showing bare wire.



13.	Lead Length	11 Inches
14.	Does it have Lugs?, If so what is the Stud Size?	(No) No
15.	Lead Numbers	1,2,3
	6 leads	
16.	Stator Temperature Detector Rating and Function	
	Quantity	Rating
		Quantity Passed
	Na	
17.	Bearing Temperature Detector Rating and Function	
	Quantity	Rating
		Quantity Passed
	Na	
18.	Frame Condition	pass
19.	Fan Condition	(F) Fail
	Cracked	



20.	Heater Quantity, Ratings		
	Quantity	Volts/Watts	Pass/Fail
	Na		
21.	Broken or Missing Components		
	All end bell housing mount bolts missing.		


Initial Electrical Inspection



22. Insulation Resistance/Megger

Megohms

P8



23. Winding Resistance



P20

1-2
0.2531-3
0.2552-3
0.252

24. Perform Surge Test

(P) Pass

P57



25. Number of Stator Slots

72

26. Stator Condition

pass

27. Stator Thermistors/Ohms

Na

28. Stator Overloads/Ohms

Na

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

Mechanical Inspection



29. Drive End Bearing Brand	FAG	
30. Drive End Bearing Number-	NU 320-E-M1-C3	P32




31. Drive End Bearing Qty.	1	
32. Drive End Bearing Type	(Roller) Roller Bearing	P51



33. Drive End Lubrication Type	(Grease) Grease Lubricated	
34. Drive End Bearing Insulation or Grounding Device?	none	
35. Drive End Wavy Washer/Snap-Ring Other Retention Device?	none	
36. Drive End Bearing Condition	replace	
37. Opposite Drive End Bearing Brand	Nachi	
38. Opposite Drive End Bearing Number-	6316	P99



Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

39.	Opposite Drive End Bearing Qty.	1
40.	Opposite Drive End Bearing Type	(Ball) Ball Bearing
41.	Opposite Drive End Lubrication Type	(Grease) Grease Lubricated
42.	Opposite Drive End Bearing Insulation or Grounding Device?	none
43.	Opposite Drive End Wavy Washer/Snap-Ring Other Retention Device?	snap ring
44.	Opposite Drive End Bearing Condition	replace
45.	Drive End Seal	na
46.	Opposite Drive End Seal	na
Rotor Inspection		
47.	Rotor Type/Material	(Squirrel Aluminum) Squirrel Cage Aluminum Die Cast
48.	Growler Test	(Pass) Pass
49.	Number of Rotor Bars	54
50.	Rotor Condition	pass
51.	List the Parts needed for the Repair Below <i>Sleeve ODE housing fit. Replace all attachment bolts for both housings and bearing caps.</i>	
52.	Signature of Technician that Disassembled Motor	Terrence Holland
		
Mechanical Fits- Rotor		
53.	Shaft Runout	0.002 inches
54.	Rotor Runout	
	Drive End Bearing Fit	Rotor Body
	Opposite Drive End Bearing	
	Na	
55.	Coupling Fit Closest to Bearing Housing	
	0 Degrees	90 Degrees
	120 Degrees	
	Na	
56.	Coupling Fit Closest to the end of the Shaft	
	0 Degrees	60 Degrees
	120 Degrees	
	Na	
57.	Drive End Bearing Shaft Fit	
	0 Degrees	60 Degrees
	120 Degrees	
	3.9379	3.9379
	3.9381	
58.	Drive End Bearing Shaft Fit Condition	(P) Pass
59.	Opposite Drive End Bearing Shaft Fit	
	0 Degrees	60 Degrees
	120 Degrees	
	3.1502	3.15
	3.15	
60.	Opposite Drive End Bearing Shaft Fit Condition	(P) Pass
61.	Shaft Air Seal Fits	
	Drive End Air Seal	Opposite Drive End Air Seal
	Na	

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

Mechanical Fits- Bearing Housings



62. Drive End - Endbell Bearing Fit

0 Degrees

60 Degrees

120 Degrees

8.464700000000001

8.464700000000001

8.4649

63. Drive End - Endbell Bearing Fit Condition

(P) Pass

64. Opposite Drive End - Endbell Bearing Fit

0 Degrees

60 Degrees

120 Degrees

7.4817

7.4818

7.4818

Excessive pitting.

65. Opposite Drive End - Endbell Bearing Fit Condition

(F) Fail

P39



66. Bearing Cap Condition

P52

Drive End Bearing Cap

Opposite Drive End Bearing Cap
pass



67. End Bell Air Seal Fits

Drive End Air Seal

Opposite Drive End Air Seal

Na

68. List Machine Work Needed Below

Sleeve ode housing fit.

69. Technician

Terrence Holland

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

Hi-Speed

Root Cause of Failure



70. Failure locations

P9

Motor requires re-lead de to insulation worn and cut on various leads. ODE housing worn and has excessive pitting. Bearing grease was dirty and contaminated.



71. Root cause of failure

Lead insulation was cut on various leads and one lead was cut very short. Also ODE housing fit is out of tolerance and pitted.

Dynamic Balance Report

72. Rotor Weight and Balance Grade

Rotor Weight	Balance Grade
--------------	---------------

73. Initial Balance Readings

Drive End	Opposite Drive End
-----------	--------------------

74. Final Balance Readings

Drive End	Opposite Drive End
-----------	--------------------

75. Technician

Rewind

76. Core Test Results - Watts loss per Pound

Pre-Burnout	Post Burnout
-------------	--------------

77. Core Hot Spot Test

Pre-Burnout	Post-Burnout
-------------	--------------

78. Post Rewind Electrical Test- Insulation Resistance

79. Post Rewind Polarization Index

80. Post Rewind Winding Resistance

1-2	1-3	2-3
-----	-----	-----

81. Post Rewind Surge Test

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

82.	Post Rewind Hi-Pot		
83.	Technician		
Mechanical Fits- Rotor - Post Repair			
84.	Shaft Runout Post Repair		
85.	Rotor Runout Post Repair		
	Drive End Bearing Fit	Rotor Body	Opposite Drive End Bearing
86.	Coupling Fit Closest to Bearing Housing Post Repair		
	0 Degrees	90 Degrees	120 Degrees
87.	Coupling Fit Closest to the end of the Shaft Post Repair		
	0 Degrees	60 Degrees	120 Degrees
88.	Drive End Bearing Shaft Fit Post Repair		
	0 Degrees	60 Degrees	120 Degrees
89.	Opposite Drive End Bearing Shaft Fit Post Repair		
	0 Degrees	60 Degrees	120 Degrees
90.	Shaft Air Seal Fits Post Repair		
	Drive End Air Seal	Opposite Drive End Air Seal	
91.	Shaft Repair Sign-off		
Mechanical Fits- Bearing Housings - Post Repair			
92.	Drive End - Endbell Bearing Fit Post Repair		
	0 Degrees	60 Degrees	120 Degrees
93.	Opposite Drive End - Endbell Bearing Fit Post Repair		
	0 Degrees	60 Degrees	120 Degrees
94.	Bearing Cap Condition Post Repair		
	Drive End Bearing Cap	Opposite Drive End Bearing Cap	
95.	End Bell Air Seal Fits Post Repair		
	Drive End Air Seal	Opposite Drive End Air Seal	
96.	End Bell Repair Sign-off		
Assembly			
97.	QC Check All Parts for Cleanliness Prior to Assembly		
98.	Photograph All Major Components prior to assembly		
99.	Final Insulation Resistance Test		
100.	Assembled Shaft Endplay		
101.	Assembled Shaft Runout		
102.	Test Run Voltage		
	Volts	Volts	Volts

103. Test Run Amperage			
Amps	Amps	Amps	
104. Drive End Vibration Readings - Inches Per Second			
Horizontal	Vertical	Axial	
105. Opposite Drive End Vibration Readings - Inches Per Second			
Horizontal	Vertical	Axial	
106. Ambient Temperature - Fahrenheit			
107. Drive End Bearing Temps - Fahrenheit			
5 Minutes	10 Minutes	15 Minutes	
108. Opposite Drive End Bearing Temps - Fahrenheit			
5 Minutes	10 Minutes	15 Minutes	
109. Document Final Condition with Pictures after paint			
110. Final Pics and QC Review			