



AC Inspection as Found
Arkansas Lime Company
600 Limedale Rd
Batesville, AR 72501

FolderID: 102804
FormID: 20117471



AC Inspection - Rev. 2

Location: LITTLE ROCK MOTOR SHOP
Serial Number: AF943097
Description: 150 HP BALDOR 1780 RPM

Hi-Speed Job Number:	102804
Manufacturer:	Baldor
Product Number:	SPEC: 18P030Z176H2
Spec/ID #:	AF943097
Serial Number:	AF943097
HP/kW:	150 (HP)
RPM:	1780 (RPM)
Frame:	445TS
Voltage:	460
Current:	167 (Amps)
Phase:	Three
Hz:	60 (Hz)
Service Factor:	1.00
Enclosure:	TEFC
# of Leads:	3
J-box Included:	Complete
Coupling/Sheave:	None
Date Received:	05/02/2024
Bearing RTDs:	No
Stator RTDs:	No
Repair Stage:	Final
Rewind:	Yes
Shaft Machined Fit Repairs Required:	No
Bearing Housing Machined Fit Repairs Required:	Yes
Heaters:	No
Winding Type :	Random Wound
Bearing Type:	Rolling Element

Priorities Found: ● 3 - High ● 7 - Good

Overall Condition



1. Report Date

05/02/2024



2. Nameplate Picture

P37



3. Photos of all six sides of the machine.

P45



Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.




4. Describe the Overall Condition of the Equipment as Received
Stator windings are blown and requires rewind. Opposite drive end needs bushing installed.

Initial Mechanical/Electrical



5.	Does Shaft Turn Freely?	(Y) Yes
6.	Does the shaft require T.I.R in Lathe to identify additional repairs?	(No) No
7.	Does Shaft Have Visible Damage?	(No) No
8.	Assembled Shaft Runout	0.0015 Inches
9.	Assembled Shaft End Play	0.001 inches
10.	Air Gap Variation <10%	No Provisions for measurement



12. Lead Length **18 Inches**

13. Does it have Lugs?, If so what is the Stud Size? **(No) No**

14. Lead Numbers **1-3**

15. Frame Condition **Pass**

16. Fan Condition **(P) Pass**

P115



17. Broken or Missing Components

Yes

P122



Fan shroud bolts.



ODE grease fitting not lined up.




Initial Electrical Inspection






18. Insulation Resistance/Megger

0 Megohms

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

19.	Winding Resistance			
	1-2	1-3	2-3	
	0	0	0	
● 20.	Perform Surge Test		(F) Fail	
21.	Number of Stator Slots		60	
22.	Stator Condition		Requires rewind	P84
				
23.	Stator Thermistors/Ohms		N/A	
24.	Stator Overloads/Ohms		N/A	
Mechanical Inspection				
25.	Drive End Bearing Brand		FAG	P12
				
26.	Drive End Bearing Number-		6319 C3	

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

27. Drive End Bearing Qty.	1	
28. Drive End Bearing Type	(Ball) Ball Bearing	
29. Drive End Lubrication Type	(Grease) Grease Lubricated	
30. Drive End Bearing Insulation or Grounding Device?	None	
31. Drive End Wavy Washer/Snap-Ring Other Retention Device?	Lock Nut	P77
		
32. Drive End Bearing Condition	Normal wear	P82
		
33. Opposite Drive End Bearing Brand	FAG	P92
		
34. Opposite Drive End Bearing Number-	6324 C3	
35. Opposite Drive End Bearing Qty.	1	
36. Opposite Drive End Bearing Type	(Ball) Ball Bearing	
37. Opposite Drive End Lubrication Type	(Grease) Grease Lubricated	

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

38.	Opposite Drive End Bearing Insulation or Grounding Device?	None	
39.	Opposite Drive End Wavy Washer/Snap-Ring Other Retention Device?	Wavy Washer	
40.	Opposite Drive End Bearing Condition	Normal wear	P118

41.	Drive End Seal	None	
42.	Opposite Drive End Seal	None	

Rotor Inspection

43.	Rotor Type/Material	(Squirrel Aluminum) Squirrel Cage Aluminum Die Cast	
44.	Growler Test	(Pass) Pass	
45.	Number of Rotor Bars	46	
46.	Rotor Condition	Pass	P41

47.	List the Parts needed for the Repair Below <i>Rewind</i> 6319 C3 6315 C3		
48.	Signature of Technician that Disassembled Motor	Brandon Woodard	

Mechanical Fits- Rotor

49.	Shaft Runout	0.001 inches	
-----	--------------	--------------	--

50.	Rotor Runout			
	Drive End Bearing Fit	Rotor Body	Opposite Drive End Bearing	
	0.002	0.002	0.002	
51.	Coupling Fit Closest to Bearing Housing			
	0 Degrees	90 Degrees	120 Degrees	
	2.375	2.375	2.375	
52.	Coupling Fit Closest to the end of the Shaft			
	0 Degrees	60 Degrees	120 Degrees	
	2.375	2.375	2.375	
53.	Drive End Bearing Shaft Fit			P79
	0 Degrees	60 Degrees	120 Degrees	
	3.7408	3.7408	3.7408	
	Tolerance is 3.7403-3.7409			
				
54.	Drive End Bearing Shaft Fit Condition			(P) Pass
55.	Opposite Drive End Bearing Shaft Fit			P89
	0 Degrees	60 Degrees	120 Degrees	
	2.7562	2.7562	2.7562	
	Tolerance is 2.7560-2.7565			
				
56.	Opposite Drive End Bearing Shaft Fit Condition			(P) Pass
57.	Shaft Air Seal Fits			
	Drive End Air Seal	Opposite Drive End Air Seal		
	Pass	Pass		

Mechanical Fits- Bearing Housings

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

58. Drive End - Endbell Bearing Fit

0 Degrees

60 Degrees

120 Degrees

7.8743

7.8743

7.8743

Tolerance is 7.8740-7.8751



59. Drive End - Endbell Bearing Fit Condition (P) Pass

60. Opposite Drive End - Endbell Bearing Fit

0 Degrees

60 Degrees

120 Degrees

5.9079

5.9078

5.908

Tolerance is 5.9055-5.9065. Bearing spun and us oversized. Requires bore and bushing installed.

61. Opposite Drive End - Endbell Bearing Fit Condition (F) Fail

62. Bearing Cap Condition

Drive End Bearing Cap

Opposite Drive End Bearing Cap

Pass

Pass

63. End Bell Air Seal Fits

Drive End Air Seal

Opposite Drive End Air Seal

Pass

Pass

64. List Machine Work Needed Below

Bore and bush opposite drive end end bell

65. Technician

Brandon Woodard

Root Cause of Failure

66. Failure locations

67. Root cause of failure

Dynamic Balance Report




68. Rotor Weight and Balance Grade

Rotor Weight

Balance Grade


Drive End

Opposite Drive End



Drive End

Opposite Drive End

**Rewind**

Pre-Burnout

Post Burnout

Pre-Burnout

Post-Burnout

1-2

1-3

2-3

Mechanical Fits- Bearing Housings - Post Repair

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

80. Drive End - Endbell Bearing Fit Post Repair

0 Degrees

60 Degrees

120 Degrees

81. Opposite Drive End - Endbell Bearing Fit Post Repair

P100

0 Degrees

60 Degrees

120 Degrees

5.906

5.906

5.9059



82. Bearing Cap Condition Post Repair

Drive End Bearing Cap

Opposite Drive End Bearing Cap

83. End Bell Air Seal Fits Post Repair

Drive End Air Seal

Opposite Drive End Air Seal

84. End Bell Repair Sign-off

Gary

Assembly



85. QC Check All Parts for Cleanliness Prior to Assembly

Terrence Holland

86. Photograph All Major Components prior to assembly

P100









87. Final Insulation Resistance Test

88. Assembled Shaft Endplay

89. Assembled Shaft Runout

90. Test Run Voltage

P500

Volts

Volts

Volts



91. Test Run Amperage

Amps

Amps

Amps

92. Drive End Vibration Readings - Inches Per Second

Horizontal

Vertical

Axial

0.03

0.02

0.02

93. Opposite Drive End Vibration Readings - Inches Per Second

Horizontal

Vertical

Axial

0.04

0.01

0.04

94. Ambient Temperature - Fahrenheit

95. Drive End Bearing Temps - Fahrenheit

5 Minutes

10 Minutes

15 Minutes

96. Opposite Drive End Bearing Temps - Fahrenheit

5 Minutes

10 Minutes

15 Minutes

97. Document Final Condition with Pictures after paint

P2300

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.





Witness: RW

