



AC Inspection as Found

Tyson Foods (10914)

1238 Market Street
Clarksville, AR 72830

FolderID: 103032
FormID: 20510953

AC Inspection - Rev. 2

Location: MOTOR SHOP LR

Serial Number: M2344254

Description: 5HP GOULDS PUMP

Hi-Speed Job Number: 103032

Manufacturer: Other

Product Number: WS501204

Serial Number: M2344254

HP/kW: 5 (HP)

RPM: 1725 (RPM)

Voltage: 220-240

Current: 26.5A

Phase: Single

Hz: 60 (Hz)

Service Factor: 1

Enclosure: Submersible

of Leads: 2

J-box Included: None

Coupling/Sheave: None

Date Received: 05/29/2024

Bearing RTDs: No

Stator RTDs: No

Repair Stage: Final

Rewind: No

Shaft Machined Fit Repairs
Required: No

Bearing Housing Machined
Fit Repairs Required: No

Heaters: No

Winding Type : Random Wound

Bearing Type: Rolling Element

Priorities Found: 1 - High 8 - Good

Overall Condition



1. Report Date

06/11/2024

2. Nameplate Picture

P37



3. Photos of all six sides of the machine.

P45



Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.







4. Describe the Overall Condition of the Equipment as Received
Serviceable

Initial Mechanical/Electrical





5. Does Shaft Turn Freely? (N) No P1



6. Does the shaft require T.I.R in Lathe to identify additional repairs?	(No) No
7. Does Shaft Have Visible Damage?	(No) No
8. Assembled Shaft Runout	0.001 Inches
9. Assembled Shaft End Play	inches
10. Air Gap Variation <10%	none
11. Lead Condition	(P) Pass
12. Lead Length	12 Inches

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

13.	Does it have Lugs?, If so what is the Stud Size?	(No) No
14.	Lead Numbers	1-3
15.	Frame Condition	pass
16.	Fan Condition	(N) NA
17.	Broken or Missing Components	None
Initial Electrical Inspection		
18.	Insulation Resistance/Megger	Megohms P8
		
19.	Winding Resistance	
	1-2	1-3 2-3
20.	Perform Surge Test	
21.	Number of Stator Slots	36
22.	Stator Condition	pass
23.	Stator Thermistors/Ohms	
24.	Stator Overloads/Ohms	
Mechanical Inspection		
25.	Drive End Bearing Brand	NSK
26.	Drive End Bearing Number-	6206 P32
		
27.	Drive End Bearing Qty.	1
28.	Drive End Bearing Type	(Ball) Ball Bearing
29.	Drive End Lubrication Type	(Oil) Oil Lubricated
30.	Drive End Bearing Insulation or Grounding Device?	none

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

31.	Drive End Wavy Washer/Snap-Ring Other Retention Device?	none	
32.	Drive End Bearing Condition	replace	
33.	Opposite Drive End Bearing Brand	NSK	
34.	Opposite Drive End Bearing Number-	6204	P99
			
35.	Opposite Drive End Bearing Qty.	1	
36.	Opposite Drive End Bearing Type	(Ball) Ball Bearing	
37.	Opposite Drive End Lubrication Type	(Oil) Oil Lubricated	
38.	Opposite Drive End Bearing Insulation or Grounding Device?	none	
39.	Opposite Drive End Wavy Washer/Snap-Ring Other Retention Device?	wavy washer & snap ring	
40.	Opposite Drive End Bearing Condition	replace	
41.	Drive End Seal	sic,sic	P120
			
42.	Opposite Drive End Seal	carbon ceramic	P123

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.










Rotor Inspection

43. Rotor Type/Material	(Squirrel Aluminum) Squirrel Cage Aluminum Die Cast
44. Growler Test	(Pass) Pass
45. Number of Rotor Bars	48
46. Rotor Condition	pass
47. List the Parts needed for the Repair Below <i>Bearings, & seals</i>	
48. Signature of Technician that Disassembled Motor	Terrence Holland

Mechanical Fits- Rotor

49.	Shaft Runout			0.003 inches
50.	Rotor Runout			
	Drive End Bearing Fit	Rotor Body	Opposite Drive End Bearing	
	0			
51.	Coupling Fit Closest to Bearing Housing			
	0 Degrees	90 Degrees	120 Degrees	
	0			
52.	Coupling Fit Closest to the end of the Shaft			
	0 Degrees	60 Degrees	120 Degrees	
	0.8745000000000001	0.8745000000000001	0.8745000000000001	
53.	Drive End Bearing Shaft Fit			
	0 Degrees	60 Degrees	120 Degrees	
	1.1814	1.1814	1.1814	
54.	Drive End Bearing Shaft Fit Condition			(P) Pass
55.	Opposite Drive End Bearing Shaft Fit			
	0 Degrees	60 Degrees	120 Degrees	
	0.7875	0.7874	0.7875	
56.	Opposite Drive End Bearing Shaft Fit Condition			(P) Pass

57.	Shaft Air Seal Fits		
	Drive End Air Seal	Opposite Drive End Air Seal	
	ok	ok	
Mechanical Fits- Bearing Housings			
58.	Drive End - Endbell Bearing Fit		
	0 Degrees	60 Degrees	120 Degrees
	2.441	2.4411	2.4409
59.	Drive End - Endbell Bearing Fit Condition		(P) Pass
60.	Opposite Drive End - Endbell Bearing Fit		
	0 Degrees	60 Degrees	120 Degrees
	1.8502	1.85	1.8503
61.	Opposite Drive End - Endbell Bearing Fit Condition		(P) Pass
62.	Bearing Cap Condition		
	Drive End Bearing Cap	Opposite Drive End Bearing Cap	
	ok	ok	
63.	End Bell Air Seal Fits		
	Drive End Air Seal	Opposite Drive End Air Seal	
	ok	ok	
64.	List Machine Work Needed Below None		
65.	Technician		Terrence. Holland
			
 Witnessed by DWM			
Root Cause of Failure			
66.	Failure locations Impeller, and stator housings.		
67.	Root cause of failure Impeller was completely wrapped around with rags and cloth material. This contributed to the shaft being completely locked up and also caused premature seal failure.		
<div style="display: flex; justify-content: space-around;">   </div>			
Dynamic Balance Report			

68. Rotor Weight and Balance Grade		
Rotor Weight	Balance Grade	
69. Initial Balance Readings		
Drive End	Opposite Drive End	
70. Final Balance Readings		
Drive End	Opposite Drive End	
71. Technician		
Assembly 		
72. QC Check All Parts for Cleanliness Prior to Assembly	Terrence Holland	P4
		
		
		
		
		
73. Photograph All Major Components prior to assembly	(Complete) Complete	
74. Final Insulation Resistance Test		
75. Assembled Shaft Endplay		
76. Assembled Shaft Runout		

77. Test Run Voltage

P56

Volts

Volts

Volts



78. Test Run Amperage

P65

Amps

Amps

Amps



79. Drive End Vibration Readings - Inches Per Second

Horizontal

Vertical

Axial

80. Opposite Drive End Vibration Readings - Inches Per Second

Horizontal

Vertical

Axial

81. Ambient Temperature - Fahrenheit

82. Drive End Bearing Temps - Fahrenheit

5 Minutes

10 Minutes

15 Minutes

83. Opposite Drive End Bearing Temps - Fahrenheit

5 Minutes

10 Minutes

15 Minutes

84. Document Final Condition with Pictures after paint

85. Final Pics and QC Review

Terrence Holland

P131

L. H. Hall



Witness: DWM



Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.