



AC Inspection as Found

Premier Technical Plastics

2120 Queensway
Searcy, Arkan 72143

FolderID: 103286
FormID: 21125497

AC Inspection - Rev. 2

Location: LR Motor Shop

Serial Number: 25MN440719 G 004 FA

Description: 100HP RELIANCE 1185RPM

Hi-Speed Job Number:	103286
Manufacturer:	Reliance
Product Number:	PN: 339431
Spec/ID #:	M: P44G0719C
Serial Number:	26MN440719 G 004 FA
HP/kW:	100 (HP)
RPM:	1185 (RPM)
Frame:	445TSC
Voltage:	230 / 460
Current:	226/113 (Amps)
Phase:	Three
Hz:	60 (Hz)
Service Factor:	1.15
Enclosure:	DP
# of Leads:	9
J-box Included:	Complete
Coupling/Sheave:	None
Date Received:	07/27/2024
Bearing RTDs:	No
Stator RTDs:	No
Repair Stage:	Final
Rewind:	Yes
Shaft Machined Fit Repairs Required:	No
Bearing Housing Machined Fit Repairs Required:	No
Heaters:	No
Winding Type :	Random Wound
Bearing Type:	Rolling Element

Priorities Found: ● 2 - High ● 14 - Good

Overall Condition



1. Report Date

07/27/2024

2. Nameplate Picture

P37



3. Photos of all six sides of the machine.

P45







4. Describe the Overall Condition of the Equipment as Received

Serviceable but dirty

Initial Mechanical/Electrical



5.	Does Shaft Turn Freely?	(Y) Yes	
6.	Does the shaft require T.I.R in Lathe to identify additional repairs?	(No) No	
7.	Does Shaft Have Visible Damage?	(No) No	
8.	Assembled Shaft Runout	0.003 Inches	
9.	Assembled Shaft End Play	0 inches	
10.	Air Gap Variation <10%		
11.	Lead Condition	(P) Pass	
12.	Lead Length	17 Inches	
13.	Does it have Lugs?, If so what is the Stud Size?	(Yes) Yes	P93



14.	Lead Numbers	1-9
15.	Frame Condition	
16.	Fan Condition	
17.	Broken or Missing Components	none

Initial Electrical Inspection

18. Insulation Resistance/Megger Megohms

Na

19. Winding Resistance




1-2

1-3

2-3

Na

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

20.	Perform Surge Test	(F) Fail	
	<i>Passed surge tests but windings have burnt strings. Rewind recommended</i>		
21.	Number of Stator Slots	90	
22.	Stator Condition	rewind	
23.	Stator Thermistors/Ohms		
	<i>Na</i>		
24.	Stator Overloads/Ohms	1.3	
Mechanical Inspection			
25.	Drive End Bearing Brand	SKF	
26.	Drive End Bearing Number-	6318-2Z/C3	P32
			
27.	Drive End Bearing Qty.	1	
28.	Drive End Bearing Type	(Ball) Ball Bearing	
29.	Drive End Lubrication Type	(Grease) Grease Lubricated	
30.	Drive End Bearing Insulation or Grounding Device?	none	
31.	Drive End Wavy Washer/Snap-Ring Other Retention Device?	none	
32.	Drive End Bearing Condition	worn	P82
			
33.	Opposite Drive End Bearing Brand	SKF	



- | | |
|--|----------------------------|
| 35. Opposite Drive End Bearing Qty. | 1 |
| 36. Opposite Drive End Bearing Type | (Ball) Ball Bearing |
| 37. Opposite Drive End Lubrication Type | (Grease) Grease Lubricated |
| 38. Opposite Drive End Bearing Insulation or Grounding Device? | none |
| 39. Opposite Drive End Wavy Washer/Snap-Ring Other Retention Device? | none |
| 40. Opposite Drive End Bearing Condition | |

P118



- | | |
|-----------------------------|--|
| 41. Drive End Seal | |
| 42. Opposite Drive End Seal | |

Rotor Inspection

- | | |
|--------------------------|--|
| 43. Rotor Type/Material | (Squirrel Aluminum) Squirrel
Cage Aluminum Die Cast |
| 44. Growler Test | (Pass) Pass |
| 45. Number of Rotor Bars | 71 |
| 46. Rotor Condition | pass |

- | | |
|--|--|
| 47. List the Parts needed for the Repair Below | |
| <i>Bearings</i> | |

- | | |
|---|------------------|
| 48. Signature of Technician that Disassembled Motor | Terrence Holland |
|---|------------------|

Mechanical Fits- Rotor49. Shaft Runout **0.003 inches** **Both ends**

50. Rotor Runout

Drive End Bearing Fit

Rotor Body

Opposite Drive End Bearing

51. Coupling Fit Closest to Bearing Housing

0 Degrees

90 Degrees

120 Degrees

52. Coupling Fit Closest to the end of the Shaft

0 Degrees

60 Degrees


120 Degrees

53. Drive End Bearing Shaft Fit

0 Degrees

60 Degrees

120 Degrees

3.5434**3.5434****3.5434** 54. Drive End Bearing Shaft Fit Condition **(P) Pass**

55. Opposite Drive End Bearing Shaft Fit

0 Degrees

60 Degrees

120 Degrees

35434**35435****35435** 56. Opposite Drive End Bearing Shaft Fit Condition **(P) Pass**

57. Shaft Air Seal Fits

Drive End Air Seal

Opposite Drive End Air Seal

Mechanical Fits- Bearing Housings

58. Drive End - Endbell Bearing Fit

0 Degrees

60 Degrees

120 Degrees

7.4806**7.4806****7.4807** 59. Drive End - Endbell Bearing Fit Condition **(P) Pass**

60. Opposite Drive End - Endbell Bearing Fit

0 Degrees

60 Degrees

120 Degrees

7.4807**7.4809****7.4808** 61. Opposite Drive End - Endbell Bearing Fit Condition **(P) Pass**

62. Bearing Cap Condition

Drive End Bearing Cap

Opposite Drive End Bearing Cap

63. End Bell Air Seal Fits

Drive End Air Seal

Opposite Drive End Air Seal

64. List Machine Work Needed Below

None

65. Technician

Terrence Holland**Root Cause of Failure**

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

66. Failure locations
Windings showed signs of excessive heat, and had burnt winding strings

67. Root cause of failure
Motor experienced excessive heat on windings possibly due to excessive dirt and grease.

Dynamic Balance Report



68. Rotor Weight and Balance Grade

Rotor Weight	Balance Grade
--------------	---------------


69. Initial Balance Readings

Drive End	Opposite Drive End
1.68	3.02

70. Final Balance Readings

Drive End	Opposite Drive End
.06	.38

P27



71. Technician

Terrence Holland

Rewind

72. Core Test Results - Watts loss per Pound

Pre-Burnout	Post Burnout
-------------	--------------

Na

73. Core Hot Spot Test

Pre-Burnout	Post-Burnout
-------------	--------------

Na

74. Post Rewind Electrical Test- Insulation Resistance






Megohms

Na

75. Post Rewind Polarization Index

Polarization Index

Na

76.	Post Rewind Winding Resistance		
	1-2	1-3	2-3
	Na		
77.	Post Rewind Surge Test		(Pass) Pass
78.	Post Rewind Hi-Pot		micro-amps
	Na		
79.	Technician		
	Na		
Assembly			
80.	QC Check All Parts for Cleanliness Prior to Assembly	Terrence Holland	
			
81.	Photograph All Major Components prior to assembly	(Complete) Complete	P17
	<div>   </div> <div>   </div>		




82.	Final Insulation Resistance Test	1.2 Gigohms	
83.	Assembled Shaft Endplay	0 inches	
84.	Assembled Shaft Runout	0.002 inches	
85.	Test Run Voltage		P56
	Volts	Volts	Volts



86.	Test Run Amperage		P65
	Amps	Amps	Amps



	87. Drive End Vibration Readings - Inches Per Second		
	Horizontal	Vertical	Axial
	0.002	0.003	0.002
	88. Opposite Drive End Vibration Readings - Inches Per Second		
	Horizontal	Vertical	Axial
	0.003	0.002	0.001
89.	Ambient Temperature - Fahrenheit		
90.	Drive End Bearing Temps - Fahrenheit		
	5 Minutes	10 Minutes	15 Minutes
91.	Opposite Drive End Bearing Temps - Fahrenheit		
	5 Minutes	10 Minutes	15 Minutes
92.	Document Final Condition with Pictures after paint		see pics below
93.	Final Pics and QC Review		Terrence Holland P131



 Witness RRW









Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.