



AC Inspection as Found

Riceland Foods (11100-RLF)

Hwy 79 & N. Park Ave.

Stuttgart, AR 72160

FolderID: 103534
FormID: 21696147

AC Inspection - Rev. 2

Location: MOTOR SHOP LR

Serial Number: M09T007375MV2D

Description: 50HP SIEMENS 1770RPM

Hi-Speed Job Number: 103534

Manufacturer: Siemens

Product Number: PART: 1MB29213AB242QGB

Serial Number: M09T007375MV2D

HP/kW: 50 (HP)

RPM: 1775 (RPM)

Frame: 326T

Voltage: 460

Current: 58 (Amps)

Phase: Three

Hz: 60 (Hz)

Enclosure: TEFC

of Leads: 3

J-box Included: Complete

Coupling/Sheave: None

Date Received: 09/23/2024

Bearing RTDs: No

Stator RTDs: No

Repair Stage: Final

Rewind: No

Shaft Machined Fit Repairs
Required: No

Bearing Housing Machined
Fit Repairs Required: Yes

Heaters: No

Winding Type : Random Wound

Bearing Type: Rolling Element

Priorities Found: ● 2 - High ● 12 - Good

Overall Condition



1. Report Date

09/23/2024









4. Describe the Overall Condition of the Equipment as Received

Dirty but serviceable

5. Report Date [COPY]

Initial Mechanical/Electrical



- | | | |
|--|---------|-----|
| 6. Does Shaft Turn Freely? | (Y) Yes | |
| 7. Does the shaft require T.I.R in Lathe to identify additional repairs? | (No) No | |
| 8. Does Shaft Have Visible Damage? | (No) No | P26 |



- | | | |
|--|-------------------------|--|
| 9. Assembled Shaft Runout | 0.001 Inches | |
| 10. Assembled Shaft End Play | 0 inches | |
| 11. Air Gap Variation <10% | | |
| 12. Lead Condition | (P) Pass | |
| 13. Lead Length | 15 Inches | |
| 14. Does it have Lugs?, If so what is the Stud Size? | (No) No | |
| 15. Lead Numbers | 1-3 | |
| 16. Frame Condition | pass | |
| 17. Fan Condition | (F) Fail | |
| <div> <i>Destroyed</i> </div> | | |
| 18. Broken or Missing Components | fan assembly destroyed. | |

Initial Electrical Inspection





20. Winding Resistance

1-2



1-3

2-3

☒ 21. Perform Surge Test

(P) Pass

P57



22. Number of Stator Slots

48

23. Stator Condition

pass

24. Stator Thermistors/Ohms

25. Stator Overloads/Ohms

0.2

P97



Mechanical Inspection



26. Drive End Bearing Brand

ORS

P12



27. Drive End Bearing Number-	6312	
28. Drive End Bearing Qty.	1	
29. Drive End Bearing Type	(Ball) Ball Bearing	
30. Drive End Lubrication Type	(Grease) Grease Lubricated	
31. Drive End Bearing Insulation or Grounding Device?	none	
32. Drive End Wavy Washer/Snap-Ring Other Retention Device?	none	
33. Drive End Bearing Condition	contaminated	
34. Opposite Drive End Bearing Brand	ORS	
35. Opposite Drive End Bearing Number-	6312 C3	P100

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.





- | | |
|--|----------------------------|
| 37. Opposite Drive End Bearing Type | (Ball) Ball Bearing |
| 38. Opposite Drive End Lubrication Type | (Grease) Grease Lubricated |
| 39. Opposite Drive End Bearing Insulation or Grounding Device? | none |
| 40. Opposite Drive End Wavy Washer/Snap-Ring Other Retention Device? | wavy washer |
| 41. Opposite Drive End Bearing Condition | contaminated grease |
| 42. Drive End Seal | dust seal |
| 43. Opposite Drive End Seal | none |

Rotor Inspection


- | | | |
|-------------------------|--|----|
| 44. Rotor Type/Material | (Squirrel Aluminum) Squirrel
Cage Aluminum Die Cast | P3 |
|-------------------------|--|----|



- | | |
|---|------------------|
| 45. Growler Test | (Pass) Pass |
| 46. Number of Rotor Bars | 41 |
| 47. Rotor Condition | pass |
| 48. List the Parts needed for the Repair Below
<i>New fan assembly</i> | |
| 49. Signature of Technician that Disassembled Motor | Terrence Holland |

Mechanical Fits- Rotor

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

50.	Shaft Runout	0.001 inches	
51.	Rotor Runout		
	Drive End Bearing Fit	Rotor Body	Opposite Drive End Bearing
52.	Coupling Fit Closest to Bearing Housing		
	0 Degrees	90 Degrees	120 Degrees
53.	Coupling Fit Closest to the end of the Shaft		
	0 Degrees	60 Degrees	120 Degrees
54.	Drive End Bearing Shaft Fit		
	0 Degrees	60 Degrees	120 Degrees
	2.3629	2.3629	2.3631
55.	Drive End Bearing Shaft Fit Condition	(P) Pass	
56.	Opposite Drive End Bearing Shaft Fit		
	0 Degrees	60 Degrees	120 Degrees
	2.363	2.363	2.363
57.	Opposite Drive End Bearing Shaft Fit Condition	(P) Pass	
58.	Shaft Air Seal Fits		
	Drive End Air Seal	Opposite Drive End Air Seal	
Mechanical Fits- Bearing Housings			
59.	Drive End - Endbell Bearing Fit		
	0 Degrees	60 Degrees	120 Degrees
	5.1192	5.119	5.1191
60.	Drive End - Endbell Bearing Fit Condition	(P) Pass	
61.	Opposite Drive End - Endbell Bearing Fit		
	0 Degrees	60 Degrees	120 Degrees
	<div>Excessive pitting</div> <div></div>		
62.	Opposite Drive End - Endbell Bearing Fit Condition	(F) Fail	

Drive End Bearing Cap

Opposite Drive End Bearing Cap



64. End Bell Air Seal Fits

Drive End Air Seal

Opposite Drive End Air Seal

65. List Machine Work Needed Below

P67

ODE housing pitted and out of tolerance.

66. Technician

Terrence Holland

A handwritten signature in black ink, appearing to read "T. Holland".



Witness:

Root Cause of Failure



67. Failure locations

ODE housing fit.

Contaminated grease in both housings led to premature bearing failure. Also found moisture inside stator housing. Additionally there was excessive amounts of debris inside the fan cover which led to total fan destruction.



Dynamic Balance Report

69. Rotor Weight and Balance Grade

Rotor Weight

Balance Grade

70. Initial Balance Readings

Drive End

Opposite Drive End

71.	Final Balance Readings		
	Drive End	Opposite Drive End	
72.	Technician		
Mechanical Fits- Bearing Housings - Post Repair			
73.	Drive End - Endbell Bearing Fit Post Repair		
	0 Degrees	60 Degrees	120 Degrees
74.	Opposite Drive End - Endbell Bearing Fit Post Repair		
	0 Degrees	60 Degrees	120 Degrees
75.	Bearing Cap Condition Post Repair		
	Drive End Bearing Cap	Opposite Drive End Bearing Cap	
76.	End Bell Air Seal Fits Post Repair		
	Drive End Air Seal	Opposite Drive End Air Seal	
77.	End Bell Repair Sign-off		
Assembly			
78.	QC Check All Parts for Cleanliness Prior to Assembly		
79.	Photograph All Major Components prior to assembly		
80.	Final Insulation Resistance Test		
81.	Assembled Shaft Endplay		
82.	Assembled Shaft Runout		
83.	Test Run Voltage		
	Volts	Volts	Volts
84.	Test Run Amperage		
	Amps	Amps	Amps
85.	Drive End Vibration Readings - Inches Per Second		
	Horizontal	Vertical	Axial
86.	Opposite Drive End Vibration Readings - Inches Per Second		
	Horizontal	Vertical	Axial
87.	Ambient Temperature - Fahrenheit		
88.	Drive End Bearing Temps - Fahrenheit		
	5 Minutes	10 Minutes	15 Minutes
89.	Opposite Drive End Bearing Temps - Fahrenheit		
	5 Minutes	10 Minutes	15 Minutes
90.	Document Final Condition with Pictures after paint		
91.	Final Pics and QC Review		