



AC Inspection as Found

Beasley Flooring (12083)

485 HWY 9 SPUR
MELBOURNE, AR 72556

FolderID: 103876
FormID: 22612547

AC Inspection - Rev. 2

Location: MOTOR SHOP LR

Serial Number: 894C-664

Description: 100HP BALDOR

Hi-Speed Job Number: 103876

Manufacturer: Baldor

Product Number: CAT: ECP4400T-4

Spec/ID #: 1GE32X20

Serial Number: 894C-664

HP/kW: 100 (HP)

RPM: 1780 (RPM)

Frame: 405T

Voltage: 460

Current: 114 (Amps)

Phase: Three

Hz: 60 (Hz)

Service Factor: 1.15

Enclosure: TEFC

of Leads: 3

J-box Included: Complete

Coupling/Sheave: None

Date Received: 12/20/2024

Bearing RTDs: No

Stator RTDs: No

Repair Stage: Final

Rewind: No

Shaft Machined Fit Repairs
Required: No

Heaters: No

Winding Type : Random Wound

Bearing Type: Rolling Element

Priorities Found: ● 1 - High ● 12 - Good

Overall Condition



1. Report Date

12/18/2024

2. Nameplate Picture

P37



3. Photos of all six sides of the machine.

P45







4. Describe the Overall Condition of the Equipment as Received

Initial Mechanical/Electrical


5. Does Shaft Turn Freely?	(Y) Yes
6. Does the shaft require T.I.R in Lathe to identify additional repairs?	(No) No
7. Does Shaft Have Visible Damage?	(No) No
8. Assembled Shaft Runout	0.003 Inches
9. Assembled Shaft End Play	0 inches
10. Air Gap Variation <10%	
11. Lead Condition	(P) Pass
12. Lead Length	11 Inches
13. Does it have Lugs?, If so what is the Stud Size?	(No) No
14. Lead Numbers	1-3
15. Frame Condition	pass
16. Fan Condition	(P) Pass
17. Broken or Missing Components	none

Initial Electrical Inspection



18. Insulation Resistance/Megger 2.314 Megohms

P8



19. Winding Resistance

P20

1-2


1-3

2-3

.0620



.0622

.0621





20. Perform Surge Test

P57



Before baking

After baking



21. Number of Stator Slots

60

22. Stator Condition

pass

23. Stator Thermistors/Ohms

24. Stator Overloads/Ohms

Mechanical Inspection



Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.



26. Drive End Bearing Number- **6316**

27. Drive End Bearing Qty. **1**

28. Drive End Bearing Type **(Ball) Ball Bearing**

29. Drive End Lubrication Type **(Grease) Grease Lubricated**

30. Drive End Bearing Insulation or Grounding Device?

31. Drive End Wavy Washer/Snap-Ring Other Retention Device?

Spanner nut, star washer

32. Drive End Bearing Condition **replace**

Metal fatigue

33. Opposite Drive End Bearing Brand **koyo**

P92



34. Opposite Drive End Bearing Number- **6313**

35. Opposite Drive End Bearing Qty. **1**

36. Opposite Drive End Bearing Type **(Ball) Ball Bearing**

37. Opposite Drive End Lubrication Type **(Grease) Grease Lubricated**

38. Opposite Drive End Bearing Insulation or Grounding Device?

39. Opposite Drive End Wavy Washer/Snap-Ring Other Retention Device? **wavy washer**

40. Opposite Drive End Bearing Condition **replace**

Metal fatigue

41. Drive End Seal **Dust seal**



42. Opposite Drive End Seal **Dust seal**

Rotor Inspection

43. Rotor Type/Material **(Squirrel Aluminum) Squirrel
Cage Aluminum Die Cast**

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

44.	Growler Test	(Pass) Pass	
45.	Number of Rotor Bars	50	
46.	Rotor Condition	pass	
47.	List the Parts needed for the Repair Below 6316 & 6313 2Z/C3 bearings		
48.	Signature of Technician that Disassembled Motor	Cody McMillan	
			
<input type="checkbox"/> Co sign: TRH			
Mechanical Fits- Rotor			
49.	Shaft Runout	0.003 inches	
50.	Rotor Runout		
	Drive End Bearing Fit	Rotor Body	Opposite Drive End Bearing
51.	Coupling Fit Closest to Bearing Housing		
	0 Degrees	90 Degrees	120 Degrees
52.	Coupling Fit Closest to the end of the Shaft		
	0 Degrees	60 Degrees	120 Degrees
53.	Drive End Bearing Shaft Fit		
	0 Degrees	60 Degrees	120 Degrees
	3.1502	3.1502	3.1502
<input checked="" type="radio"/> 54.	Drive End Bearing Shaft Fit Condition	(P) Pass	
55.	Opposite Drive End Bearing Shaft Fit		
	0 Degrees	60 Degrees	120 Degrees
	2.5596	2.5594	2.5594
<input checked="" type="radio"/> 56.	Opposite Drive End Bearing Shaft Fit Condition	(P) Pass	
57.	Shaft Air Seal Fits		
	Drive End Air Seal	Opposite Drive End Air Seal	
Mechanical Fits- Bearing Housings			

58.	Drive End - Endbell Bearing Fit	P2		
	0 Degrees	60 Degrees	120 Degrees	
	<div><div></div><div>Fail</div></div> <div>Excessive Pitting, recommend sleeving. Verified by machinist.</div> <div></div>			
59.	Drive End - Endbell Bearing Fit Condition	(F) Fail		P15
	<div><div></div><div>Excessive pitting. Verified by machinist.</div></div> <div></div>			
60.	Opposite Drive End - Endbell Bearing Fit			
	0 Degrees	60 Degrees	120 Degrees	
	5.5122	5.512	5.512	
61.	Opposite Drive End - Endbell Bearing Fit Condition	(P) Pass		
62.	Bearing Cap Condition			
	Drive End Bearing Cap	Opposite Drive End Bearing Cap		
	pass	pass		
63.	End Bell Air Seal Fits			
	Drive End Air Seal	Opposite Drive End Air Seal		
64.	List Machine Work Needed Below			
	Sleeve D.E housing fit			
65.	Technician	Terrence Holland		



Co witness: CM

Root Cause of Failure

66. Failure locations
Bearings & bearing grease. D.E housing fit has excessive pitting.
67. Root cause of failure
Water contaminated grease caused premature bearing failure

Dynamic Balance Report

68. Rotor Weight and Balance Grade

Rotor Weight	Balance Grade
--------------	---------------

69. Initial Balance Readings

Drive End	Opposite Drive End
-----------	--------------------

70. Final Balance Readings

Drive End	Opposite Drive End
-----------	--------------------

71. Technician

Mechanical Fits- Bearing Housings - Post Repair

72. Drive End - Endbell Bearing Fit Post Repair

0 Degrees	60 Degrees	120 Degrees
-----------	------------	-------------

73. Opposite Drive End - Endbell Bearing Fit Post Repair

0 Degrees	60 Degrees	120 Degrees
-----------	------------	-------------

74. Bearing Cap Condition Post Repair

Drive End Bearing Cap	Opposite Drive End Bearing Cap
-----------------------	--------------------------------

75. End Bell Air Seal Fits Post Repair

Drive End Air Seal	Opposite Drive End Air Seal
--------------------	-----------------------------

76. End Bell Repair Sign-off

Assembly

77. QC Check All Parts for Cleanliness Prior to Assembly
78. Photograph All Major Components prior to assembly
79. Final Insulation Resistance Test
80. Assembled Shaft Endplay
81. Assembled Shaft Runout
82. Test Run Voltage

Volts	Volts	Volts
-------	-------	-------

83.	Test Run Amperage		
	Amps	Amps	Amps
84.	Drive End Vibration Readings - Inches Per Second		
	Horizontal	Vertical	Axial
85.	Opposite Drive End Vibration Readings - Inches Per Second		
	Horizontal	Vertical	Axial
86.	Ambient Temperature - Fahrenheit		
87.	Drive End Bearing Temps - Fahrenheit		
	5 Minutes	10 Minutes	15 Minutes
88.	Opposite Drive End Bearing Temps - Fahrenheit		
	5 Minutes	10 Minutes	15 Minutes
89.	Document Final Condition with Pictures after paint		
90.	Final Pics and QC Review		