



Hi-Speed Industrial Service
7030 Ryburn Dr
Millington, Tn 38053
901-873-5300

AC Inspection as Found

ARKEMA, INC.
2571 Fite Road
Memphis, TN 38127

FolderID: 152680
FormID: 20240862



AC Inspection - Rev. 2

Location: MLMR Shop

Serial Number: 8207

Description: 125 Hp Ac Motor

Hi-Speed Job Number:	152680
Manufacturer:	TECO Westinghouse
Product Number:	773B975G27
Serial Number:	8207
HP/kW:	125 (HP)
RPM:	1780 (RPM)
Frame:	444T
Voltage:	460
Current:	136 (Amps)
Phase:	Three
Hz:	60 (Hz)
Service Factor:	1.16
Enclosure:	TEFC
# of Leads:	3
J-box Included:	Half
Coupling/Sheave:	None
Date Received:	04/29/2024
Bearing RTDs:	No
Stator RTDs:	No
Repair Stage:	Teardown Inspection
Shaft Machined Fit Repairs Required:	No
Bearing Housing Machined Fit Repairs Required:	Yes
Heaters:	No
Winding Type :	Random Wound
Bearing Type:	Rolling Element

Priorities Found: ● 1 - High ● 18 - Good

Overall Condition



● 1. Report Date

04/30/2024

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

Printed on 5/8/2024

Powered by [INSPECTALL](#)

Page 1 of 9





4. Describe the Overall Condition of the Equipment as Received

Initial Mechanical/Electrical




5.	Does Shaft Turn Freely?	(Y) Yes	
6.	Does the shaft require T.I.R in Lathe to identify additional repairs?	(No) No	
7.	Does Shaft Have Visible Damage?	(No) No	
8.	Assembled Shaft Runout	0.0005 Inches	
9.	Assembled Shaft End Play	0.0005 inches	
10.	Air Gap Variation <10%	no provision for measurement	
11.	Lead Condition	(P) Pass	
12.	Lead Length	16 Inches	
13.	Does it have Lugs?, If so what is the Stud Size?	(Yes) Yes	
	3/8 hole		
14.	Lead Numbers	1-3	
15.	Frame Condition		
16.	Fan Condition	(P) Pass	P16



17. Broken or Missing Components

Initial Electrical Inspection





19. Winding Resistance

P19

1-2


1-3

2-3

.0407

.0408

.0404



20. Perform Surge Test


(P) Pass

21. Number of Stator Slots

72

22. Stator Condition

P22



23. Stator Thermistors/Ohms

none present

24. Stator Overloads/Ohms

none present

Mechanical Inspection



25. Drive End Bearing Brand

SKF

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.



27. Drive End Bearing Qty.	1
28. Drive End Bearing Type	(Ball) Ball Bearing
29. Drive End Lubrication Type	(Grease) Grease Lubricated
30. Drive End Bearing Insulation or Grounding Device?	none present
31. Drive End Wavy Washer/Snap-Ring Other Retention Device?	none
32. Drive End Bearing Condition	

P32



33. Opposite Drive End Bearing Brand	SKF
34. Opposite Drive End Bearing Number-	6313 C3ZZ

P34



35. Opposite Drive End Bearing Qty.	1
36. Opposite Drive End Bearing Type	(Ball) Ball Bearing
37. Opposite Drive End Lubrication Type	(Grease) Grease Lubricated
38. Opposite Drive End Bearing Insulation or Grounding Device?	none present
39. Opposite Drive End Wavy Washer/Snap-Ring Other Retention Device?	none present
40. Opposite Drive End Bearing Condition	

P40




41. Drive End Seal	none present
42. Opposite Drive End Seal	none present

Rotor Inspection

43. Rotor Type/Material	(Squirrel Aluminum) Squirrel Cage Aluminum Die Cast
-------------------------	--

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

44.	Growler Test		(Pass) Pass
45.	Number of Rotor Bars		
46.	Rotor Condition		acceptable
47.	List the Parts needed for the Repair Below 6319ZZC3 bearing 6313ZZC3 bearing		
48.	Signature of Technician that Disassembled Motor		
Mechanical Fits- Rotor			
49.	Shaft Runout		0.001 inches
50.	Rotor Runout		
	Drive End Bearing Fit	Rotor Body	Opposite Drive End Bearing
	0.002	2	2
51.	Coupling Fit Closest to Bearing Housing		
	0 Degrees	90 Degrees	120 Degrees
	3.375	3.375	3.375
52.	Coupling Fit Closest to the end of the Shaft		
	0 Degrees	60 Degrees	120 Degrees
	3.375	3.375	3.375
53.	Drive End Bearing Shaft Fit		
	0 Degrees	60 Degrees	120 Degrees
	3.7404	3.7404	3.7404
	Tolerance is 3.7403-3.7409		
54.	Drive End Bearing Shaft Fit Condition		(P) Pass



55. Opposite Drive End Bearing Shaft Fit

0 Degrees	60 Degrees	120 Degrees
2.5595	2.5595	2.5595

Tolerance is 2.5592-2.5597



56. Opposite Drive End Bearing Shaft Fit Condition (P) Pass

57. Shaft Air Seal Fits

Drive End Air Seal	Opposite Drive End Air Seal
Pass	Pass

Mechanical Fits- Bearing Housings



58. Drive End - Endbell Bearing Fit

0 Degrees	60 Degrees	120 Degrees
7.8771	7.8771	7.8774

Tolerance is 7.8740-7.8751

59. Drive End - Endbell Bearing Fit Condition (F) Fail

60. Opposite Drive End - Endbell Bearing Fit

P60

0 Degrees	60 Degrees	120 Degrees
5.5127	5.5127	5.5127




Tolerance is 5.5118-5.5128



61. Opposite Drive End - Endbell Bearing Fit Condition (P) Pass

62. Bearing Cap Condition

Drive End Bearing Cap	Opposite Drive End Bearing Cap
N/A	N/A

63. End Bell Air Seal Fits	
Drive End Air Seal	Opposite Drive End Air Seal
Pass	Pass
64. List Machine Work Needed Below	
<i>Bore and bush drive end.</i> <i>Drive end end bell is cracked and needs repaired</i>	
	
65. Technician	Brandon Woodard
	
Root Cause of Failure	
66. Failure locations	
67. Root cause of failure	