



## AC Inspection as Found

USG Interiors  
850 No Broadway  
Greenville, MS 38701

FolderID: 152685  
FormID: 20321981



### AC Inspection - Rev. 2

Location: Millington Motorshop

Serial Number:

Hi-Speed Job Number:	152685
Manufacturer:	Baldor
HP/kW:	100 (HP)
RPM:	1785 (RPM)
Frame:	405T
Voltage:	230 / 460
Current:	224/112 (Amps)
Phase:	Three
Hz:	60 (Hz)
Service Factor:	1.15
Enclosure:	TEFC
# of Leads:	9
J-box Included:	Complete
Coupling/Sheave:	None
Date Received:	04/24/2024
Bearing RTDs:	No
Stator RTDs:	No
Repair Stage:	Teardown Inspection
Heaters:	No
Winding Type :	Random Wound
Bearing Type:	Rolling Element

Priorities Found: ● 5 - High ● 41 - Good

### Overall Condition



- |                      |            |
|----------------------|------------|
| 1. Report Date       | 05/08/2024 |
| 2. Nameplate Picture | P2         |



- |  |    |
|--|----|
| 3. Photos of all six sides of the machine. | P3 |
|--|----|

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.



4. Describe the Overall Condition of the Equipment as Received

#### Initial Mechanical/Electrical

5. Does Shaft Turn Freely?	(Y) Yes
6. Does the shaft require T.I.R in Lathe to identify additional repairs?	(No) No
7. Does Shaft Have Visible Damage?	
8. Assembled Shaft Runout	0.001 Inches
9. Assembled Shaft End Play	0.0005 inches
10. Air Gap Variation <10%	no provision for measurement
11. Lead Condition	(P) Pass
12. Lead Length	12 Inches
13. Does it have Lugs?, If so what is the Stud Size?	(No) No

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

14.	Lead Numbers	1-9
15.	Frame Condition	
16.	Fan Condition	(P) Pass
17.	Broken or Missing Components	
Initial Electrical Inspection		
18.	Insulation Resistance/Megger	9516 Megohms P19
19.	Winding Resistance	P20
	1-2	1-3
	.0279	.0279
		2-3
		.0279
20.	Perform Surge Test	(P) Pass P21
21.	Number of Stator Slots	60

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

22.	Stator Condition	good	
23.	Stator Thermistors/Ohms	N/A	
24.	Stator Overloads/Ohms	N/A	
<b>Mechanical Inspection</b>			
25.	Drive End Bearing Brand	skf	
26.	Drive End Bearing Number-	6316 zz c3	
27.	Drive End Bearing Qty.	1	
28.	Drive End Bearing Type	(Ball) Ball Bearing	
29.	Drive End Lubrication Type	(Grease) Grease Lubricated	
30.	Drive End Bearing Insulation or Grounding Device?	none present	
31.	Drive End Wavy Washer/Snap-Ring Other Retention Device?	none present	
32.	Drive End Bearing Condition	normal wear	P33
			
33.	Opposite Drive End Bearing Brand	skf	
34.	Opposite Drive End Bearing Number-	6316 zz c3	
35.	Opposite Drive End Bearing Qty.	1	
36.	Opposite Drive End Bearing Type	(Ball) Ball Bearing	
37.	Opposite Drive End Lubrication Type	(Grease) Grease Lubricated	
38.	Opposite Drive End Bearing Insulation or Grounding Device?	none present	
39.	Opposite Drive End Wavy Washer/Snap-Ring Other Retention Device?	wavy washer	
40.	Opposite Drive End Bearing Condition	looks to have been ungreased	P41
			
41.	Drive End Seal	va-80	
42.	Opposite Drive End Seal	va-80	

### Rotor Inspection

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

43.	Rotor Type/Material	(Aluminum Bar) Aluminum Barred Rotor	
44.	Growler Test	(Pass) Pass	
45.	Number of Rotor Bars	47	
46.	Rotor Condition	good	
47.	List the Parts needed for the Repair Below 2- VA-80 lip seals 2- 6316 zz c3 bearings		
48.	Signature of Technician that Disassembled Motor		
<b>Mechanical Fits- Rotor</b>			
49.	Shaft Runout		
50.	Rotor Runout		
	Drive End Bearing Fit	Rotor Body	Opposite Drive End Bearing
51.	Coupling Fit Closest to Bearing Housing		
	0 Degrees	90 Degrees	120 Degrees
	2.8745	2.8745	2.8745
52.	Coupling Fit Closest to the end of the Shaft		
	0 Degrees	60 Degrees	120 Degrees
	2.875	2.875	2.875
53.	Drive End Bearing Shaft Fit		
	0 Degrees	60 Degrees	120 Degrees
	3.149	3.149	3.149
	80mm = 3.1496 Pressfit tolerance is from 3.1497 to 3.1502		
	<div>   </div>		
54.	Drive End Bearing Shaft Fit Condition	(F) Fail	
	I would recommend loctiting this bearing		



55. Opposite Drive End Bearing Shaft Fit

0 Degrees	60 Degrees	120 Degrees
3.1495	3.1495	3.1493

80mm = 3.1496 Pressfit tolerance is from 3.1497 to 3.1502



56. Opposite Drive End Bearing Shaft Fit Condition

(F) Fail

I would recommend loctiting this bearing to

57. Shaft Air Seal Fits

Drive End Air Seal	Opposite Drive End Air Seal
--------------------	-----------------------------

Mechanical Fits- Bearing Housings



58. Drive End - Endbell Bearing Fit

0 Degrees	60 Degrees	120 Degrees
6.6948	6.6948	6.6948

170mm = 6.6929 Tolerance is from 6.6929 to 6.6939



59. Drive End - Endbell Bearing Fit Condition

(F) Fail

This endbell needs to be bored and bushed

60. Opposite Drive End - Endbell Bearing Fit

0 Degrees	60 Degrees	120 Degrees
6.701	6.705	6.698

170mm = 6.6929 Tol. Is 6.6929 to 6.6939



61. Opposite Drive End - Endbell Bearing Fit Condition

(F) Fail

This bearing has been spinning in the endbell for a while  
This endbell has to be bored and bushed

62. Bearing Cap Condition

Drive End Bearing Cap	Opposite Drive End Bearing Cap
-----------------------	--------------------------------

63. End Bell Air Seal Fits

Drive End Air Seal	Opposite Drive End Air Seal
--------------------	-----------------------------

64. List Machine Work Needed Below

Both endbells need to be bored and bushed

65. Technician

Roger Ventrini

Root Cause of Failure

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

66.	Failure locations
67.	Root cause of failure