



AC Inspection as Found
Almatis Inc/RCP Bauxite (10014)
4701 Alcoa Road
Bauxite, AR 72011

FolderID: 103040
FormID: 20517314



AC Inspection - Rev. 2

Location: LR Motor Shop
Serial Number:
Description: 60HP EMERSON EVAL

Hi-Speed Job Number:	103040
Manufacturer:	Other
Product Number:	8P60P2C
Spec/ID #:	BJ53
HP/kW:	60 (HP)
RPM:	1785 (RPM)
Frame:	364T
Voltage:	460
Current:	69.0 (Amps)
Phase:	Three
Hz:	60 (Hz)
Service Factor:	1.15
Enclosure:	TEFC
# of Leads:	3
J-box Included:	Complete
Coupling/Sheave:	None
Date Received:	05/29/2024
Bearing RTDs:	No
Stator RTDs:	No
Repair Stage:	Teardown Inspection
Rewind:	No
Shaft Machined Fit Repairs Required:	No
Bearing Housing Machined Fit Repairs Required:	No
Heaters:	No
Winding Type :	Random Wound
Bearing Type:	Rolling Element

Priorities Found: ● 3 - High ● 8 - Good

Overall Condition



1. Report Date

06/05/2024

2. Nameplate Picture

P37



3. Photos of all six sides of the machine.

P45





4. Describe the Overall Condition of the Equipment as Received

Good condition. Passed all electrical tests. Requires new bearings and fan to recondition. Bearing cap bolts from opposite drive end were missing. Bearing cap spun on shaft but didn't cause any damage to shaft. Fins on rotor were ground down but not an issue.

Initial Mechanical/Electrical



5.	Does Shaft Turn Freely?	(Y) Yes
6.	Does the shaft require T.I.R in Lathe to identify additional repairs?	(No) No
7.	Does Shaft Have Visible Damage?	(No) No
8.	Assembled Shaft Runout	0.001 Inches
9.	Assembled Shaft End Play	0 inches
10.	Air Gap Variation <10%	No Provisions for measurement
11.	Lead Condition	(P) Pass

P69



12.	Lead Length	10 Inches
13.	Does it have Lugs?, If so what is the Stud Size?	(Yes) Yes
	5/16"	
14.	Lead Numbers	1-3
15.	Frame Condition	Pass



17. Broken or Missing Components

Lifting eye



Drilled and tapped.

Bearing cap bolts missing on ODE.



Initial Electrical Inspection





19. Winding Resistance

P20

1-2

1-3

2-3

.10037

.10013


.10032



20. Perform Surge Test

(P) Pass

P57



21. Number of Stator Slots

48

22. Stator Condition

P84



23. Stator Thermistors/Ohms

N/A

24. Stator Overloads/Ohms

N/A

Mechanical Inspection



25. Drive End Bearing Brand

MLK

P12



26. Drive End Bearing Number-

6313 C3

27. Drive End Bearing Qty.

1

28. Drive End Bearing Type

(Ball) Ball Bearing

29. Drive End Lubrication Type

(Grease) Grease Lubricated

30. Drive End Bearing Insulation or Grounding Device?

Nine

31. Drive End Wavy Washer/Snap-Ring Other Retention Device?

None

32. Drive End Bearing Condition

Normal wear

P82



Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.



34. Opposite Drive End Bearing Number-	6313 C3
35. Opposite Drive End Bearing Qty.	1
36. Opposite Drive End Bearing Type	(Ball) Ball Bearing
37. Opposite Drive End Lubrication Type	(Grease) Grease Lubricated
38. Opposite Drive End Bearing Insulation or Grounding Device?	None
39. Opposite Drive End Wavy Washer/Snap-Ring Other Retention Device?	wavy washer
40. Opposite Drive End Bearing Condition	Normal wear

P118



41. Drive End Seal

Labyrinth

P120




42. Opposite Drive End Seal


labyrinth


P123



Rotor Inspection			
43. Rotor Type/Material	(Squirrel Aluminum) Squirrel Cage Aluminum Die Cast		
44. Growler Test	(Pass) Pass		
45. Number of Rotor Bars	56		
46. Rotor Condition			P41



47.	List the Parts needed for the Repair Below	
	6313 C3 x2 3/4 eye bolt Fan	
48.	Signature of Technician that Disassembled Motor	Brandon Woodard
		

Mechanical Fits- Rotor			
49. Shaft Runout	0.001 inches		
50. Rotor Runout			
Drive End Bearing Fit	Rotor Body	Opposite Drive End Bearing	
0.001	0.001	0.001	

51. Coupling Fit Closest to Bearing Housing

P33

0 Degrees	90 Degrees	120 Degrees
2.375	2.375	2.375



52. Coupling Fit Closest to the end of the Shaft

0 Degrees	60 Degrees	120 Degrees
2.375	2.375	2.375

53. Drive End Bearing Shaft Fit

P79

0 Degrees	60 Degrees	120 Degrees
2.5592	2.5592	2.5592

Tolerance is 2.5592-2.5597



54. Drive End Bearing Shaft Fit Condition

(P) Pass

55. Opposite Drive End Bearing Shaft Fit

0 Degrees	60 Degrees	120 Degrees
2.5598	2.5598	2.5598

Tolerance is 2.5592-2.5597



56. Opposite Drive End Bearing Shaft Fit Condition (P) Pass

57. Shaft Air Seal Fits

Drive End Air Seal	Opposite Drive End Air Seal
Pass	Pass

Mechanical Fits- Bearing Housings



P2

58. Drive End - Endbell Bearing Fit

0 Degrees	60 Degrees	120 Degrees
5.1125	5.1125	5.1125

Tolerance is 5.5118-5.5128



59. Drive End - Endbell Bearing Fit Condition (P) Pass

60. Opposite Drive End - Endbell Bearing Fit

0 Degrees	60 Degrees	120 Degrees
5.1126	5.1126	5.1126

Tolerance is 5.5118-5.5128



61. Opposite Drive End - Endbell Bearing Fit Condition (P) Pass

62. Bearing Cap Condition

Drive End Bearing Cap	Opposite Drive End Bearing Cap
Pass	Pass

63. End Bell Air Seal Fits

Drive End Air Seal	Opposite Drive End Air Seal
Pass	Pass

64. List Machine Work Needed Below

None

65. Technician Brandon Woodard

Root Cause of Failure

66. Failure locations

67. Root cause of failure