



Hi-Speed Industrial Service
7030 Ryburn Dr
Millington, Tn 38053
901-873-5300

AC Inspection as Found
UNITED SOLUTIONS
1052 INDUSTRIAL PARK RD
SARDIS, MS 38666

FolderID: 153300
FormID: 21235398



AC Inspection - Rev. 2

Location: Motor Shop

Serial Number:

Hi-Speed Job Number:	153300
Manufacturer:	Other
Product Number:	WK 315M/4-550T
Spec/ID #:	7215392
HP/kW:	400 (HP)
RPM:	1780 (RPM)
Frame:	550T
Voltage:	460
Current:	450 (Amps)
Phase:	Three
Hz:	60 (Hz)
# of Leads:	12
J-box Included:	Complete
Coupling/Sheave:	Coupling
Date Received:	07/25/2024
Bearing RTDs:	No
Stator RTDs:	No
Repair Stage:	Teardown Inspection
Rewind:	Yes
Shaft Machined Fit Repairs Required:	No
Bearing Housing Machined Fit Repairs Required:	No
Heaters:	No
Winding Type :	Random Wound
Bearing Type:	Rolling Element

Priorities Found: ● 3 - High ● 8 - Good

Overall Condition



1. Report Date

08/07/2024

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

2. Nameplate Picture

P2



3. Photos of all six sides of the machine.

P3





4. Describe the Overall Condition of the Equipment as Received

Stator windings blown in center of iron. Requires extensive repair work or restack. Rotor has several rotor bars broken and requires extensive repair or replacement.

5. Distance from the end of the shaft to the Coupling/Sheave

-0.25 inches

P5







6. Report Date [COPY]



Initial Mechanical/Electrical



7.	Does Shaft Turn Freely?	(Y) Yes
8.	Does the shaft require T.I.R in Lathe to identify additional repairs?	(No) No
9.	Does Shaft Have Visible Damage?	(No) No
10.	Assembled Shaft Runout	0.001 Inches
11.	Assembled Shaft End Play	0.001 inches

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

12.	Air Gap Variation <10%	No Provisions for Measurement	
● 13.	Lead Condition	(P) Pass	
14.	Lead Length	24 Inches	
● 15.	Does it have Lugs?, If so what is the Stud Size?	(No) No	
16.	Lead Numbers		P16
<div>   </div>			
17.	Frame Condition	Pass	
18.	Fan Condition	(N) NA	
19.	Broken or Missing Components		P22
<div>  </div>			
Coupling set screw			
Initial Electrical Inspection 			
20.	Insulation Resistance/Megger	0 Megohms	
21.	Winding Resistance		
	1-2	1-3	2-3
	0	0	0
● 22.	Perform Surge Test	(F) Fail	
23.	Number of Stator Slots	60	

24.	Stator Condition	Requires rewind	P27
	Additionally stator will require extensive iron work or restock!!!		
			
25.	Stator Thermistors/Ohms	186	
26.	Stator Overloads/Ohms	N/A	
Mechanical Inspection			
27.	Drive End Bearing Brand	FAG	P30
			
28.	Drive End Bearing Number-	6317 C3	
29.	Drive End Bearing Qty.	1	
30.	Drive End Bearing Type	(Ball) Ball Bearing	
31.	Drive End Lubrication Type	(Grease) Grease Lubricated	
32.	Drive End Bearing Insulation or Grounding Device?	None	

33. Drive End Wavy Washer/Snap-Ring Other Retention Device?

P36



34. Drive End Bearing Condition

Normal wear

35. Opposite Drive End Bearing Brand

FAG

P38



36. Opposite Drive End Bearing Number-

6317 c3

37. Opposite Drive End Bearing Qty.

1

38. Opposite Drive End Bearing Type

(Ball) Ball Bearing

39. Opposite Drive End Lubrication Type

(Grease) Grease Lubricated

40. Opposite Drive End Bearing Insulation or Grounding Device?

None

41. Opposite Drive End Wavy Washer/Snap-Ring Other Retention Device?

P44




42. Opposite Drive End Bearing Condition

Normal wear

P45

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.




43.	Drive End Seal	va 85
44.	Opposite Drive End Seal	va 85
Rotor Inspection		
45.	Rotor Type/Material	(Copper Barred) Copper Barred Rotor
46.	Growler Test	(Pass) Pass
47.	Number of Rotor Bars	48

48. Rotor Condition

requires extensive repair

P59

Several rotor bars broken.



49. List the Parts needed for the Repair Below

2- Va 85
2- 6317 c3

50. Signature of Technician that Disassembled Motor

Brandon Woodard

A handwritten signature in black ink, appearing to read "Brandon Woodard".

Mechanical Fits- Rotor



51. Shaft Runout **0.001 inches**

52. Rotor Runout

Drive End Bearing Fit	Rotor Body	Opposite Drive End Bearing
0.001	0.001	0.001

53. Coupling Fit Closest to Bearing Housing

0 Degrees	90 Degrees	120 Degrees
3.125	3.125	3.125

54. Coupling Fit Closest to the end of the Shaft

0 Degrees	60 Degrees	120 Degrees
3.125	3.125	3.125

55. Drive End Bearing Shaft Fit

P66

0 Degrees	60 Degrees	120 Degrees
3.3467	3.3467	3.3467

Tolerance is 3.3466-4.3472



56. Drive End Bearing Shaft Fit Condition **(P) Pass**

57. Opposite Drive End Bearing Shaft Fit

P68



0 Degrees	60 Degrees	120 Degrees
3.3468	3.3468	3.3468

Tolerance is 3.3466-4.3472



58. Opposite Drive End Bearing Shaft Fit Condition **(P) Pass**

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

59.	Shaft Air Seal Fits		
	Drive End Air Seal	Opposite Drive End Air Seal	
	Pass	Pass	
Mechanical Fits- Bearing Housings			
60.	Drive End - Endbell Bearing Fit		P71
	0 Degrees	60 Degrees	120 Degrees
	7.0872	7.0872	7.0872
	Tolerance is 7.0866-7.0876		
			
61.	Drive End - Endbell Bearing Fit Condition		(P) Pass
62.	Opposite Drive End - Endbell Bearing Fit		P73
	0 Degrees	60 Degrees	120 Degrees
	7.0871	7.0871	7.0871
	Tolerance is 7.0866-7.0876		
			
63.	Opposite Drive End - Endbell Bearing Fit Condition		(P) Pass
64.	Bearing Cap Condition		
	Drive End Bearing Cap	Opposite Drive End Bearing Cap	
	Pass	Pass	
65.	End Bell Air Seal Fits		
	Drive End Air Seal	Opposite Drive End Air Seal	
	Pass	Pass	
66.	List Machine Work Needed Below		
	None		
67.	Technician		Brandon Woodard

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.



Root Cause of Failure

68. Failure locations

69. Root cause of failure