



Hi-Speed Industrial Service  
7030 Ryburn Dr  
Millington, Tn 38053  
901-873-5300

## AC Inspection as Found

Big River Steel (004767)

2027 E State Highway 198  
Osceola, AR 72370

FolderID: 153676  
FormID: 21608538



### AC Inspection - Rev. 2

Location: Default

Serial Number:

Hi-Speed Job Number: 153676

Manufacturer: Rossi

Product Number: RC00037158

Serial Number: 1960678

HP/kW: 4 (HP)

RPM: 1740 (RPM)

Voltage: 230 / 460

Current: 10-5.8 (Amps)

Phase: Three

Hz: 60 (Hz)

Service Factor: 1.15

Enclosure: TEFC

# of Leads: 6

J-box Included: Complete

Coupling/Sheave: Gear

Date Received: 09/13/2024

Bearing RTDs: No

Stator RTDs: No

Repair Stage: Teardown Inspection

Shaft Machined Fit Repairs  
Required: No

Bearing Housing Machined  
Fit Repairs Required: No

Heaters: No

Winding Type : Random Wound

Bearing Type: Rolling Element

Priorities Found: ● 3 - High

● 11 - Good

### Overall Condition



1. Report Date

09/13/2024

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

Printed on 9/24/2024

Powered by [INSPECTALL](#)

Page 1 of 7

2. Nameplate Picture

P2




3. Photos of all six sides of the machine.





P3








4.	Describe the Overall Condition of the Equipment as Received <i>Rewind stator and replace gear box seals</i>	
5.	Distance from the end of the shaft to the Coupling/Sheave <i>Shouldered with shaft bolt</i>	0 inches
6.	Report Date [COPY]	09/13/2024
Initial Mechanical/Electrical		
7.	Does Shaft Turn Freely?	(Y) Yes
8.	Does the shaft require T.I.R in Lathe to identify additional repairs?	(No) No
9.	Does Shaft Have Visible Damage?	(No) No
10.	Assembled Shaft Runout	0.001 Inches
11.	Assembled Shaft End Play	0.0005 inches

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

12.	Air Gap Variation <10%	no provision for measurement	
●	13. Lead Condition	(P) Pass	P13
<div>   </div>			
	14. Lead Length	4 Inches	
●	15. Does it have Lugs?, If so what is the Stud Size?	(Yes) Yes	P15
<div>  </div>			
	16. Lead Numbers	1-6	
	17. Frame Condition	good	
●	18. Fan Condition	(P) Pass	
	19. Broken or Missing Components	none	
<b>Initial Electrical Inspection</b>			
	20. Insulation Resistance/Megger	4204 Megohms	
	21. Winding Resistance		
	1-2	1-3	2-3
	2.206	2.835	0.814



23.	Number of Stator Slots	36	
24.	Stator Condition	rewind	
25.	Stator Thermistors/Ohms	.590	
	1- .590 k ohms		
26.	Stator Overloads/Ohms		
Mechanical Inspection			
27.	Drive End Bearing Brand	nsk	
28.	Drive End Bearing Number-	6206 zz c3	
29.	Drive End Bearing Qty.	1	
30.	Drive End Bearing Type	(Ball) Ball Bearing	
31.	Drive End Lubrication Type	(Grease) Grease Lubricated	
32.	Drive End Bearing Insulation or Grounding Device?	none present	
33.	Drive End Wavy Washer/Snap-Ring Other Retention Device?	wavy washer	P33



34.	Drive End Bearing Condition	
35.	Opposite Drive End Bearing Brand	<b>nsk</b>
36.	Opposite Drive End Bearing Number-	<b>6206 2rs</b>
37.	Opposite Drive End Bearing Qty.	<b>1</b>
38.	Opposite Drive End Bearing Type	<b>(Ball) Ball Bearing</b>
39.	Opposite Drive End Lubrication Type	<b>(Grease) Grease Lubricated</b>
40.	Opposite Drive End Bearing Insulation or Grounding Device?	<b>none present</b>
41.	Opposite Drive End Wavy Washer/Snap-Ring Other Retention Device?	<b>snap ring on shaft and in endbell</b>
42.	Opposite Drive End Bearing Condition	

Page 5 of 7



44. Opposite Drive End Seal

va32-20

**Rotor Inspection**

45. Rotor Type/Material (Aluminum Bar) Aluminum Barred Rotor

46. Growler Test (Pass) Pass

47. Number of Rotor Bars 26

48. Rotor Condition good

49. List the Parts needed for the Repair Below

- 1- VA32-20
- 1- 30-50-7 lip seal
- 2- 6206 2rs c3 bearings
- 1- 40-90-8/7 lipseal
- 1- 50-66-8/8.5 lipseal

50. Signature of Technician that Disassembled Motor

Nigel Hill

**Mechanical Fits- Rotor**

51. Shaft Runout

52. Rotor Runout

Drive End Bearing Fit

Rotor Body

Opposite Drive End Bearing

53. Coupling Fit Closest to Bearing Housing

0 Degrees

90 Degrees

120 Degrees

54. Coupling Fit Closest to the end of the Shaft

0 Degrees

60 Degrees

120 Degrees

55. Drive End Bearing Shaft Fit

0 Degrees

60 Degrees

120 Degrees

1.1815


1.1814

1.1814

Tol. 1.1815-1.1812

56. Drive End Bearing Shaft Fit Condition

(P) Pass

57.	Opposite Drive End Bearing Shaft Fit		
	0 Degrees	60 Degrees	120 Degrees
	1.1813	1.1813	1.1813
	Tol. 1.1815-1.1812		
58.	Opposite Drive End Bearing Shaft Fit Condition (P) Pass		
59.	Shaft Air Seal Fits		
	Drive End Air Seal	Opposite Drive End Air Seal	
	good	good	
Mechanical Fits- Bearing Housings			
60.	Drive End - Endbell Bearing Fit		
	0 Degrees	60 Degrees	120 Degrees
	2.4414	2.4415	2.4414
	Tol. 2.4409-2.4416		
61.	Drive End - Endbell Bearing Fit Condition (P) Pass		
62.	Opposite Drive End - Endbell Bearing Fit		
	0 Degrees	60 Degrees	120 Degrees
	2.441	2.4411	2.4411
	Tol. 2.4409-2.4416		
63.	Opposite Drive End - Endbell Bearing Fit Condition (P) Pass		
64.	Bearing Cap Condition		
	Drive End Bearing Cap	Opposite Drive End Bearing Cap	
	n/a	n/a	
65.	End Bell Air Seal Fits		
	Drive End Air Seal	Opposite Drive End Air Seal	
	good	good	
66.	List Machine Work Needed Below		
	No work needed		
67.	Technician		Nigel Hill
			
Root Cause of Failure			
68.	Failure locations		
	Winding failed		
69.	Root cause of failure		