



Hi-Speed Industrial Service  
7030 Ryburn Dr  
Millington, Tn 38053  
901-873-5300

## AC Inspection as Found

ARKEMA, INC.  
2571 Fite Road  
Memphis, TN 38127

FolderID: 153189  
FormID: 20989729



### AC Inspection - Rev. 2

Location: MLMR Shop

Serial Number:

Description: 125 HP

Hi-Speed Job Number: 153189

Manufacturer: Siemens

HP/kW: 125 (HP)

RPM: 1785 (RPM)

Frame: 444T

Voltage: 460

Current: 145 (Amps)

Phase: Three

Hz: 60 (Hz)

Service Factor: 1.15

Enclosure: TEFC

# of Leads: 6

J-box Included: None

Coupling/Sheave: None

Date Received: 07/11/2024

Bearing RTDs: No

Stator RTDs: No

Repair Stage: Teardown Inspection

Rewind: Yes

Shaft Machined Fit Repairs  
Required: No

Bearing Housing Machined  
Fit Repairs Required: Yes

Heaters: No

Winding Type : Random Wound

Bearing Type: Rolling Element

Priorities Found: ● 3 - High ● 8 - Good

### Overall Condition



1. Report Date

07/12/2024

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

Printed on 8/2/2024

Powered by [INSPECTALL](#)

Page 1 of 9

2. Nameplate Picture

P2



3. Photos of all six sides of the machine.

P3





4. Describe the Overall Condition of the Equipment as Received

*Failed electrical tests and requires rewind. Additional requires machine work to bearing fits*

#### Initial Mechanical/Electrical



5.	Does Shaft Turn Freely?	(Y) Yes
6.	Does the shaft require T.I.R in Lathe to identify additional repairs?	(No) No
7.	Does Shaft Have Visible Damage?	(No) No
8.	Assembled Shaft Runout	0.003 Inches
9.	Assembled Shaft End Play	0.002 inches
10.	Air Gap Variation <10%	No Provisions for measurement
11.	Lead Condition	(P) Pass
12.	Lead Length	22 Inches
13.	Does it have Lugs?, If so what is the Stud Size?	(No) No
14.	Lead Numbers	11,22,33
15.	Frame Condition	Pass
16.	Fan Condition	(P) Pass



Fins broke of by fork lift driver at Arkema.

### Initial Electrical Inspection



18. Insulation Resistance/Megger **100000 Megohms**

19. Winding Resistance

P19

1-2

1-3

2-3

.03603

.03396


.03564



20. Perform Surge Test

(F) Fail

P20






21. Number of Stator Slots

48

22. Stator Condition

Requires rewind

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

23.	Stator Thermistors/Ohms	N/A	
24.	Stator Overloads/Ohms	N/A	
<b>Mechanical Inspection</b>			
25.	Drive End Bearing Brand	NTN	P25
			
26.	Drive End Bearing Number-	6318 Z C3	
27.	Drive End Bearing Qty.	1	
28.	Drive End Bearing Type	(Ball) Ball Bearing	
29.	Drive End Lubrication Type	(Grease) Grease Lubricated	
30.	Drive End Bearing Insulation or Grounding Device?	None	
31.	Drive End Wavy Washer/Snap-Ring Other Retention Device?	Snap Ring	
32.	Drive End Bearing Condition	Normal wear	P32
			





34. Opposite Drive End Bearing Number-	6316 ZC3
35. Opposite Drive End Bearing Qty.	1
36. Opposite Drive End Bearing Type	(Ball) Ball Bearing
37. Opposite Drive End Lubrication Type	(Grease) Grease Lubricated
38. Opposite Drive End Bearing Insulation or Grounding Device?	None
39. Opposite Drive End Wavy Washer/Snap-Ring Other Retention Device?	Wavy Washer
40. Opposite Drive End Bearing Condition	Normal wear

P40



41. Drive End Seal	None
42. Opposite Drive End Seal	None

**Rotor Inspection**

43. Rotor Type/Material	(Squirrel Aluminum) Squirrel Cage Aluminum Die Cast
44. Growler Test	(Pass) Pass
45. Number of Rotor Bars	36
46. Rotor Condition	Pass

47. List the Parts needed for the Repair Below

6318 C3  
6316 C3  
Rewind

48. Signature of Technician that Disassembled Motor

Brandon Woodard



### Mechanical Fits- Rotor



49. Shaft Runout **0.001 inches**

50. Rotor Runout

Drive End Bearing Fit	Rotor Body	Opposite Drive End Bearing
<b>0.001</b>	<b>0.001</b>	<b>0.001</b>

51. Coupling Fit Closest to Bearing Housing

P51

0 Degrees	90 Degrees	120 Degrees
<b>3.375</b>	<b>3.375</b>	<b>3.375</b>



52. Coupling Fit Closest to the end of the Shaft

0 Degrees	60 Degrees	120 Degrees
<b>3.375</b>	<b>3.375</b>	<b>3.375</b>

53. Drive End Bearing Shaft Fit

P53

0 Degrees	60 Degrees	120 Degrees
<b>3.5439</b>	<b>3.5439</b>	<b>3.5439</b>

 *Tolerance is 3.5434-3.5440*



54. Drive End Bearing Shaft Fit Condition

**(P) Pass**

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

55. Opposite Drive End Bearing Shaft Fit

0 Degrees	60 Degrees	120 Degrees
3.1501	3.1501	3.1501

Tolerance is 3.1497-3.1502



56. Opposite Drive End Bearing Shaft Fit Condition

(P) Pass

57. Shaft Air Seal Fits

Drive End Air Seal	Opposite Drive End Air Seal
Pass	Pass

Mechanical Fits- Bearing Housings



58. Drive End - Endbell Bearing Fit

0 Degrees	60 Degrees	120 Degrees
7.4815	7.4815	7.4815

Tolerance is 7.4803-7.4814



59. Drive End - Endbell Bearing Fit Condition

(P) Pass



60. Opposite Drive End - Endbell Bearing Fit

0 Degrees	60 Degrees	120 Degrees
6.6968	6.6962	6.6964

Tolerance is 6.6929-6.6939. Out of tolerance and requires bore and bushing installed



61. Opposite Drive End - Endbell Bearing Fit Condition (F) Fail

62. Bearing Cap Condition

Drive End Bearing Cap	Opposite Drive End Bearing Cap
Pass	Pass

63. End Bell Air Seal Fits

Drive End Air Seal	Opposite Drive End Air Seal
Pass	Pass

64. List Machine Work Needed Below

Bore and install bushing in opposite drive end endbell.

65. Technician Brandon Woodard

Root Cause of Failure

66. Failure locations

67. Root cause of failure