



Hi-Speed Industrial Service
7030 Ryburn Dr
Millington, Tn 38053
901-873-5300

AC Inspection as Found

KTG USA
400 Mahannah
Memphis, TN 38107

FolderID: 152514
FormID: 20012153



AC Inspection - Rev. 2

Location: Default

Serial Number:

Description: 125 HP AC

Hi-Speed Job Number: 152514

Manufacturer: GE

HP/kW: 125 (HP)

RPM: 1190 (RPM)

Voltage: 460

Current: 139 (Amps)

Phase: Three

Hz: 60 (Hz)

Service Factor: 1.15

Enclosure: TEFC

of Leads: 3

J-box Included: None

Coupling/Sheave: None

Date Received: 04/04/2024

Bearing RTDs: No

Stator RTDs: No

Repair Stage: Teardown Inspection

Rewind: No

Shaft Machined Fit Repairs
Required: Yes

Bearing Housing Machined
Fit Repairs Required: No

Heaters: No

Winding Type : Random Wound

Bearing Type: Rolling Element

Priorities Found: ● 4 - High ● 7 - Good

Overall Condition



1. Report Date **04/08/2024**

2. Nameplate Picture

P2



Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.



4. Describe the Overall Condition of the Equipment as Received

Good condition. Drive end bearing spun on shaft and shaft requires repair. Passed all electrical tests. Drive end bearing was electric fluted. Recommend adding AEGIS ring and insulated bearing.

Initial Mechanical/Electrical



5. Does Shaft Turn Freely?	(Y) Yes
6. Does the shaft require T.I.R in Lathe to identify additional repairs?	(No) No
7. Does Shaft Have Visible Damage?	(No) No
8. Assembled Shaft Runout	0.001 Inches
9. Assembled Shaft End Play	0.003 inches
10. Air Gap Variation <10%	No Provisions for measurement

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.



12. Lead Length	20 Inches	
13. Does it have Lugs?, If so what is the Stud Size?	(Yes) Yes	P13
<div>1/2"</div>		



14. Lead Numbers	None	
15. Frame Condition	Pass	
16. Fan Condition	(F) Fail	P16
<div>Cracked and needs replaced</div>		



17. Broken or Missing Components	None	
----------------------------------	------	--



19. Winding Resistance

P19

1-2

1-3

2-3

.06205

.0612


.06117



20. Perform Surge Test

(P) Pass

P20



21. Number of Stator Slots

72

22. Stator Condition

P22



23. Stator Thermistors/Ohms

N/A

24. Stator Overloads/Ohms

N/A

Mechanical Inspection



25. Drive End Bearing Brand

KOYO

P25



26. Drive End Bearing Number-

6318 ZZ C3

27. Drive End Bearing Qty.

1

28. Drive End Bearing Type

(Ball) Ball Bearing

29. Drive End Lubrication Type

(Grease) Grease Lubricated

30. Drive End Bearing Insulation or Grounding Device?

None


31. Drive End Wavy Washer/Snap-Ring Other Retention Device?

None

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.





41.	Drive End Seal	None
42.	Opposite Drive End Seal	None
Rotor Inspection		
43.	Rotor Type/Material	(Squirrel Aluminum) Squirrel Cage Aluminum Die Cast
44.	Growler Test	(Pass) Pass
45.	Number of Rotor Bars	60
46.	Rotor Condition	

P46



47. List the Parts needed for the Repair Below

P47

Fan

6318 ZZ C3

6318 ZZ C3 insulated

Aegis ring SGR-104.3-3FH



48. Signature of Technician that Disassembled Motor

Brandon Woodard

Mechanical Fits- Rotor



49. Shaft Runout **0.001 inches**

50. Rotor Runout

Drive End Bearing Fit

Rotor Body

Opposite Drive End Bearing

0.002

0.002

0.002

51. Coupling Fit Closest to Bearing Housing

P51

0 Degrees

90 Degrees

120 Degrees

3.3666

3.3666

3.3666



52. Coupling Fit Closest to the end of the Shaft

0 Degrees

60 Degrees

120 Degrees

3.3732

3.3732

3.3732

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

53. Drive End Bearing Shaft Fit

0 Degrees	60 Degrees	120 Degrees
3.5428	3.5429	3.5425

Tolerance is 3.5434-3.5440
Bearing pulled of shaft. Requires repair.



54. Drive End Bearing Shaft Fit Condition (F) Fail

55. Opposite Drive End Bearing Shaft Fit

P55

0 Degrees	60 Degrees	120 Degrees
3.5435	3.5435	3.5435

Tolerance is 3.5434-3.5440



56. Opposite Drive End Bearing Shaft Fit Condition (P) Pass

57. Shaft Air Seal Fits

Drive End Air Seal	Opposite Drive End Air Seal
Pass	Pass

Mechanical Fits- Bearing Housings



58. Drive End - Endbell Bearing Fit

P58

0 Degrees

60 Degrees

120 Degrees

7.4812

7.4812

7.4812



59. Drive End - Endbell Bearing Fit Condition

(P) Pass

60. Opposite Drive End - Endbell Bearing Fit

P60

0 Degrees

60 Degrees

120 Degrees

7.4815

7.4815

7.4815



61. Opposite Drive End - Endbell Bearing Fit Condition

(P) Pass

62. Bearing Cap Condition

Drive End Bearing Cap

Opposite Drive End Bearing Cap

Pass

Pass

63. End Bell Air Seal Fits

Drive End Air Seal

Opposite Drive End Air Seal

Pass

Pass

64. List Machine Work Needed Below

Repair drive end shaft bearing fit. Normal turn and metalizing.

65. Technician

Brandon Woodard

A handwritten signature in black ink, appearing to read 'Brandon Woodard'.

Root Cause of Failure

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

66. Failure locations

Drive end bearing

67. Root cause of failure

Spun on shaft.