



QualiTest® Diagnostics

7030 Ryburn Dr. Millington, TN

Phone: (901) 873-5300

Fax: (901) 873-5301

www.gohispeed.com

September 24, 2024

Terry Glover
USG
Greenville, MS

Terry,

The following is a summary report from the September 2024 quarterly oil analysis on the Wet Zone and Dry Zone Circ Fan Bearings. Please let us know if there are any questions or comments. As always, it has been a pleasure to serve USG-Greenville, MS. If there are any comments or questions, do not hesitate to contact us.

Sincerely,

A handwritten signature in black ink that reads 'Kevin W. Maxwell'.

Senior Reliability Specialist
ISO/ANSI Certified Vibration Analyst, Category III



QualiTest® Diagnostics

Cell: 901-486-4565

Email: kwilliam@gohispeed.com

Hi-Speed Industrial Service tests and inspects industrial machinery and equipment and makes recommendations concerning maintenance and repairs based on its experience in the field of industrial repair and maintenance. The information contained herein is provided as an opinion only, not as a guaranty or warranty of the matters discussed herein.

Wet Zone Circ Fan Drive Bearing

Note copper, lead, tin, and silicon. The oil has an ISO 46 viscosity, and it isn't contaminated with water or overly oxidized based on the insolubles. We'll look for metals and silicon to decrease or stabilize next time. **OIL IS OK FOR USE**

ELEMENTS IN PARTS PER MILLION	MI/HR on Oil		UNIT / LOCATION AVERAGES					UNIVERSAL AVERAGES
	MI/HR on Unit							
	Sample Date	9/14/2024						
	Make Up Oil Added							
ALUMINUM	2	1						4
CHROMIUM	0	0						0
IRON	26	13						19
COPPER	18	22						7
LEAD	226	160						3
TIN	76	33						1
MOLYBDENUM	0	0						3
NICKEL	0	0						0
MANGANESE	0	0						0
SILVER	0	0						0
TITANIUM	0	0						1
POTASSIUM	1	1						1
BORON	1	1						4
SILICON	18	10						5
SODIUM	3	3						6
CALCIUM	115	100						145
MAGNESIUM	1	1						23
PHOSPHORUS	366	342						345
ZINC	562	456						178
BARIIUM	0	0						1

Values
Should Be*

PROPERTIES	SUS Viscosity @ 210°F	49.4					
	cSt Viscosity @ 100°C	7.10					
	Flashpoint in °F	425					
	Fuel %	-					
	Antifreeze %	-					
	Water %	0.0	0.0				
	Insolubles %	0.3	<0.6				
	TBN						
	TAN						
	ISO Code						

* THIS COLUMN REFERS ONLY TO THE CURRENT SAMPLE

Dry Zone Circ Fan Drive Bearing

Copper, lead, and tin could be elevated at these levels. No water contamination or excess oil oxidation is evident. The viscosity is in the ISO 46 range. We'll learn more with trends; however, an oil change would help reset metal counts. **CHANGE OIL SOON**

ELEMENTS IN PARTS PER MILLION	MI/HR on Oil							
	MI/HR on Unit		UNIT /					UNIVERSAL
	Sample Date	9/14/2024	LOCATION					AVERAGES
	Make Up Oil Added		AVERAGES					
ALUMINUM	0	1						4
CHROMIUM	0	0						0
IRON	9	13						19
COPPER	14	22						7
LEAD	128	160						3
TIN	9	33						1
MOLYBDENUM	0	0						3
NICKEL	0	0						0
MANGANESE	0	0						0
SILVER	0	0						0
TITANIUM	0	0						1
POTASSIUM	2	1						1
BORON	1	1						4
SILICON	8	10						5
SODIUM	3	3						6
CALCIUM	90	100						145
MAGNESIUM	2	1						23
PHOSPHORUS	306	342						345
ZINC	403	456						178
BARIIUM	0	0						1

Values
Should Be*

PROPERTIES	SUS Viscosity @ 210°F	48.1					
	cSt Viscosity @ 100°C	6.68					
	Flashpoint in °F	360					
	Fuel %	-					
	Antifreeze %	-					
	Water %	0.0	0.0				
	Insolubles %	TR	<0.6				
	TBN						
	TAN						
	ISO Code						

