

LR Field Services

Prepared for Tolm Group Inc (12758)

210 N Moose St
Morrilton AR 72110

Table of Contents

AC Inspection as Found - <i>LR MOTOR SHOP</i>	AC Inspection - Rev. 2	1.0
AC Random Coil Rewind Report		2.0



Hi-Speed Industrial Service
7030 Ryburn Dr
Millington, Tn 38053
901-873-5300

AC Inspection as Found

Tolm Group Inc (12758)

210 N Moose St
Morrliton, AR 72110

FolderID: 103543
FormID: 21721874

AC Inspection - Rev. 2

Location: LR MOTOR SHOP

Serial Number:

Description: 150 HP WEG

Hi-Speed Job Number: 103543

Manufacturer: WEG

Product Number: T15036ET3G445TS-W22

HP/kW: 150 (HP)

RPM: 3570 (RPM)

Frame: 444/5TS

Voltage: 460

Current: 163

Phase: Three

Hz: 60 (Hz)

Service Factor: 1.15

Enclosure: TEFC

of Leads: 12

J-box Included: None

Coupling/Sheave: Coupling (FLUSH)

Date Received: 09/24/2024

Bearing RTDs: No

Stator RTDs: No

Repair Stage: Final

Rewind: Yes

Shaft Machined Fit Repairs
Required: No

Bearing Housing Machined
Fit Repairs Required: Yes

Heaters: Yes

Winding Type : Random Wound

Bearing Type: Rolling Element

Priorities Found: ● 1 - High ● 9 - Good

Overall Condition

1. Report Date

09/24/2024

2. Nameplate Picture

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

Printed on 11/25/2024

Powered by [INSPECTALL](#)

1.0



3. Photos of all six sides of the machine.






Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

Printed on 11/25/2024

Powered by [INSPECTALL](#)





4. Describe the Overall Condition of the Equipment as Received
Serviceable

5. Distance from the end of the shaft to the Coupling/Sheave
Flush



0 inches




Initial Mechanical/Electrical

6.	Does Shaft Turn Freely?	(Y) Yes
7.	Does the shaft require T.I.R in Lathe to identify additional repairs?	(No) No
8.	Does Shaft Have Visible Damage?	(No) No
9.	Assembled Shaft Runout	0.002 Inches

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

10. Assembled Shaft End Play	0 inches
11. Air Gap Variation <10%	
12. Lead Condition	(P) Pass
	
13. Lead Length	15 Inches
14. Does it have Lugs?, If so what is the Stud Size?	(Yes) Yes
15. Lead Numbers	T1-T12
16. Frame Condition	pass
17. Fan Condition	(P) Pass
	

18. Heater Quantity, Ratings			
Quantity	Volts/Watts	Pass/Fail	
2	110/140	pass	
			
19. Broken or Missing Components		All connection box mount bolts	
Initial Electrical Inspection			
20. Insulation Resistance/Megger		Megohms	
21. Winding Resistance			
1-2	1-3	2-3	
22. Perform Surge Test			
23. Number of Stator Slots		48	
24. Stator Condition		rewind	
25. Stator Thermistors/Ohms			
26. Stator Overloads/Ohms			
Mechanical Inspection			
27. Drive End Bearing Brand		C&U	
28. Drive End Bearing Number-		6314 C3	
29. Drive End Bearing Qty.		1	
30. Drive End Bearing Type		(Ball) Ball Bearing	
31. Drive End Lubrication Type		(Grease) Grease Lubricated	
32. Drive End Bearing Insulation or Grounding Device?		none	
33. Drive End Wavy Washer/Snap-Ring Other Retention Device?		none	
34. Drive End Bearing Condition		contaminated grease.	
35. Opposite Drive End Bearing Brand		C&U	
36. Opposite Drive End Bearing Number-		6314	
37. Opposite Drive End Bearing Qty.		1	
38. Opposite Drive End Bearing Type		(Ball) Ball Bearing	
39. Opposite Drive End Lubrication Type		(Grease) Grease Lubricated	
40. Opposite Drive End Bearing Insulation or Grounding Device?		none	
41. Opposite Drive End Wavy Washer/Snap-Ring Other Retention Device?		snap ring	
42. Opposite Drive End Bearing Condition		replace	

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.



- 43. Drive End Seal
- 44. Opposite Drive End Seal

Rotor Inspection

- 45. Rotor Type/Material

(Squirrel Aluminum) Squirrel
Cage Aluminum Die Cast



- 46. Growler Test (Pass) Pass
- 47. Number of Rotor Bars 40
- 48. Rotor Condition pass
- 49. List the Parts needed for the Repair Below
- 50. Signature of Technician that Disassembled Motor Terrence Holland

[Handwritten signature: Terrence Holland]

Mechanical Fits- Rotor

- 51. Shaft Runout 0.002 inches
- 52. Rotor Runout
 - Drive End Bearing Fit Rotor Body Opposite Drive End Bearing
- 53. Coupling Fit Closest to Bearing Housing
 - 0 Degrees 90 Degrees 120 Degrees

●	54. Coupling Fit Closest to the end of the Shaft		
	0 Degrees	60 Degrees	120 Degrees
	2.3755	2.3754	2.3756
	55. Drive End Bearing Shaft Fit		
	0 Degrees	60 Degrees	120 Degrees
	2.7569	2.7569	2.7568
●	56. Drive End Bearing Shaft Fit Condition		(P) Pass
	57. Opposite Drive End Bearing Shaft Fit		
	0 Degrees	60 Degrees	120 Degrees
	2.7569	2.7568	2.7568
●	58. Opposite Drive End Bearing Shaft Fit Condition		(P) Pass
●	59. Shaft Air Seal Fits		
	Drive End Air Seal	Opposite Drive End Air Seal	
Mechanical Fits- Bearing Housings			
	60. Drive End - Endbell Bearing Fit		
	0 Degrees	60 Degrees	120 Degrees
	5.9056	5.9058	5.9058
●	61. Drive End - Endbell Bearing Fit Condition		(P) Pass
	62. Opposite Drive End - Endbell Bearing Fit		
	0 Degrees	60 Degrees	120 Degrees
	5.9052	5.9051	5.9052
●	63. Opposite Drive End - Endbell Bearing Fit Condition		(F) Fail
■	<i>Undersized</i>		

64. Bearing Cap Condition

Drive End Bearing Cap
pass



Opposite Drive End Bearing Cap
pass



65. End Bell Air Seal Fits

Drive End Air Seal

Opposite Drive End Air Seal

66. List Machine Work Needed Below

ODE housing fit undersized

67. Technician

Terrence Holland

Root Cause of Failure

68. Failure locations

Rewind stator & sleeve ode housing fit

69. Root cause of failure

Water leaked into stator windings from improperly sealed connection box. Motor showed signs of being single phased because of 2 groups of coils being overheated. see pictures.

Dynamic Balance Report

70. Rotor Weight and Balance Grade


Rotor Weight

Balance Grade

71. Initial Balance Readings

Drive End


Opposite Drive End



72. Final Balance Readings

Drive End

Opposite Drive End



73. Technician

Rewind

74. Core Test Results - Watts loss per Pound

Pre-Burnout

Post Burnout

75. Core Hot Spot Test

Pre-Burnout

Post-Burnout

76. Post Rewind Electrical Test- Insulation Resistance

Megohms

77. Post Rewind Polarization Index

Polarization Index

78. Post Rewind Winding Resistance


1-2


1-3

2-3

79. Post Rewind Surge Test

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

● 80.	Post Rewind Hi-Pot	micro-amps
● 81.	Technician	
Mechanical Fits- Bearing Housings - Post Repair		
● 82.	Drive End - Endbell Bearing Fit Post Repair	
	0 Degrees	60 Degrees 120 Degrees
● 83.	Opposite Drive End - Endbell Bearing Fit Post Repair	
	0 Degrees	60 Degrees 120 Degrees
● 84.	Bearing Cap Condition Post Repair	
	Drive End Bearing Cap	Opposite Drive End Bearing Cap
● 85.	End Bell Air Seal Fits Post Repair	
	Drive End Air Seal	Opposite Drive End Air Seal
● 86.	End Bell Repair Sign-off	
Assembly		
87.	QC Check All Parts for Cleanliness Prior to Assembly	Cw
		

● 88.	Photograph All Major Components prior to assembly	(Complete) Complete
<div>   </div>		





89. Final Insulation Resistance Test	Megohms		
90. Assembled Shaft Endplay	inches		
91. Assembled Shaft Runout	inches		
92. Test Run Voltage			
Volts	Volts	Volts	



93. Test Run Amperage			
Amps	Amps	Amps	

Witnessed by TRH



Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

94. Drive End Vibration Readings - Inches Per Second		
Horizontal	Vertical	Axial
0.03	0.03	0.05
95. Opposite Drive End Vibration Readings - Inches Per Second		
Horizontal	Vertical	Axial
0.03	0.02	0.05
96. Ambient Temperature - Fahrenheit		
97. Drive End Bearing Temps - Fahrenheit		
5 Minutes	10 Minutes	15 Minutes
98. Opposite Drive End Bearing Temps - Fahrenheit		
5 Minutes	10 Minutes	15 Minutes

99. Document Final Condition with Pictures after paint



100. Final Pics and QC Review

Crw

Co sign: TRH



Hi-Speed Industrial Service
7030 Ryburn Dr
Millington, Tn 38053
901-873-5300

AC Random Coil Rewind Report

FolderID: 103543
FormID: 22187444


Tolm Group Inc (12758)
210 N Moose St
Morrliton, AR 72110

Priorities Found: ● 3 - High ● 3 - Good

General		
1.	Job Number	103543
2.	Report Date	11/05/2024
3.	Customer	TOLM
Stator Winding		
4.	Core Length	12.25 "
	Conn End 5.25 O End 4.75	
5.	Core ID	11 "
6.	Back Iron Depth	2.875 "
7.	Slot Depth	1.125 "
8.	Tooth Width	0.357 "
9.	Number of Vents	0
10.	Vent Width	0 "
●	11. Before Burnout Core loss	(P) Pass
12.	Flux Before Burnout	
13.	Watts before burnout	
14.	Watts loss per lb. before burnout	1.5 W/lbs.
●	15. After Burnout Core Loss	(P) Pass
16.	Flux After burnout	
17.	Watts After Burnout	
18.	Watts loss per lb After Burnout	1.494 W/lbs.
19.	Core Iron Condition	
●	20. RTD's	(N) No
21.	RTD's Reading	
●	22. Motor Heaters	(N) No
23.	Heater Qty.	0
24.	Heater Voltage	
25.	Heater Wattage	
●	26. Thermistors	(N) No
27.	Number of Poles	2
28.	Slots	48
29.	Number of Coils	30
30.	Coil Weight	
31.	Lead Markings	1-12
32.	Grouping	

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

6 Groups 5	
33. Multiple Wires	
34. Wire Size	
35. Turns per coil	
■ 1-16-18-20-22-24 5 5 10 10 10 t/c	
36. Pitch 1 to:	
■ 1-16,18,20,22,24	
37. Connection	
1-2 wye/delta	
38. Lead Length	12 "
39. Lead Size	
40. Number of Leads	12
41. Megger Reading After Rewind	7647 Mohms
42. Coil Machine Slot	
43. Coil Machine Tip	
44. Coil Machine Pitch	
45. Hi Pot Reading After Rewind	0.095 Ua
● 46. Surge Pattern After Rewind	(P) Pass
47. Service Technician	
	
■ 130lbs #15 65lbs #16 45lbs #17 20lbs 30' #6 lead wire 600v epdm	



Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

Printed on 11/25/2024

Powered by [INSPECTALL](#)