

FolderID: 103978 FormID: 23037007



3333 Springhill Drive North Little Rock, AR 72116

Serial Number:

AC Inspection as Found Baptist Medical Center (10043)

AC Inspection - Rev. 2

LR MOTOR SHOP Location:

Z0108030063

Description: 100 HP BALDOR

Hi-Speed Job Number:	103978
Manufacturer:	Baldor
Product Number:	EM2555T-4
Serial Number:	Z0108030063
HP/kW:	100 (HP)
RPM:	1780 (RPM)
Frame:	404T
Voltage:	460
Current:	115 (Amps)
Phase:	Three
Hz:	60 (Hz)
Service Factor:	1.15
Enclosure:	ODP
# of Leads:	6
J-box Included:	None
Coupling/Sheave:	None
Date Received:	01/27/2025
Bearing RTDs:	No
Stator RTDs:	No
Repair Stage:	Final
Rewind:	Yes
Shaft Machined Fit Repairs Required:	No
Bearing Housing Machined Fit Repairs Required:	Yes
Heaters:	No
Winding Type :	Random Wound
Bearing Type:	Rolling Element

Priorities Found: 1 - High





9 - Good

Overall Condition

0

01/27/2025 Report Date



3. Photos of all six sides of the machine.








P45





Missing mount bolt





















4. Describe the Overall Condition of the Equipment as Received Serviceable

Ini	itial I	Mechanical/Electrical	Ō
	5.	Does Shaft Turn Freely?	(Y) Yes
	6.	Does the shaft require T.I.R in Lathe to identify additional repairs?	(No) No
	7.	Does Shaft Have Visible Damage?	(No) No
	8.	Assembled Shaft Runout	0.001 Inches
	9.	Assembled Shaft End Play	0 inches
	10.	Air Gap Variation <10%	good




	12.	Lead Length	16 Inches	
	13.	Does it have Lugs?, If so what is the Stud Size?	(No) No	
	14.	Lead Numbers	1-6	
	15.	Frame Condition	pass	
	16.	Fan Condition		
	17.	Broken or Missing Components	missing end bell mount bolt	
In	itial I	Electrical Inspection	Ō	1

Initial Electrical Inspection

Insulation Resistance/Megger Megohms P8



21.	Number of Stator Slots		4	8
20.	Perform Surge Test			
	1-2	1-3	2-3	
19.	Winding Resistance			



Shorted in slots



P84



Stator Thermistors/Ohms 23.

Stator Overloads/Ohms 24.

Mechanical Inspection

0

Drive End Bearing Brand

Nachi

P12



Drive End Bearing Number-

6316 NSL

P32



27. Drive End Bearing Qty.

(Ball) Ball Bearing

P51

Drive End Bearing Type








Frosting

29.	Drive End Lubrication Type	(Grease) Grease Lubricated	
30.	Drive End Bearing Insulation or Grounding Device?	none	
31.	Drive End Wavy Washer/Snap-Ring Other Retention Device?	bearing cap	P77



32. Drive End Bearing Condition

replace



34. Opposite Drive End Bearing Number-

6312-2Z/C3GJN

P99



35. Opposite Drive End Bearing Qty.

(Ball) Ball Bearing

P106





Frosting

37.	Opposite Drive End Lubrication Type	(Grease) Grease Lubricated	
38.	Opposite Drive End Bearing Insulation or Grounding Device?	none	
39.	Opposite Drive End Wavy Washer/Snap-Ring Other Retention Device?	wavy washer	
40.	Opposite Drive End Bearing Condition	replace	
41.	Drive End Seal	none	
42.	Opposite Drive End Seal	none	



P3

43. Rotor Type/Material (Squirrel Aluminum) Squirrel
Cage Aluminum Die Cast



44.	Growler Test	(Pass) Pass	
45.	Number of Rotor Bars	40	
46.	Rotor Condition	pass	
47.	List the Parts needed for the Repair Below		
	None		

48. Signature of Technician that Disassembled Motor

Terrence Holland

	4.	P
Machanical Fita Datas		

Mecha	nical Fits- Rotor			
49.	Shaft Runout		0.001 inche	S
50.	Rotor Runout			
	Drive End Bearing Fit	Rotor Body	Opposite Drive End Bearing	
51.	Coupling Fit Closest to Bearing H	lousing		
	0 Degrees	90 Degrees	120 Degrees	
52.	Coupling Fit Closest to the end of	f the Shaft		
	0 Degrees	60 Degrees	120 Degrees	
53.	Drive End Bearing Shaft Fit			
	0 Degrees	60 Degrees	120 Degrees	
	3.1497	3.1496	3.1496	
5 4.	Drive End Bearing Shaft Fit Cond	lition	(P) Pas	s
55.	Opposite Drive End Bearing Shat	t Fit		
	0 Degrees	60 Degrees	120 Degrees	
	2.3628	2.3629	2.3628	
5 6.	Opposite Drive End Bearing Shat	t Fit Condition	(P) Pas	s

57. Shaft Air Seal Fits Drive End Air Seal Opposite Drive End Air Seal
57. Shaft Air Seal Fits

Mechanical Fits- Bearing Housings

0

8. Drive End - Endbell Bearing Fit

0 Degrees

60 Degrees

120 Degrees

Bad. Excessive wear.



● 59. Drive End - Endbell Bearing Fit Condition (F) Fail

Excessive wear and pitting

60. Opposite Drive End - Endbell Bearing Fit

0 Degrees 60 Degrees 120 Degrees 5.1182 5.1181 5.1181

61. Opposite Drive End - Endbell Bearing Fit Condition (P) Pass

62. Bearing Cap Condition P52

Drive End Bearing Cap

Opposite Drive End Bearing Cap

fail

na

Cracked





63. End Bell Air Seal Fits

Drive End Air Seal Opposite Drive End Air Seal

64. List Machine Work Needed Below

P67





0

65. Technician Terrence Holland

Co sign RRW


Root Cause of Failure

66. Failure locations

Windings in slot.
D.E bearing cap cracked
Sleeve D.E housing fit
Both bearings show frosting. Aegis measurement 3.7364

67. Root cause of failure P18

Stator windings shorted between slots.



Dynamic Balance Report

68. Rotor Weight and Balance Grade

Rotor Weight Balance Grade

P11

Drive End

Opposite Drive End




70. Final Balance Readings

P27

Drive End

Opposite Drive End





71. Technician

Terrence Holland



72. Core Test Results - Watts loss per Pound

Pre-Burnout Post Burnout

73. Core Hot Spot Test

Pre-Burnout Post-Burnout

74. Post Rewind Electrical Test- Insulation Resistance Megohms

75. Post Rewind Polarization Index Polarization Index



77. Post Rewind Surge Test

78. Post Rewind Hi-Pot micro-amps

79. Technician

Mechanical Fits- Bearing Housings - Post Repair

0

P5

80. Drive End - Endbell Bearing Fit Post Repair0 Degrees 60 Degrees 120 Degrees

6.6934 6.6934 6.6934



81. Opposite Drive End - Endbell Bearing Fit Post Repair

0 Degrees 60 Degrees 120 Degrees

■ NA

82. Bearing Cap Condition Post Repair

P24

Drive End Bearing Cap Opposite Drive End Bearing Cap pass



83. End Bell Air Seal Fits Post Repair

Drive End Air Seal Opposite Drive End Air Seal

NA

RW



Assembly

0

85. QC Check All Parts for Cleanliness Prior to Assembly

Terrence Holland



86. Photograph All Major Components prior to assembly

P17









Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.









Final Insulation Resistance Test Megohms Pass Assembled Shaft Endplay 0 inches 88. Assembled Shaft Runout 0.001 inches 89. 90. Test Run Voltage P56 Volts Volts Volts 461 459 461



91.	Test Run Amperage			P65
	Amps	Amps	Amps	
	40.6	42.9	38.9	



92.	Drive End Vibration Readings - In	ches Per Second	
	Horizontal	Vertical	Axial
93.	Opposite Drive End Vibration Rea	adings - Inches Per Second	
	Horizontal	Vertical	Axial
94.	Ambient Temperature - Fahrenhe	it	
95.	Drive End Bearing Temps - Fahre	enheit	
	5 Minutes	10 Minutes	15 Minutes
96.	Opposite Drive End Bearing Tem	ps - Fahrenheit	
	5 Minutes	10 Minutes	15 Minutes

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.









98. Final Pics and QC Review

Terrence Holland

Co sign: RRW