



AC Inspection as Found

American Kraft Paper

1701 Jefferson Parkway

White Hall, AR 71602

FolderID: 104086

FormID: 23256287

AC Inspection - Rev. 2

Location: MOTOR SHOP LR

Serial Number: WCE9179032001

Description: 125HP TECO 1780RPM

Hi-Speed Job Number: 104086

Manufacturer: TECO Westinghouse

Product Number: TYPE: AEHH8P-10R

Spec/ID #: CAT: NP1254R

Serial Number: WCE9179032001

HP/kW: 125 (HP)

RPM: 1780 (RPM)

Frame: 444T

Voltage: 230 / 460

Current: 292 (Amps)

Phase: Three

Hz: 60 (Hz)

Service Factor: 1.15

Enclosure: TEFC

of Leads: 12

J-box Included: None

Coupling/Sheave: None

Date Received: 05/02/2025

Bearing RTDs: No

Stator RTDs: No

Repair Stage: Final

Rewind: Yes

Shaft Machined Fit Repairs
Required: No

Bearing Housing Machined
Fit Repairs Required: No

Heaters: No

Winding Type : Random Wound

Bearing Type: Rolling Element

Priorities Found: 2 - High

11 - Good

Overall Condition



1. Report Date

02/03/2025




3. Photos of all six sides of the machine.



Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.



4. Describe the Overall Condition of the Equipment as Received
Windings are shorted. Needs rewind and bearings.

Initial Mechanical/Electrical 	
● 5. Does Shaft Turn Freely?	(Y) Yes
● 6. Does the shaft require T.I.R in Lathe to identify additional repairs?	(No) No
7. Does Shaft Have Visible Damage?	(No) No
● 8. Assembled Shaft Runout	0.0015 Inches
9. Assembled Shaft End Play	0 inches
10. Air Gap Variation <10%	Na
● 11. Lead Condition	(P) Pass

12.	Lead Length	12 Inches	
13.	Does it have Lugs?, If so what is the Stud Size?	(Yes) Yes	
	3/8		
14.	Lead Numbers	not ledge able	
15.	Frame Condition	Good	
16.	Fan Condition	(P) Pass	P115




17.	Does motor have internal fan?	(No) No	
18.	Broken or Missing Components	broken screw shaft air fit seal. no j-box	P124



Initial Electrical Inspection



19.	Insulation Resistance/Megger	0 Megohms	P8
-----	------------------------------	-----------	----



Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

20.	Winding Resistance	1-2	1-3	2-3
	<div><div></div>Fail</div>			
21.	Perform Surge Test	(F) Fail		P57
<div><div><div><div>1500</div><div>Set Pass/Fail Tolerances</div><div>Surge Test Results: FAIL</div><div>Limit P-P EAR</div><div>Select the next test to perform</div><div><div>Temp / Res</div><div>Megohm</div><div>PI</div><div>Step-Voltage</div></div><div>Continue Next Phase</div><div>Or Stop Testing</div><div>STOP TESTING</div></div></div><div><div>2.5</div><div>5.0</div><div>7.5</div><div>10.0</div><div>12.5</div><div>15.0</div><div>17.5</div><div>µSECONDS</div></div></div> <div><div>2/4/2025 11:00:41 AM</div><div>400V w/R...</div><div>FAIL</div><div>2/4/2025 10:49:35 AM</div><div>480V w/R...</div><div>Test Date</div><div>2/4/2025</div><div>Test Time</div><div>11:00:41 AM</div><div>10:49:35 AM</div><div>DC Status</div><div>PASS</div><div>No Test</div><div>Test Type</div><div>Step-Voltage</div><div>Volts (V)</div><div>1404</div><div>I(µA)</div><div>0.0715</div><div>Resist</div><div>19649</div><div>At 40°C</div><div>5305</div><div>Surge Status</div><div>Limit P-P EAR</div><div>No Test</div><div>Peak Volt(V) L1</div><div>1500</div><div>Peak Volt(V) L2</div><div>690</div><div>Peak Volt(V) L3</div><div>0</div><div>Max P-P EAR(4.5/5.9)...</div><div>4.5/5.9/...</div><div>EAR 1-2/2-3/...</div><div>No Test</div><div>Nameplate</div><div>Application</div><div>Results Summary</div><div>Surge</div></div>				
22.	Number of Stator Slots			60
23.	Stator Condition			Rewind
24.	Stator Thermistors/Ohms			na
25.	Stator Overloads/Ohms			na
Mechanical Inspection				
26.	Drive End Bearing Brand			Koyo
27.	Drive End Bearing Number-			6318 zzxc3
28.	Drive End Bearing Qty.			1
29.	Drive End Bearing Type			(Ball) Ball Bearing
30.	Drive End Lubrication Type			(Grease) Grease Lubricated
31.	Drive End Bearing Insulation or Grounding Device?			no
32.	Drive End Wavy Washer/Snap-Ring Other Retention Device?			no
33.	Drive End Bearing Condition			worn
34.	Opposite Drive End Bearing Brand			SKF
35.	Opposite Drive End Bearing Number-			6316
36.	Opposite Drive End Bearing Qty.			1
37.	Opposite Drive End Bearing Type			(Ball) Ball Bearing
38.	Opposite Drive End Lubrication Type			(Grease) Grease Lubricated
39.	Opposite Drive End Bearing Insulation or Grounding Device?			no
40.	Opposite Drive End Wavy Washer/Snap-Ring Other Retention Device?			no
41.	Opposite Drive End Bearing Condition			worn
42.	Drive End Seal			no
43.	Opposite Drive End Seal			no
Rotor Inspection				
44.	Rotor Type/Material			(Squirrel Aluminum) Squirrel Cage Aluminum Die Cast
45.	Growler Test			(Pass) Pass
46.	Number of Rotor Bars			50
47.	Rotor Condition			Good

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

48. List the Parts needed for the Repair Below

6318zzc3
6316zzc3
Rewind

49. Signature of Technician that Disassembled Motor

Shon /Trevor



Mechanical Fits- Rotor

50. Shaft Runout **0.001 inches**

51. Rotor Runout

Drive End Bearing Fit

Rotor Body

Opposite Drive End Bearing

0.002

0.002

0.003

52. Coupling Fit Closest to Bearing Housing

0 Degrees

90 Degrees

120 Degrees

3.3735

3.3733

3.3735

53. Coupling Fit Closest to the end of the Shaft

0 Degrees

60 Degrees

120 Degrees

3.3746

3.3746

3.3746

54. Drive End Bearing Shaft Fit

0 Degrees

60 Degrees

120 Degrees

3.544

3.5439

3.5439

55. Drive End Bearing Shaft Fit Condition **(P) Pass**

56. Opposite Drive End Bearing Shaft Fit

0 Degrees

60 Degrees

120 Degrees

3.1498

3.1499

3.1499

57. Opposite Drive End Bearing Shaft Fit Condition **(P) Pass**

58. Shaft Air Seal Fits

Drive End Air Seal

Opposite Drive End Air Seal

good

good

Mechanical Fits- Bearing Housings

59. Drive End - Endbell Bearing Fit

0 Degrees

60 Degrees

120 Degrees

7.4812

7.4813

7.4813

60. Drive End - Endbell Bearing Fit Condition **(P) Pass**

61. Opposite Drive End - Endbell Bearing Fit

0 Degrees

60 Degrees

120 Degrees

6.6941

6.6941

6.6941

 **.0002 over max**

62. Opposite Drive End - Endbell Bearing Fit Condition **(P) Pass**

63. Bearing Cap Condition

Drive End Bearing Cap

Opposite Drive End Bearing Cap

good

good

64. End Bell Air Seal Fits

Drive End Air Seal

Opposite Drive End Air Seal

good

good

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

65. List Machine Work Needed Below

None

66. Technician

Shon/ Trevor Finished

SJ/TH



Co-sign TRH

Root Cause of Failure

67. Failure locations

Windings failed. They got hot and shorted.

68. Root cause of failure

Overloading of the windings

Dynamic Balance Report



69. Rotor Weight and Balance Grade

Rotor Weight

Balance Grade



See below

70. Initial Balance Readings

Drive End

Opposite Drive End

1.35

.40

71. Final Balance Readings

Drive End

Opposite Drive End

.07

.28

P27



72. Technician

Terrence Holland

TH



Rewind

73. Core Test Results - Watts loss per Pound

Pre-Burnout

Post Burnout

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

74.	Core Hot Spot Test		
	Pre-Burnout	Post-Burnout	
75.	Post Rewind Electrical Test- Insulation Resistance		Megohms
76.	Post Rewind Polarization Index		Polarization Index
77.	Post Rewind Winding Resistance		
	1-2	1-3	2-3
78.	Post Rewind Surge Test		
79.	Post Rewind Hi-Pot		micro-amps
80.	Technician		
Assembly 			
81.	QC Check All Parts for Cleanliness Prior to Assembly		Terrence Holland
			

82. Photograph All Major Components prior to assembly

P17









83. Final Insulation Resistance Test

4.59 Gigohms

P31



84. Assembled Shaft Endplay

0 inches

85. Assembled Shaft Runout

0.002 inches

86. Test Run Voltage

P55

Volts

Volts

Volts

455

454

458



87. Test Run Amperage

P65

Amps

Amps

Amps

43.5

39.5

40.1



88. Drive End Vibration Readings - Inches Per Second

Horizontal	Vertical	Axial
0.06	0.05	0.06

89. Opposite Drive End Vibration Readings - Inches Per Second

Horizontal	Vertical	Axial
0.02	0.01	0.03

90. Ambient Temperature - Fahrenheit

91. Drive End Bearing Temps - Fahrenheit

5 Minutes	10 Minutes	15 Minutes

92. Opposite Drive End Bearing Temps - Fahrenheit

5 Minutes	10 Minutes	15 Minutes

93. Document Final Condition with Pictures after paint

see below

94. Final Pics and QC Review

Terrence Holland

P132

Co sign: DM



