



AC Inspection as Found

FUTURE FUEL CHEMICAL

2800 GAP RD HWY 394 SO
BATESVILLE, AR 72501

FolderID: 104106
FormID: 23300438

AC Inspection - Rev. 2

Location: LR MOTOR SHOP

Serial Number: A1803222065

Description: 75 HP BALDOR

Hi-Speed Job Number: 104106

Manufacturer: Baldor

Product Number: A40-1168-0769

Serial Number: A1803222065

HP/kW: 75 (HP)

RPM: 1185 (RPM)

Frame: 405LPZ

Voltage: 460

Current: 86.9 (Amps)

Phase: Three

Hz: 60 (Hz)

Service Factor: 1.15

Enclosure: TEFC

of Leads: 6

J-box Included: Complete

Coupling/Sheave: Propeller

Bearing RTDs: No

Stator RTDs: No

Repair Stage: Final

Rewind: Yes

Shaft Machined Fit Repairs
Required: Yes

Bearing Housing Machined
Fit Repairs Required: Yes

Heaters: No

Winding Type : Random Wound

Bearing Type: Rolling Element

Priorities Found:  5 - High  15 - Good

Overall Condition



1. Report Date











4. Describe the Overall Condition of the Equipment as Received
Dirty

5. Distance from the end of the shaft to the Coupling/Sheave inches
Pin hole alignment

Initial Mechanical/Electrical



- | | | |
|---|--|-----------|
| ● | 6. Does Shaft Turn Freely? | (Y) Yes |
| ● | 7. Does the shaft require T.I.R in Lathe to identify additional repairs? | (No) No |
| | 8. Does Shaft Have Visible Damage? | (Yes) Yes |

P26



Bushing ride area

Propeller ride area

- | | | |
|---|---------------------------|---------------|
| ● | 9. Assembled Shaft Runout | 0.0003 Inches |
|---|---------------------------|---------------|


Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

10.	Assembled Shaft End Play	inches
11.	Air Gap Variation <10%	
12.	Lead Condition	(NA) Not Applicable
13.	Lead Length	12 Inches
14.	Does it have Lugs?, If so what is the Stud Size?	
	Yes	
15.	Lead Numbers	1-3
16.	Frame Condition	pass
17.	Fan Condition	(P) Pass
18.	Does motor have internal fan?	(No) No
19.	Broken or Missing Components	propeller pin is broke in half

Initial Electrical Inspection




20.	Insulation Resistance/Megger	Megohms	P8
-----	------------------------------	---------	----



21.	Winding Resistance		P20
-----	--------------------	--	-----

1-2	1-3	2-3
-----	-----	-----





23. Number of Stator Slots

24. Stator Condition

Needs rewind

25. Stator Thermistors/Ohms

26. Stator Overloads/Ohms

Mechanical Inspection

27. Drive End Bearing Brand

skf

28. Drive End Bearing Number-

3316

29. Drive End Bearing Qty.

1

30. Drive End Bearing Type

(Ball) Ball Bearing

31. Drive End Lubrication Type

(Grease) Grease Lubricated

32. Drive End Bearing Insulation or Grounding Device?

33. Drive End Wavy Washer/Snap-Ring Other Retention Device?

Spanner nut

34. Drive End Bearing Condition

P82

Contamination



35. Opposite Drive End Bearing Brand

skf

36. Opposite Drive End Bearing Number-

6313

37. Opposite Drive End Bearing Qty.

1

38. Opposite Drive End Bearing Type

(Ball) Ball Bearing


39. Opposite Drive End Lubrication Type

(Grease) Grease Lubricated

40. Opposite Drive End Bearing Insulation or Grounding Device?

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

●	41. Opposite Drive End Wavy Washer/Snap-Ring Other Retention Device?	wavy washer
	42. Opposite Drive End Bearing Condition	P117
■	<i>Contamination</i>	
<div style="display: flex; justify-content: space-around; align-items: center;">   </div>		
●	43. Drive End Seal	lip seal
■	<i>2.8125-3.3625-0.25</i>	
	44. Opposite Drive End Seal	
Rotor Inspection		
	45. Rotor Type/Material	(Squirrel Aluminum) Squirrel Cage Aluminum Die Cast
	46. Growler Test	(Pass) Pass
	47. Number of Rotor Bars	
●	48. Rotor Condition	
	49. List the Parts needed for the Repair Below <i>3316 6313 Lip seal Propeller pin</i>	
	50. Signature of Technician that Disassembled Motor	Cw
		
Mechanical Fits- Rotor		
	51. Shaft Runout	inches
	52. Rotor Runout	
	Drive End Bearing Fit	Opposite Drive End Bearing
	Rotor Body	
	53. Coupling Fit Closest to Bearing Housing	
	0 Degrees	120 Degrees
	90 Degrees	
	54. Coupling Fit Closest to the end of the Shaft	
	0 Degrees	120 Degrees
	60 Degrees	

55.	Drive End Bearing Shaft Fit		
	0 Degrees	60 Degrees	120 Degrees
	<div>3.1504-3.1505-3.1505</div>		
56.	Drive End Bearing Shaft Fit Condition (P) Pass		
57.	Opposite Drive End Bearing Shaft Fit		
	0 Degrees	60 Degrees	120 Degrees
	<div>2.5597-2.5597-2.5597</div>		
58.	Opposite Drive End Bearing Shaft Fit Condition (P) Pass		
59.	Shaft Air Seal Fits		
	Drive End Air Seal	Opposite Drive End Air Seal	
Mechanical Fits- Bearing Housings <div> <div></div> </div>			
60.	Drive End - Endbell Bearing Fit		
	0 Degrees	60 Degrees	120 Degrees
	<div>Excessive wear</div>		
			
61.	Drive End - Endbell Bearing Fit Condition (F) Fail		
62.	Opposite Drive End - Endbell Bearing Fit		
	0 Degrees	60 Degrees	120 Degrees
	<div>5.5129-5.5127-5.5128</div>		
63.	Opposite Drive End - Endbell Bearing Fit Condition (P) Pass		
64.	Bearing Cap Condition		
	Drive End Bearing Cap	Opposite Drive End Bearing Cap	
65.	End Bell Air Seal Fits		
	Drive End Air Seal	Opposite Drive End Air Seal	
66.	List Machine Work Needed Below		
	DE end bell bearing fit, bushing, bushing shaft fit, and propeller shaft fit, and bore propeller for new shaft fit		

Cherin TLH

Co sign:TLH

Root Cause of Failure


- 68. Failure locations
Windings, bearings, propeller shaft fit, bushing shaft fit, and seal
- 69. Root cause of failure
Wear, water contamination and bad connection on cord plugin.

Dynamic Balance Report

70. Rotor Weight and Balance Grade



P7

Rotor Weight Balance Grade



71. Initial Balance Readings

Drive End	Opposite Drive End
0.28	0.07

72.	Final Balance Readings		
	Drive End	Opposite Drive End	
	0.28	0.07	
73.	Technician		RW
			
Rewind			
74.	Core Test Results - Watts loss per Pound		
	Pre-Burnout	Post Burnout	
75.	Core Hot Spot Test		
	Pre-Burnout	Post-Burnout	
76.	Post Rewind Electrical Test- Insulation Resistance		Megohms
77.	Post Rewind Polarization Index		Polarization Index
78.	Post Rewind Winding Resistance		
	1-2	1-3	2-3
79.	Post Rewind Surge Test		
80.	Post Rewind Hi-Pot		micro-amps
81.	Technician		
Mechanical Fits- Rotor - Post Repair			
82.	Shaft Runout Post Repair		inches
83.	Rotor Runout Post Repair		
	Drive End Bearing Fit	Rotor Body	Opposite Drive End Bearing
84.	Coupling Fit Closest to Bearing Housing Post Repair		
	0 Degrees	90 Degrees	120 Degrees
85.	Coupling Fit Closest to the end of the Shaft Post Repair		
	0 Degrees	60 Degrees	120 Degrees
86.	Drive End Bearing Shaft Fit Post Repair		
	0 Degrees	60 Degrees	120 Degrees
87.	Opposite Drive End Bearing Shaft Fit Post Repair		
	0 Degrees	60 Degrees	120 Degrees
88.	Shaft Air Seal Fits Post Repair		
	Drive End Air Seal	Opposite Drive End Air Seal	
89.	Shaft Repair Sign-off		
Mechanical Fits- Bearing Housings - Post Repair			

90. Drive End - Endbell Bearing Fit Post Repair

P5

0 Degrees

60 Degrees

120 Degrees

6.6938

6.6939

6.6938



91. Opposite Drive End - Endbell Bearing Fit Post Repair

0 Degrees

60 Degrees

120 Degrees

92. Bearing Cap Condition Post Repair

Drive End Bearing Cap

Opposite Drive End Bearing Cap

93. End Bell Air Seal Fits Post Repair

P42

Drive End Air Seal

Opposite Drive End Air Seal

lip seal

▪ *Machined for a 3.5 x 2.75 x .375 lip seal.*



94. End Bell Repair Sign-off

Gary

Assembly



95. QC Check All Parts for Cleanliness Prior to Assembly

RW



96. Photograph All Major Components prior to assembly

(Complete) Complete

P17



Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.



97. Final Insulation Resistance Test

6,630 Megohms

P31



98. Assembled Shaft Endplay

0 inches

99. Assembled Shaft Runout

0.004 inches

100. Test Run Voltage

P55

Volts

Volts

Volts

459

458

459



101. Test Run Amperage

P65

Amps

Amps

Amps

28

27.8

27.3

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.



102. Drive End Vibration Readings - Inches Per Second

Horizontal	Vertical	Axial
0.01	0.04	0.01

103. Opposite Drive End Vibration Readings - Inches Per Second

Horizontal	Vertical	Axial
0.02	0.04	0.03

104. Ambient Temperature - Fahrenheit

105. Drive End Bearing Temps - Fahrenheit

5 Minutes	10 Minutes	15 Minutes
-----------	------------	------------

106. Opposite Drive End Bearing Temps - Fahrenheit

5 Minutes	10 Minutes	15 Minutes
-----------	------------	------------

107. Document Final Condition with Pictures after paint

see below

108. Final Pics and QC Review

Terrence Holland

P132

[Handwritten signature]

Co sign: RRW



