



## AC Inspection as Found

### FUTURE FUEL CHEMICAL

2800 GAP RD HWY 394 SO  
BATESVILLE, AR 72501

FolderID: 104368  
FormID: 23893611

#### AC Inspection - Rev. 2

Location: LR MOTOR SHOP

Serial Number: A2109292022

Description: 75 HP BALDOR

Hi-Speed Job Number: 104368

Manufacturer: Baldor

Serial Number: A2109292022

HP/kW: 75 (HP)

RPM: 1185 (RPM)

Voltage: 460

Current: 87.3 (Amps)

Phase: Three

Hz: 60 (Hz)

Enclosure: TEFC

# of Leads: 3

J-box Included: Complete

Coupling/Sheave: None

Bearing RTDs: No

Stator RTDs: No

Repair Stage: Final

Rewind: Yes

Shaft Machined Fit Repairs  
Required: Yes

Bearing Housing Machined  
Fit Repairs Required: Yes

Heaters: No

Winding Type: Random Wound

Bearing Type: Rolling Element

Priorities Found: ● 4 - High ● 7 - Good

#### Overall Condition



1. Report Date

03/28/2025







*Broken bolt*

*Part Broken off in housing.*







4. Describe the Overall Condition of the Equipment as Received  
*Dirty*

#### Initial Mechanical/Electrical



5. Does Shaft Turn Freely?	(N) No
6. Does the shaft require T.I.R in Lathe to identify additional repairs?	
7. Does Shaft Have Visible Damage?	(Yes) Yes
8. Assembled Shaft Runout	Inches
Unable to perform due to locked up shaft	
9. Assembled Shaft End Play	0 inches
10. Air Gap Variation <10%	

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.



12. Lead Length	15 Inches	
13. Does it have Lugs?, If so what is the Stud Size?	(Yes) Yes	
14. Lead Numbers	1-3	
15. Frame Condition	pass	
16. Fan Condition	(P) Pass	P115



17. Does motor have internal fan?	(No) No	
18. Broken or Missing Components	p	P124
<div>Broken of fan cover mount bolt on ODE.</div>		



See item 21



## 20. Winding Resistance

1-2

1-3

2-3

## 21. Perform Surge Test

(F) Fail

P57



## 22. Number of Stator Slots

90

## 23. Stator Condition

rewind

## 24. Stator Thermistors/Ohms

none

## 25. Stator Overloads/Ohms

none

## Mechanical Inspection



## 26. Drive End Bearing Brand

Unknown

## 27. Drive End Bearing Number-

7219

## 28. Drive End Bearing Qty.

1

## 29. Drive End Bearing Type

(Ball) Ball Bearing

## 30. Drive End Lubrication Type




(Grease) Grease Lubricated

## 31. Drive End Bearing Insulation or Grounding Device?

none

## 32. Drive End Wavy Washer/Snap-Ring Other Retention Device?

none

33. Drive End Bearing Condition	<b>destroyed</b>	P82
		
34. Opposite Drive End Bearing Brand	<b>SKF</b>	P92
		
35. Opposite Drive End Bearing Number-	<b>6313 C3</b>	P99
		
36. Opposite Drive End Bearing Qty.	<b>1</b>	
37. Opposite Drive End Bearing Type	<b>(Ball) Ball Bearing</b>	P106





- |  |                            |
|--|----------------------------|
| 38. Opposite Drive End Lubrication Type                              | (Grease) Grease Lubricated |
| 39. Opposite Drive End Bearing Insulation or Grounding Device?       | none                       |
| 40. Opposite Drive End Wavy Washer/Snap-Ring Other Retention Device? | none                       |
| 41. Opposite Drive End Bearing Condition                             | replace                    |
| <div> <div></div> <i>Normal wear.</i> </div>                         |                            |
| 42. Drive End Seal   |                            |
| 43. Opposite Drive End Seal  |                            |





#### Rotor Inspection

- |  |  |
|--|--|
| 44. Rotor Type/Material  | (Squirrel Aluminum) Squirrel<br>Cage Aluminum Die Cast |
| 45. Growler Test   | (Pass) Pass  |
| 46. Number of Rotor Bars   | 70   |
| 47. Rotor Condition  | pass   |
| 48. List the Parts needed for the Repair Below<br><i>New shaft. Rewind stator &amp; major core repair.<br/> Replace broken DE bearing<br/> Sleeve for 7219 housing fit.<br/> 6313 and 7219 bearings.</i> |  |
| 49. Signature of Technician that Disassembled Motor  | Terrence Holland                                       |

#### Mechanical Fits- Rotor

- |   |            |
|---|------------|
| 50. Shaft Runout                                | inches     |
| <div> <div></div> <i>Needs new shaft</i> </div> |            |
| 51. Rotor Runout                                |            |
| Drive End Bearing Fit                           | Rotor Body |
| Opposite Drive End Bearing                      |            |
| 52. Coupling Fit Closest to Bearing Housing     |            |
| 0 Degrees                                       | 90 Degrees |
| 120 Degrees                                     |            |

*See item 50*

53.	Coupling Fit Closest to the end of the Shaft			
	0 Degrees	60 Degrees	120 Degrees	
	 See item 50			
54.	Drive End Bearing Shaft Fit			
	0 Degrees	60 Degrees	120 Degrees	
55.	Drive End Bearing Shaft Fit Condition			(P) Pass
56.	Opposite Drive End Bearing Shaft Fit			
	0 Degrees	60 Degrees	120 Degrees	
	2.5592	2.5593	2.5593	
57.	Opposite Drive End Bearing Shaft Fit Condition			(P) Pass
58.	Shaft Air Seal Fits			
	Drive End Air Seal	Opposite Drive End Air Seal		
	 See item 50			
<b>Mechanical Fits- Bearing Housings</b>				
59.	Drive End - Endbell Bearing Fit			
	0 Degrees	60 Degrees	120 Degrees	
	 Fit bad because of both bearings suffering catastrophic failure!			
60.	Drive End - Endbell Bearing Fit Condition			(F) Fail
61.	Opposite Drive End - Endbell Bearing Fit			
	0 Degrees	60 Degrees	120 Degrees	
	5.5126	5.5126	5.5127	
62.	Opposite Drive End - Endbell Bearing Fit Condition			(P) Pass

63. Bearing Cap Condition

Drive End Bearing Cap  
destroyed

Opposite Drive End Bearing Cap  
pass



64. End Bell Air Seal Fits

Drive End Air Seal  
bad

Opposite Drive End Air Seal  
good

65. List Machine Work Needed Below

Replace shaft  
Machine DE housing bearing it and repair shaft air seal

66. Technician

Terrence Holland

A handwritten signature in black ink, reading "Terrence Holland".

Root Cause of Failure

67. Failure locations

Windings shorted. DE bearing cap destroyed. D.E housing fit bad.  
Core repair on stator required. Shaft repair required on DE from excessive wear.

68. Root cause of failure

DE bearing suffered catastrophic cage failure due to contaminated lubrication. This caused the rotor to drop onto the stator core and particles from the failed bearing, and broken bearing cap impacted the windings causing a short circuit.

Dynamic Balance Report

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

69.	Rotor Weight and Balance Grade		
	Rotor Weight	Balance Grade	
70.	Initial Balance Readings		
	Drive End	Opposite Drive End	
71.	Final Balance Readings		
	Drive End	Opposite Drive End	
72.	Technician		
<b>Rewind</b>			
73.	Core Test Results - Watts loss per Pound		
	Pre-Burnout	Post Burnout	
74.	Core Hot Spot Test		
	Pre-Burnout	Post-Burnout	
75.	Post Rewind Electrical Test- Insulation Resistance		
76.	Post Rewind Polarization Index		
77.	Post Rewind Winding Resistance		
	1-2	1-3	2-3
78.	Post Rewind Surge Test		
79.	Post Rewind Hi-Pot		
80.	Technician		
<b>Mechanical Fits- Rotor - Post Repair</b>			
81.	Shaft Runout Post Repair		
82.	Rotor Runout Post Repair		
	Drive End Bearing Fit	Rotor Body	Opposite Drive End Bearing
83.	Coupling Fit Closest to Bearing Housing Post Repair		
	0 Degrees	90 Degrees	120 Degrees
84.	Coupling Fit Closest to the end of the Shaft Post Repair		
	0 Degrees	60 Degrees	120 Degrees
85.	Drive End Bearing Shaft Fit Post Repair		
	0 Degrees	60 Degrees	120 Degrees
86.	Opposite Drive End Bearing Shaft Fit Post Repair		
	0 Degrees	60 Degrees	120 Degrees
87.	Shaft Air Seal Fits Post Repair		
	Drive End Air Seal	Opposite Drive End Air Seal	
88.	Shaft Repair Sign-off		
<b>Mechanical Fits- Bearing Housings - Post Repair</b>			

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.



89.	Drive End - Endbell Bearing Fit Post Repair		
	0 Degrees	60 Degrees	120 Degrees
90.	Opposite Drive End - Endbell Bearing Fit Post Repair		
	0 Degrees	60 Degrees	120 Degrees
91.	Bearing Cap Condition Post Repair		
	Drive End Bearing Cap	Opposite Drive End Bearing Cap	
92.	End Bell Air Seal Fits Post Repair		
	Drive End Air Seal	Opposite Drive End Air Seal	
93.	End Bell Repair Sign-off		
Assembly			
94.	QC Check All Parts for Cleanliness Prior to Assembly		
95.	Photograph All Major Components prior to assembly		
96.	Final Insulation Resistance Test		
97.	Assembled Shaft Endplay		
98.	Assembled Shaft Runout		
99.	Test Run Voltage		
	Volts	Volts	Volts
100.	Test Run Amperage		
	Amps	Amps	Amps
101.	Drive End Vibration Readings - Inches Per Second		
	Horizontal	Vertical	Axial
102.	Opposite Drive End Vibration Readings - Inches Per Second		
	Horizontal	Vertical	Axial
103.	Ambient Temperature - Fahrenheit		
104.	Drive End Bearing Temps - Fahrenheit		
	5 Minutes	10 Minutes	15 Minutes
105.	Opposite Drive End Bearing Temps - Fahrenheit		
	5 Minutes	10 Minutes	15 Minutes
106.	Document Final Condition with Pictures after paint		
107.	Final Pics and QC Review		