

0



AC Inspection as Found

Arkansas Lime Company 600 Limedale Rd

Batesville, AR 72501

FolderID: 104402 FormID: 23980593

AC Inspection - Rev. 2

Location:

LITTLE ROCK MOTOR SHOP

Serial Number:

Description:250 HP TOSHIBA

Hi-Speed Job Number:	104402
Manufacturer:	Toshiba
Product Number:	E2506FLF4BM
HP/kW:	250 (HP)
RPM:	1185 (RPM)
Frame:	N587UZ
Voltage:	460
Current:	296 (Amps)
Phase:	Three
Hz:	60 (Hz)
Service Factor:	1.15
Enclosure:	TEFC
# of Leads:	12
J-box Included:	None
Coupling/Sheave:	Sheave
Bearing RTDs:	No
Stator RTDs:	No
Repair Stage:	Final
Rewind:	No
Shaft Machined Fit Repairs Required:	No
Bearing Housing Machined Fit Repairs Required:	Yes
Heaters:	No
Winding Type :	Random Wound
Bearing Type:	Rolling Element
13 - Good	

Priorities Found: 8 - High





1 - Low



13 - Good

Overall Condition

Report Date



3. Photos of all six sides of the machine.







P45



Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

















 Describe the Overall Condition of the Equipment as Received Dirty

In	itial	Mechanical/Electrical	6
	5.	Does Shaft Turn Freely?	(Y) Yes
	6.	Does the shaft require T.I.R in Lathe to identify additional repairs?	(No) No
	7.	Does Shaft Have Visible Damage?	(Yes) Yes P26



8. Assembled Shaft Runout0.001 Inches









2.0405 in

10.	Assembled Shaft End Play	inches
11.	Air Gap Variation <10%	
12.	Lead Condition	(P) Pass
13.	Lead Length	12 Inches
14.	Does it have Lugs?, If so what is the Stud Size?	(No) No
15.	Lead Numbers	1-12
16.	Frame Condition	
17.	Fan Condition	(P) Pass
18.	Does motor have internal fan?	(Yes) Yes
19.	Broken or Missing Components	
-	J-box and bolts	


Initial Electrical Inspection


0

Megohms

P8

Insulation Resistance/Megger





Contamination



1250 100			
35.	Opposite Drive End Bearing Brand	коуо	
36.	Opposite Drive End Bearing Number-	6320	
37.	Opposite Drive End Bearing Qty.	1	
38.	Opposite Drive End Bearing Type	(Ball) Ball Bearing	
39.	Opposite Drive End Lubrication Type	(Grease) Grease Lubricated	
40.	Opposite Drive End Bearing Insulation or Grounding Device?		
41.	Opposite Drive End Wavy Washer/Snap-Ring Other Retention Device?	snap ring	
42.	Opposite Drive End Bearing Condition		P117
-	Normal wear		



- 43. Drive End Seal
- 44. Opposite Drive End Seal

Rotor Inspection

- 45. Rotor Type/Material (Squirrel Aluminum) Squirrel
 Cage Aluminum Die Cast
- 46. Growler Test (Pass) Pass
- 47. Number of Rotor Bars 60
- 48. Rotor Condition
 - 49. List the Parts needed for the Repair Below NU324 6320

50.	Signature of Technician that Disassembled Motor
	Morry

Cw

M	echa	nical Fits- Rotor			
	51.	Shaft Runout		inches	
	52.			mones	
	02.	Drive End Bearing Fit	Rotor Body	Opposite Drive End Bearing	
		Divo Lina Boaring Fix	ricion Body	opposite 2.110 2.110 g	
	53.	Coupling Fit Closest to Bearing F	lousing		
		0 Degrees	90 Degrees	120 Degrees	
	54.	Coupling Fit Closest to the end o	f the Shaft		
		0 Degrees	60 Degrees	120 Degrees	
	55.	Drive End Bearing Shaft Fit			
		0 Degrees	60 Degrees	120 Degrees	
_	—	4.7251-4.7253-4.7254			
	56. _	Drive End Bearing Shaft Fit Cond		(F) Fail	
		Recommend new shaft due to gou			
	57.	Opposite Drive End Bearing Sha		400 D	
		0 Degrees	60 Degrees	120 Degrees	
		3.9370-3.9372-3.9372			
	58.	Opposite Drive End Bearing Sha	ft Eit Condition	(F) Fail	
	59.	Shaft Air Seal Fits	it it Condition	(1)1 all	
	55.	Drive End Air Seal	Opposite Drive End Air Seal		
		Drive Life All Seal	Opposite Drive End Air Gear		
М	echa	nical Fits- Bearing Housings			
	60.	Drive End - Endbell Bearing Fit			
		0 Degrees	60 Degrees	120 Degrees	
		- 2 - 2 - 3 - 3 - 3 - 3 - 3 - 3 - 3 - 3	00 <u> </u>	0 _ 0 g. 0 0 0	
	-	Excessive pitting and gouge mark	s		
	61.	Drive End - Endbell Bearing Fit C	Condition	(F) Fail	
	62.	Opposite Drive End - Endbell Be			
		0 Degrees	60 Degrees	120 Degrees	
		-	-		
	-	Excessive pitting and gouge mark	s		
	63.	Excessive pitting and gouge mark Opposite Drive End - Endbell Be		(F) Fail	
	-			(F) Fail	

65. End Bell Air Seal Fits

Drive End Air Seal Opposite Drive End Air Seal

66. List Machine Work Needed Below

Both end bell bearing fits and recommend new shaft due to damage on DE shaft bearing fit

67. Technician

Cherin

Co sign: DM

Root Cause of Failure

68. Failure locations

Bearings and bearing fits

69. Root cause of failure

Excessive wear and contamination due to mixing of grease

Dynamic Balance Report

0

P7

70. Rotor Weight and Balance Grade

Rotor Weight

Balance Grade





Fan

		_	
71.	Initial	Ralanca	Readings

		0		
	Drive End		Opposite Drive End	
	6.20		6.75	
_	0.50			

2.50

72. Final Balance Readings

Drive End	Opposite Drive End
.27	.22

0.15



Mechanical Fits- Bearing Housings - Post Repair

0

74. Drive End - Endbell Bearing Fit Post Repair

P0

0 Degrees 60 Degrees 120 Degrees

10.237 10.237 10.237



75. Opposite Drive End - Endbell Bearing Fit Post Repair

P100

0 Degrees 60 Degrees 120 Degrees

8.4648 8.4648 8.4648



76. Bearing Cap Condition Post Repair

Drive End Bearing Cap Opposite Drive End Bearing Cap

77. End Bell Air Seal Fits Post Repair

Drive End Air Seal Opposite Drive End Air Seal

78. End Bell Repair Sign-off Gary P800

Machined and installed new shaft.





Assembly

79. QC Check All Parts for Cleanliness Prior to Assembly

RW

Photograph All Major Components prior to assembly

(Complete) Complete

P17



















81.	Final Insulation Resistance Test		5912 N	legohms
82.	Assembled Shaft Endplay			0 inches
83.	Assembled Shaft Runout		0.000	2 inches
84.	Test Run Voltage			P55
	Volts	Volts	Volts	
	458	454	461	



Amps	Amps	Amps	
90.7	84.7	86.0999999999999	



86. Drive End Vibration Readings - Inches Per Second

Horizontal Vertical Axial

	0.00	0.04	0.04		
	0.02	0.04	0.04		
87.	Opposite Drive End Vibration	Readings - Inches Per Second			
	Horizontal	Vertical	Axial		
	0.04	0.01	0.04		
88.	Ambient Temperature - Fahre	nheit			
89.	Drive End Bearing Temps - Fahrenheit				
	5 Minutes	10 Minutes	15 Minutes		
90.	Opposite Drive End Bearing T	emps - Fahrenheit			
	5 Minutes	10 Minutes	15 Minutes		
91.	Document Final Condition with	Pictures after paint	see pics below		
92.	Final Pics and QC Review		Terrence Holland	P132	











Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.