



AC Inspection as Found

Welspun Tubular (11685)

9301 Frazier Pike

Little Rock, AR 72206

FolderID: 104556

FormID: 24332439

AC Inspection - Rev. 2

Location: LR MOTOR SHOP

Serial Number: UD1206/1456097-001-1

Description: 18.6 KW NEMA

Hi-Speed Job Number:	104556
Manufacturer:	Siemens
Product Number:	1LE15231EB290JZ4
Serial Number:	UD1206/1456097-001-1
HP/kW:	18.6 (kW)
RPM:	1775 (RPM)
Frame:	60034
Voltage:	480
Current:	29.5 (Amps)
Phase:	Three
Hz:	60 (Hz)
Service Factor:	1.15
Enclosure:	TEFC
# of Leads:	6
J-box Included:	Complete
Coupling/Sheave:	None
Bearing RTDs:	No
Stator RTDs:	No
Repair Stage:	Final
Rewind:	Yes
Shaft Machined Fit Repairs Required:	No
Bearing Housing Machined Fit Repairs Required:	Yes
Heaters:	No
Winding Type :	Random Wound
Bearing Type:	Rolling Element

Priorities Found: 2 - High 13 - Good

Overall Condition



1. Report Date

05/14/2025















4.	Describe the Overall Condition of the Equipment as Received	
	<i>Serviceable</i>	
5.	Is this a UL Listed Motor	(No) No
6.	Is the motor water cooled or can be pressure checked before teardown	(No) No
Initial Mechanical/Electrical		<input type="checkbox"/>
7.	Does Shaft Turn Freely?	(Y) Yes
8.	Does the shaft require T.I.R in Lathe to identify additional repairs?	(No) No
9.	Does Shaft Have Visible Damage?	(No) No
10.	Assembled Shaft Runout	0.001 Inches
11.	Assembled Shaft End Play	inches
12.	Air Gap Variation <10%	

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

●	13. Lead Condition	(P) Pass	P69
			
●	14. Lead Length	8 Inches	
●	15. Does it have Lugs?, If so what is the Stud Size?	(Yes) Yes	
■	Connection block installed.		
●	16. Lead Numbers	1-6	P99
■	U1-V1-W1 U2-V2-W2		
			
●	17. Are the Leads insulated with Chico or other material	(No) No	
●	18. Frame Condition	pass	
●	19. Fan Condition	(P) Pass	P119
			
●	20. Does motor have internal fan?	(No) No	

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

21. Broken or Missing Components	DE snap ring		
Initial Electrical Inspection			
22. Insulation Resistance/Megger	Megohms		
23. Winding Resistance			P20
1-2	1-3	2-3	
 <i>Motor windings blown in slot.</i>			
			
24. Perform Surge Test	(NA) Not Applicable		P57
			
25. Number of Stator Slots	36		
26. Stator Condition	pass		
27. Stator Thermistors/Ohms			
28. Stator Overloads/Ohms	.3		
Mechanical Inspection			
29. Drive End Bearing Brand	ORS		
30. Drive End Bearing Number-	6210 C3		
31. Drive End Bearing Qty.	1		

32. Drive End Bearing Type

(Ball) Ball Bearing

P51



33. Drive End Lubrication Type

(Grease) Grease Lubricated

34. Drive End Bearing Insulation or Grounding Device?

none

35. Drive End Wavy Washer/Snap-Ring Other Retention Device?

wavy washer

P77

 Wavy washer broken

36. Drive End Bearing Condition

worn

37. Opposite Drive End Bearing Brand

ORS

38. Opposite Drive End Bearing Number-

6210 C3

39. Opposite Drive End Bearing Qty.

1

40. Opposite Drive End Bearing Type

(Ball) Ball Bearing




P110





41. Opposite Drive End Lubrication Type

(Grease) Grease Lubricated

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

42.	Opposite Drive End Bearing Insulation or Grounding Device?	none
43.	Opposite Drive End Wavy Washer/Snap-Ring Other Retention Device?	two snap rings
44.	Opposite Drive End Bearing Condition	worn
45.	Drive End Seal	dust seal
46.	Opposite Drive End Seal	dust seal
Rotor Inspection		
47.	Rotor Type/Material	(Squirrel Aluminum) Squirrel Cage Aluminum Die Cast P3
		
48.	Growler Test	(Pass) Pass
49.	Number of Rotor Bars	28
50.	Rotor Condition	pass
51.	List the Parts needed for the Repair Below 2) 6210 C3 bearings	
52.	Signature of Technician that Disassembled Motor	Terrence Holland
		
Mechanical Fits- Rotor		
53.	Shaft Runout	0.001 inches
54.	Rotor Runout	
	Drive End Bearing Fit	Rotor Body Opposite Drive End Bearing
55.	Coupling Fit Closest to Bearing Housing	
	0 Degrees	90 Degrees 120 Degrees
56.	Coupling Fit Closest to the end of the Shaft	
	0 Degrees	60 Degrees 120 Degrees
57.	Drive End Bearing Shaft Fit	
	0 Degrees	60 Degrees 120 Degrees
	1.9691	1.969 1.969
58.	Drive End Bearing Shaft Fit Condition	(P) Pass

59.	Opposite Drive End Bearing Shaft Fit		
	0 Degrees	60 Degrees	120 Degrees
	1.969	1.969	1.969
60.	Opposite Drive End Bearing Shaft Fit Condition (P) Pass		
61.	Shaft Air Seal Fits		
	Drive End Air Seal	Opposite Drive End Air Seal	
Mechanical Fits- Bearing Housings			
62.	Drive End - Endbell Bearing Fit		
	0 Degrees	60 Degrees	120 Degrees
			
63.	Drive End - Endbell Bearing Fit Condition (F) Fail		
	Lip worn in.		
			
64.	Opposite Drive End - Endbell Bearing Fit		
	0 Degrees	60 Degrees	120 Degrees
	3.5448	3.5446	3.5447
	Max allowed is 3.5442		
65.	Opposite Drive End - Endbell Bearing Fit Condition (F) Fail		
	See above		
66.	Bearing Cap Condition		
	Drive End Bearing Cap	Opposite Drive End Bearing Cap	

67. End Bell Air Seal Fits

Drive End Air Seal

Opposite Drive End Air Seal

68. List Machine Work Needed Below

Sleeve both end bell housing fits.

69. Technician

Terrence Holland

[Handwritten signature]

Co sign:

Root Cause of Failure



70. Failure locations

P9

Both housing fits bad. Rewind stator. Windings blown in slot



71. Root cause of failure

D.E. Housing fit has lip worn in allowing the rotor to impact the stator iron causing a electrical grounding to the iron. Contaminated grease I both bearings was a contributing factor to premature bearing failure.

Dynamic Balance Report

72. Rotor Weight and Balance Grade

Rotor Weight

Balance Grade

73. Initial Balance Readings

Drive End

Opposite Drive End

74. Final Balance Readings

Drive End

Opposite Drive End

75. Technician

Rewind

76. Core Test Results - Watts loss per Pound

Pre-Burnout

Post Burnout

77.	Core Hot Spot Test		
	Pre-Burnout	Post-Burnout	
78.	Post Rewind Electrical Test- Insulation Resistance		
79.	Post Rewind Polarization Index		
80.	Post Rewind Winding Resistance		
	1-2	1-3	2-3
81.	Post Rewind Surge Test		
82.	Post Rewind Hi-Pot		
83.	Technician		
Mechanical Fits- Bearing Housings - Post Repair			
84.	Drive End - Endbell Bearing Fit Post Repair		
	0 Degrees	60 Degrees	120 Degrees
85.	Opposite Drive End - Endbell Bearing Fit Post Repair		
	0 Degrees	60 Degrees	120 Degrees
86.	Bearing Cap Condition Post Repair		
	Drive End Bearing Cap	Opposite Drive End Bearing Cap	
87.	End Bell Air Seal Fits Post Repair		
	Drive End Air Seal	Opposite Drive End Air Seal	
88.	End Bell Repair Sign-off		
Assembly			
89.	QC Check All Parts for Cleanliness Prior to Assembly		
90.	Photograph All Major Components prior to assembly		
91.	Final Insulation Resistance Test		
92.	Assembled Shaft Endplay		
93.	Assembled Shaft Runout		
94.	Test Run Voltage		
	Volts	Volts	Volts
95.	Test Run Amperage		
	Amps	Amps	Amps
96.	Drive End Vibration Readings - Inches Per Second		
	Horizontal	Vertical	Axial
97.	Opposite Drive End Vibration Readings - Inches Per Second		
	Horizontal	Vertical	Axial
98.	Ambient Temperature - Fahrenheit		
99.	Drive End Bearing Temps - Fahrenheit		
	5 Minutes	10 Minutes	15 Minutes

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

100. Opposite Drive End Bearing Temps - Fahrenheit			
5 Minutes	10 Minutes	15 Minutes	
101. Document Final Condition with Pictures after paint			
102. Final Pics and QC Review			