



AC Inspection as Found
Green Bay Packaging, Pinecrest (11362)
3610 Hwy 64 East
Plummerville, AR 72127

FolderID: 104598
FormID: 24418677

AC Inspection - Rev. 2

Location: LITTLE ROCK MOTOR SHOP

Serial Number:

Description: MOTOR -NO NAMEPLATE DATA

Hi-Speed Job Number: 104598

Manufacturer: Baldor

Serial Number: A1212172065

HP/kW: 150 (HP)

RPM: 3570 (RPM)

Frame: 445TS

Voltage: 460

Current: 164 (Amps)

Phase: Three

Hz: 60 (Hz)

Service Factor: 1.15

Enclosure: TEFC

of Leads: 6

J-box Included: Complete

Coupling/Sheave: None

Bearing RTDs: No

Stator RTDs: No

Repair Stage: Final

Shaft Machined Fit Repairs
Required: No

Bearing Housing Machined
Fit Repairs Required: No

Heaters: No

Winding Type : Random Wound

Bearing Type: Rolling Element

Priorities Found: ● 17 - Good

Overall Condition



1. Report Date

05/21/2025

2. Nameplate Picture

P37



Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.







4.	Describe the Overall Condition of the Equipment as Received	
	<i>Serviceable</i>	
5.	Is this a UL Listed Motor	(No) No
6.	Is the motor water cooled or can be pressure checked before teardown	(No) No
Initial Mechanical/Electrical		
7.	Does Shaft Turn Freely?	(Y) Yes
8.	Does the shaft require T.I.R in Lathe to identify additional repairs?	(No) No
9.	Does Shaft Have Visible Damage?	(No) No
10.	Assembled Shaft Runout	0.003 Inches
11.	Assembled Shaft End Play	0 inches
12.	Air Gap Variation <10%	

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

13.	Lead Condition	(P) Pass	
14.	Lead Length	26 Inches	
15.	Does it have Lugs?, If so what is the Stud Size?	(Yes) Yes	P95



16.	Lead Numbers	1-3	
17.	Are the Leads insulated with Chico or other material	(No) No	
18.	Frame Condition	acceptable	
19.	Fan Condition	(P) Pass	
20.	Does motor have internal fan?	(No) No	
21.	Broken or Missing Components	None	

Initial Electrical Inspection



22.	Insulation Resistance/Megger	496 Megohms	P8
-----	------------------------------	-------------	----




1-2	1-3	2-3
1-2 0.029410	1-3 0.9380	2-3 0.29350



24. Perform Surge Test

(P) Pass

P57



25.	Number of Stator Slots	48
26.	Stator Condition	pass
27.	Stator Thermistors/Ohms	
28.	Stator Overloads/Ohms	

Mechanical Inspection



29.	Drive End Bearing Brand	SKF
30.	Drive End Bearing Number-	6313zz
31.	Drive End Bearing Qty.	1
32.	Drive End Bearing Type	(Ball) Ball Bearing
33.	Drive End Lubrication Type	(Grease) Grease Lubricated
34.	Drive End Bearing Insulation or Grounding Device?	
35.	Drive End Wavy Washer/Snap-Ring Other Retention Device?	

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.



37. Opposite Drive End Bearing Brand	SKF
38. Opposite Drive End Bearing Number-	6313zz
39. Opposite Drive End Bearing Qty.	1
40. Opposite Drive End Bearing Type	(Ball) Ball Bearing
41. Opposite Drive End Lubrication Type	(Grease) Grease Lubricated
42. Opposite Drive End Bearing Insulation or Grounding Device?	
43. Opposite Drive End Wavy Washer/Snap-Ring Other Retention Device?	
<input checked="" type="checkbox"/> <i>Wavy washer</i>	
44. Opposite Drive End Bearing Condition	

P120



45. Drive End Seal
46. Opposite Drive End Seal

Rotor Inspection

47. Rotor Type/Material	(Squirrel Aluminum) Squirrel Cage Aluminum Die Cast
48. Growler Test	(Pass) Pass
49. Number of Rotor Bars	39
50. Rotor Condition	acceptable
51. List the Parts needed for the Repair Below <i>6313zz 6313zz</i>	
52. Signature of Technician that Disassembled Motor	Donny Spears

Mechanical Fits- Rotor

53. Shaft Runout	0 inches
------------------	-----------------

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

54.	Rotor Runout		
	Drive End Bearing Fit	Rotor Body	Opposite Drive End Bearing
55.	Coupling Fit Closest to Bearing Housing		
	0 Degrees	90 Degrees	120 Degrees
56.	Coupling Fit Closest to the end of the Shaft		
	0 Degrees	60 Degrees	120 Degrees
57.	Drive End Bearing Shaft Fit		
	0 Degrees	60 Degrees	120 Degrees
	2.5592		
58.	Drive End Bearing Shaft Fit Condition		(P) Pass
59.	Opposite Drive End Bearing Shaft Fit		
	0 Degrees	60 Degrees	120 Degrees
	2.5592		
60.	Opposite Drive End Bearing Shaft Fit Condition		(P) Pass
61.	Shaft Air Seal Fits		
	Drive End Air Seal	Opposite Drive End Air Seal	
Mechanical Fits- Bearing Housings			
62.	Drive End - Endbell Bearing Fit		
	0 Degrees	60 Degrees	120 Degrees
	5.5122		
63.	Drive End - Endbell Bearing Fit Condition		(P) Pass
64.	Opposite Drive End - Endbell Bearing Fit		
	0 Degrees	60 Degrees	120 Degrees
	5.5121		
65.	Opposite Drive End - Endbell Bearing Fit Condition		(P) Pass
66.	Bearing Cap Condition		
	Drive End Bearing Cap	Opposite Drive End Bearing Cap	
	Acceptable		
67.	End Bell Air Seal Fits		
	Drive End Air Seal	Opposite Drive End Air Seal	
68.	List Machine Work Needed Below		
	None		
69.	Technician		Donny Spears
	Donny Spears		
Root Cause of Failure			
70.	Failure locations		
	No failure		

71. Root cause of failure

Recondition

Dynamic Balance Report




72. Rotor Weight and Balance Grade

P7

Rotor Weight

Balance Grade



73. Initial Balance Readings

Drive End

Opposite Drive End

See above

74. Final Balance Readings

Drive End

Opposite Drive End

See item 72

75. Technician

Rewind

76. Core Test Results - Watts loss per Pound

Pre-Burnout

Post Burnout

77. Core Hot Spot Test

Pre-Burnout

Post-Burnout

78. Post Rewind Electrical Test- Insulation Resistance

Megohms

79. Post Rewind Polarization Index

Polarization Index

80. Post Rewind Winding Resistance

1-2

1-3

2-3

81. Post Rewind Surge Test

82. Post Rewind Hi-Pot

micro-amps

83. Technician

Assembly







86. Final Insulation Resistance Test

Megohms

P31



87. Assembled Shaft Endplay **0 inches**

88. Assembled Shaft Runout **0.002 inches**

89. Test Run Voltage P55

Volts	Volts	Volts
457	457	480



90. Test Run Amperage P65

Amps	Amps	Amps
38.6	35.7	37.4



91. Drive End Vibration Readings - Inches Per Second

Horizontal	Vertical	Axial
0.02	0.01	0.02

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

92. Opposite Drive End Vibration Readings - Inches Per Second

Horizontal	Vertical	Axial
0.02	0.008999999999999999	0.03

93. Ambient Temperature - Fahrenheit

94. Drive End Bearing Temps - Fahrenheit

5 Minutes	10 Minutes	15 Minutes
-----------	------------	------------

95. Opposite Drive End Bearing Temps - Fahrenheit

5 Minutes	10 Minutes	15 Minutes
-----------	------------	------------

96. Document Final Condition with Pictures after paint


See below

97. Final Pics and QC Review

Terrence Holland

P135

RRW



Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

Printed on 6/6/2025

Powered by INSPECTALL

Page 13 of 13