



AC Inspection as Found

Riceland Foods (11100-RLF)

Hwy 79 & N. Park Ave.

Stuttgart, AR 72160

FolderID: 104790

FormID: 24885368

AC Inspection - Rev. 2

Location: MOTOR SHOP LR

Serial Number: CAT# X100E3B

Description: 100 HP EMERSON

Hi-Speed Job Number: 104790

Manufacturer: Emerson

Product Number: AC19

Spec/ID #: K06-AC19-M

Serial Number: CAT# X100E3B

HP/kW: 100 (HP)

RPM: 1185 (RPM)

Frame: 444T

Voltage: 460

Current: 128 (Amps)

Phase: Three

Hz: 60 (Hz)

Service Factor: 1.00

Enclosure: TE

of Leads: 6

J-box Included: Complete

Coupling/Sheave: None

Bearing RTDs: No

Stator RTDs: No

Repair Stage: Final

Rewind: Yes

Shaft Machined Fit Repairs
Required: Yes

Bearing Housing Machined
Fit Repairs Required: Yes

Heaters: No

Winding Type : Random Wound

Bearing Type: Rolling Element

Priorities Found: ● 4 - High

● 8 - Good

Overall Condition



1. Report Date

07/07/2025

2. Nameplate Picture

P37



3. Photos of all six sides of the machine.

P44









4. Describe the Overall Condition of the Equipment as Received
Serviceable

5.	Is this a UL Listed Motor	(YES) YES	P83
----	---------------------------	-----------	-----



6.	Is the motor water cooled or can be pressure checked before teardown	(NO) NO
----	--	---------

Initial Mechanical/Electrical



7. Does Shaft Turn Freely? (N) No

8. Does the shaft require T.I.R in Lathe to identify additional repairs? (YES) YES

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

9. Does Shaft Have Visible Damage?

(Yes) Yes

P26



10. Assembled Shaft Runout

Inches

Unable to perform due to locked shaft.

11. Assembled Shaft End Play

0 inches

12. Air Gap Variation <10%

13. Lead Condition

P70



14. Lead Length

9.5 Inches

15. Does it have Lugs?, If so what is the Stud Size?

(YES) YES

16. Lead Numbers

1-6

Delta connection

17. Are the Leads insulated with Chico or other material

(YES) YES

18. Frame Condition

pass

19. Fan Condition

(P) Pass

P120



- | | | |
|-----------------------------------|-----------------------|------|
| 20. Does motor have internal fan? | (NO) NO | |
| 21. Broken or Missing Components | DE bearing cap broken | P128 |



Initial Electrical Inspection



- | | | |
|----------------------------------|---------|-----|
| 22. Insulation Resistance/Megger | Megohms | |
| 23. Winding Resistance | | |
| 1-2 | 1-3 | 2-3 |

- | | | |
|--------------------------|---------------------|-----|
| ● 24. Perform Surge Test | (NA) Not Applicable | P59 |
|--------------------------|---------------------|-----|



- | | |
|-----------------------------|--------|
| 25. Number of Stator Slots | 72 |
| 26. Stator Condition | rewind |
| 27. Stator Thermistors/Ohms | |



Mechanical Inspection



29. Drive End Bearing Brand	unreadable	
30. Drive End Bearing Number-	6220-J/C3	
31. Drive End Bearing Qty.	1	P34



32. Drive End Bearing Type	(Ball) Ball Bearing	
33. Drive End Lubrication Type	(Grease) Grease Lubricated	
34. Drive End Bearing Insulation or Grounding Device?	none	
35. Drive End Wavy Washer/Snap-Ring Other Retention Device?	snap ring	
36. Drive End Bearing Condition	excessive wear	P82



37. Opposite Drive End Bearing Brand	unreadable	
--------------------------------------	------------	--

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

38. Opposite Drive End Bearing Number-	6313-J/C3	
39. Opposite Drive End Bearing Qty.	1	P106

40. Opposite Drive End Bearing Type	(Ball) Ball Bearing
41. Opposite Drive End Lubrication Type	(Grease) Grease Lubricated
42. Opposite Drive End Bearing Insulation or Grounding Device?	none
43. Opposite Drive End Wavy Washer/Snap-Ring Other Retention Device?	
44. Opposite Drive End Bearing Condition	worn
45. Drive End Seal	
46. Opposite Drive End Seal	

Rotor Inspection

47. Rotor Type/Material	(Squirrel Aluminum) Squirrel Cage Aluminum Die Cast	P3
-------------------------	--	----

48. Growler Test	(Pass) Pass
49. Number of Rotor Bars	57
50. Rotor Condition	pass
51. List the Parts needed for the Repair Below	

*Possible new shaft and new DE bearing cap.
Machine shaft opening on DE housing
Both end bell housing fits bad.*

52. Signature of Technician that Disassembled Motor

Terrence Holland


Mechanical Fits- Rotor53. Shaft Runout **0.003 inches**

54. Rotor Runout

Drive End Bearing Fit

Rotor Body

Opposite Drive End Bearing

55. Coupling Fit Closest to Bearing Housing

0 Degrees

90 Degrees

120 Degrees

56. Coupling Fit Closest to the end of the Shaft

0 Degrees

60 Degrees

120 Degrees

57. Drive End Bearing Shaft Fit

P79

0 Degrees

60 Degrees

120 Degrees


● 58. Drive End Bearing Shaft Fit Condition **(F) Fail**

59. Opposite Drive End Bearing Shaft Fit

0 Degrees

60 Degrees

120 Degrees

2.5595**2.5595****2.5596**
● 60. Opposite Drive End Bearing Shaft Fit Condition **(P) Pass**

61. Shaft Air Seal Fits

Drive End Air Seal

Opposite Drive End Air Seal

Mechanical Fits- Bearing Housings

62. Drive End - Endbell Bearing Fit

0 Degrees

60 Degrees

120 Degrees

*Excessive wear*
● 63. Drive End - Endbell Bearing Fit Condition **(F) Fail**

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

64.	Opposite Drive End - Endbell Bearing Fit		
	0 Degrees	60 Degrees	120 Degrees
	<div> <div></div> <div>Excessive wear.</div> </div>		
65.	Opposite Drive End - Endbell Bearing Fit Condition		(F) Fail
66.	Bearing Cap Condition		
	Drive End Bearing Cap	Opposite Drive End Bearing Cap	
	destroyed	good	
67.	End Bell Air Seal Fits		
	Drive End Air Seal	Opposite Drive End Air Seal	
	excessive wear		
68.	List Machine Work Needed Below		
	<i>New bearing cap</i> <i>Repair both housing fits</i> <i>Repair shaft opening air seal fit</i> <i>Machine new snap ring groove.</i>		
69.	Technician		Terrence Holland
			
	<div> <div></div> <div>Co sign: RRW</div> </div>		
Root Cause of Failure			
70.	Failure locations		
	<i>Windings shorted on coil head.</i> <i>Both housing fits bad</i> <i>D.E cap broken.</i>		
71.	Root cause of failure		
	<i>Bearing cap fragments impacted the windings causing a short circuit.</i>		
Dynamic Balance Report			
72.	Rotor Weight and Balance Grade		
	Rotor Weight	Balance Grade	
73.	Initial Balance Readings		
	Drive End	Opposite Drive End	
74.	Final Balance Readings		
	Drive End	Opposite Drive End	
75.	Technician		
Rewind			
76.	Core Test Results - Watts loss per Pound		
	Pre-Burnout	Post Burnout	
77.	Core Hot Spot Test		
	Pre-Burnout	Post-Burnout	
78.	Post Rewind Electrical Test- Insulation Resistance		

79.	Post Rewind Polarization Index		
80.	Post Rewind Winding Resistance		
	1-2	1-3	2-3
81.	Post Rewind Surge Test		
82.	THERMAL DETECTION EQUIPMENT FINAL TESTING - RTD'S/KLIXONS/THERMISTORS		
83.	Post Rewind Hi-Pot		
84.	Technician		
Mechanical Fits- Rotor - Post Repair			
85.	Shaft Runout Post Repair		
86.	Rotor Runout Post Repair		
	Drive End Bearing Fit	Rotor Body	Opposite Drive End Bearing
87.	Coupling Fit Closest to Bearing Housing Post Repair		
	0 Degrees	90 Degrees	120 Degrees
88.	Coupling Fit Closest to the end of the Shaft Post Repair		
	0 Degrees	60 Degrees	120 Degrees
89.	Drive End Bearing Shaft Fit Post Repair		
	0 Degrees	60 Degrees	120 Degrees
90.	Opposite Drive End Bearing Shaft Fit Post Repair		
	0 Degrees	60 Degrees	120 Degrees
91.	Shaft Air Seal Fits Post Repair		
	Drive End Air Seal	Opposite Drive End Air Seal	
92.	Shaft Repair Sign-off		
Mechanical Fits- Bearing Housings - Post Repair			
93.	Drive End - Endbell Bearing Fit Post Repair		
	0 Degrees	60 Degrees	120 Degrees
94.	Opposite Drive End - Endbell Bearing Fit Post Repair		
	0 Degrees	60 Degrees	120 Degrees
95.	Bearing Cap Condition Post Repair		
	Drive End Bearing Cap	Opposite Drive End Bearing Cap	
96.	End Bell Air Seal Fits Post Repair		
	Drive End Air Seal	Opposite Drive End Air Seal	
97.	End Bell Repair Sign-off		
Assembly			
98.	QC Check All Parts for Cleanliness Prior to Assembly		
99.	Photograph All Major Components prior to assembly		
100.	Was a Insulated bearing or end bell tested?		

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

101.	Final Insulation Resistance Test		
102.	Assembled Shaft Endplay		
103.	Assembled Shaft Runout		
104.	Test Run Voltage		
	Volts	Volts	Volts
105.	Test Run Amperage		
	Amps	Amps	Amps
106.	Motor RPM		
107.	Drive End Vibration Readings - Inches Per Second		
	Horizontal	Vertical	Axial
108.	Opposite Drive End Vibration Readings - Inches Per Second		
	Horizontal	Vertical	Axial
109.	Ambient Temperature - Fahrenheit		
110.	Drive End Bearing Temps - Fahrenheit		
	5 Minutes	10 Minutes	15 Minutes
111.	Opposite Drive End Bearing Temps - Fahrenheit		
	5 Minutes	10 Minutes	15 Minutes
112.	Document Final Condition with Pictures after paint		
113.	Final Pics and QC Review		