



AC Inspection as Found

Sage V Foods

5901 SLOAN DRIVE
LITTLE ROCK, AR 72206

FolderID: 104819
FormID: 24981621

AC Inspection - Rev. 2

Location: MOTOR SHOP LR

Serial Number: 1475951-134

Description: .90 KW BECKER

Hi-Speed Job Number:	104819
Manufacturer:	Other
Product Number:	IEC60034
Spec/ID #:	41784407275114 IL
Serial Number:	1475951-134
HP/kW:	.90 (kW)
RPM:	1745 (RPM)
Voltage:	230 / 460
Current:	3.6/1.8 (Amps)
Phase:	Three
Hz:	60 (Hz)
Enclosure:	TE
# of Leads:	9
J-box Included:	Complete
Coupling/Sheave:	None
Date Received:	07/14/2025
Bearing RTDs:	No
Stator RTDs:	No
Repair Stage:	Final
Rewind:	No
Shaft Machined Fit Repairs Required:	No
Bearing Housing Machined Fit Repairs Required:	No
Heaters:	No
Winding Type :	Random Wound
Bearing Type:	Rolling Element

Priorities Found: ● 1 - High ● 11 - Good

Overall Condition



1. Report Date

07/14/2025











4.	Describe the Overall Condition of the Equipment as Received	
	<i>Acceptable</i>	
5.	Is this a UL Listed Motor	(NO) NO
6.	Is the motor water cooled or can be pressure checked before teardown	(NO) NO
Initial Mechanical/Electrical		
7.	Does Shaft Turn Freely?	(N) No
8.	Does the shaft require T.I.R in Lathe to identify additional repairs?	(NO) NO
9.	Does Shaft Have Visible Damage?	(No) No
10.	Assembled Shaft Runout	0 Inches
11.	Assembled Shaft End Play	inches
	<i>None</i>	

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

12.	Air Gap Variation <10%		
13.	Lead Condition		(P) Pass
14.	Lead Length		Inches
	6"		
15.	Does it have Lugs?, If so what is the Stud Size?		(YES) YES
16.	Lead Numbers		1-9
17.	Are the Leads insulated with Chico or other material		(NO) NO
18.	Frame Condition		Dirty
19.	Fan Condition		(P) Pass
20.	Does motor have internal fan?		(NO) NO
21.	Broken or Missing Components		
	None		
Initial Electrical Inspection			
22.	Insulation Resistance/Megger		34945 Megohms
23.	Winding Resistance		
	1-2	1-3	2-3
	1-2 10.877	1-3 10.845	2-3 10.876
24.	Perform Surge Test		(P) Pass
			P57
			
25.	Number of Stator Slots		36
26.	Stator Condition		
27.	Stator Thermistors/Ohms		
28.	Stator Overloads/Ohms		
	.1		
Mechanical Inspection			
29.	Drive End Bearing Brand		NTN
30.	Drive End Bearing Number-		6207LUA
31.	Drive End Bearing Qty.		1
32.	Drive End Bearing Type		(Ball) Ball Bearing
33.	Drive End Lubrication Type		(Grease) Grease Lubricated
34.	Drive End Bearing Insulation or Grounding Device?		
35.	Drive End Wavy Washer/Snap-Ring Other Retention Device?		



- | | |
|--|----------------------------|
| 37. Opposite Drive End Bearing Brand | SKF |
| 38. Opposite Drive End Bearing Number- | 6205zz |
| 39. Opposite Drive End Bearing Qty. | 1 |
| 40. Opposite Drive End Bearing Type | (Ball) Ball Bearing |
| 41. Opposite Drive End Lubrication Type | (Grease) Grease Lubricated |
| 42. Opposite Drive End Bearing Insulation or Grounding Device? | |
| 43. Opposite Drive End Wavy Washer/Snap-Ring Other Retention Device? | P115 |

Flat washers




44. Opposite Drive End Bearing Condition



P120



45. Drive End Seal

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

46.	Opposite Drive End Seal		
Rotor Inspection			
47.	Rotor Type/Material	(Squirrel Aluminum) Squirrel Cage Aluminum Die Cast	
48.	Growler Test	(Pass) Pass	
49.	Number of Rotor Bars	28	
50.	Rotor Condition	acceptable	
51.	List the Parts needed for the Repair Below <i>6207 2RS</i> <i>6205 2RS</i> <i>Filter 90950500</i> <i>Pump Vanes 7971570 BG 21 BECKER WN 124-162</i> <i>Wash and bake</i>		
52.	Signature of Technician that Disassembled Motor	Donny Spears	
			
Mechanical Fits- Rotor			
53.	Shaft Runout	0 inches	
54.	Rotor Runout		
	Drive End Bearing Fit	Rotor Body	Opposite Drive End Bearing
	.00		
55.	Coupling Fit Closest to Bearing Housing		
	0 Degrees	90 Degrees	120 Degrees
56.	Coupling Fit Closest to the end of the Shaft		
	0 Degrees	60 Degrees	120 Degrees
57.	Drive End Bearing Shaft Fit		
	0 Degrees	60 Degrees	120 Degrees
	1.3786		
58.	Drive End Bearing Shaft Fit Condition	(P) Pass	
59.	Opposite Drive End Bearing Shaft Fit		
	0 Degrees	60 Degrees	120 Degrees
	0.9844		
60.	Opposite Drive End Bearing Shaft Fit Condition	(P) Pass	
61.	Shaft Air Seal Fits		
	Drive End Air Seal	Opposite Drive End Air Seal	
Mechanical Fits- Bearing Housings			
62.	Drive End - Endbell Bearing Fit		
	0 Degrees	60 Degrees	120 Degrees
	2.8355		

63.	Drive End - Endbell Bearing Fit Condition	(P) Pass
64.	Opposite Drive End - Endbell Bearing Fit	
	0 Degrees 60 Degrees 120 Degrees	
	2.0479	
65.	Opposite Drive End - Endbell Bearing Fit Condition	(P) Pass
66.	Bearing Cap Condition	
	Drive End Bearing Cap Opposite Drive End Bearing Cap	
67.	End Bell Air Seal Fits	
	Drive End Air Seal Opposite Drive End Air Seal	
68.	List Machine Work Needed Below	
	None	
69.	Technician	Donny Spears
		
Root Cause of Failure		
70.	Failure locations	
	Pump end	
71.	Root cause of failure	
	Rust in pump end	
Dynamic Balance Report		
72.	Rotor Weight and Balance Grade	
	Rotor Weight Balance Grade	
73.	Initial Balance Readings	
	Drive End Opposite Drive End	
74.	Final Balance Readings	
	Drive End Opposite Drive End	
75.	Technician	
Rewind		
76.	THERMAL DETECTION EQUIPMENT FINAL TESTING - RTD'S/KLIXONS/THERMISTORS	
Assembly		
77.	QC Check All Parts for Cleanliness Prior to Assembly	Terrence Holland
		



79. Was a Insulated bearing or end bell tested?

(NA) Not Applicable

80. Final Insulation Resistance Test

Megohms

P37



81. Assembled Shaft Endplay	0 inches	
82. Assembled Shaft Runout	0.001 inches	
83. Test Run Voltage		

P69

Volts	Volts	Volts
460	458	462

Witness: TLH



84. Test Run Amperage		
-----------------------	--	--

P77

Amps	Amps	Amps
1.3	1.2	1.3



Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

85.	Motor RPM	1790		
86.	Drive End Vibration Readings - Inches Per Second			
	Horizontal	Vertical	Axial	
87.	Opposite Drive End Vibration Readings - Inches Per Second			
	Horizontal	Vertical	Axial	
88.	Ambient Temperature - Fahrenheit			
89.	Drive End Bearing Temps - Fahrenheit			
	5 Minutes	10 Minutes	15 Minutes	
90.	Opposite Drive End Bearing Temps - Fahrenheit			
	5 Minutes	10 Minutes	15 Minutes	

91. Document Final Condition with Pictures after paint

P139





92. Final Pics and QC Review

Terrence Holland

[Handwritten signature]



See item above