



AC Inspection as Found
Arkansas Electric Coop. (11681)
17400 highway 365 south
Little Rock, AR 72206

FolderID: 104824
FormID: 24987363

AC Inspection - Rev. 2

Location: MOTOR SHOP LR

Serial Number: 038736

Description: 4.3 HP AMATEK

Hi-Speed Job Number: 104824

Manufacturer: Other

Product Number: DR858AY72X

Serial Number: 038736

HP/kW: 7.5 (HP)

RPM: 3450 (RPM)

Frame: 215TCZ

Voltage: 208-230/460

Current: 24.5/22.2/11.1

Phase: Three

Hz: 60 (Hz)

Service Factor: 1.15

Enclosure: TEFC

of Leads: 9

J-box Included: Complete

Coupling/Sheave: None

Date Received: 06/26/2025

Bearing RTDs: No

Stator RTDs: No

Repair Stage: Final

Rewind: Yes

Shaft Machined Fit Repairs
Required: No

Bearing Housing Machined
Fit Repairs Required: Yes

Heaters: No

Winding Type : Random Wound

Bearing Type: Rolling Element

Priorities Found: ● 5 - High ● 9 - Good

Overall Condition



1. Report Date

07/09/2025









4.	Describe the Overall Condition of the Equipment as Received	
	<i>Acceptable</i>	
5.	Is this a UL Listed Motor	(NO) NO
6.	Is the motor water cooled or can be pressure checked before teardown	(NO) NO
Initial Mechanical/Electrical		<input checked="" type="checkbox"/>
7.	Does Shaft Turn Freely?	(Y) Yes
8.	Does the shaft require T.I.R in Lathe to identify additional repairs?	(NO) NO
9.	Does Shaft Have Visible Damage?	(No) No
10.	Assembled Shaft Runout	0 Inches


Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

11.	Assembled Shaft End Play	inches	
	None		
12.	Air Gap Variation <10%		
13.	Lead Condition	(P) Pass	
14.	Lead Length	Inches	
	10"		
15.	Does it have Lugs?, If so what is the Stud Size?	(NO) NO	
16.	Lead Numbers	1-9	
17.	Are the Leads insulated with Chico or other material	(NO) NO	
18.	Frame Condition	acceptable	
19.	Fan Condition	(P) Pass	
20.	Does motor have internal fan?	(NO) NO	
21.	Broken or Missing Components		P130
	Shaft sleeve		
Initial Electrical Inspection			
22.	Insulation Resistance/Megger	0.01233 Megohms	
23.	Winding Resistance		
	1-2	1-3	2-3
	1-2 1.497300	1-3 1.557900	2-3 1.487600
24.	Perform Surge Test	(F) Fail	P57
25.	Number of Stator Slots	36	
26.	Stator Condition	shorted	
27.	Stator Thermistors/Ohms		





Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

28.	Stator Overloads/Ohms		
Mechanical Inspection			
29.	Drive End Bearing Brand	NACHI	
30.	Drive End Bearing Number-	6309ZE	
31.	Drive End Bearing Qty.	1	
32.	Drive End Bearing Type	(Ball) Ball Bearing	
33.	Drive End Lubrication Type	(Grease) Grease Lubricated	
34.	Drive End Bearing Insulation or Grounding Device?		
35.	Drive End Wavy Washer/Snap-Ring Other Retention Device?		
36.	Drive End Bearing Condition	good	P82
			
37.	Opposite Drive End Bearing Brand	SKF	
38.	Opposite Drive End Bearing Number-	6206-2RS	
39.	Opposite Drive End Bearing Qty.	1	
40.	Opposite Drive End Bearing Type	(Ball) Ball Bearing	
41.	Opposite Drive End Lubrication Type	(Grease) Grease Lubricated	
42.	Opposite Drive End Bearing Insulation or Grounding Device?		
43.	Opposite Drive End Wavy Washer/Snap-Ring Other Retention Device?	washers	
44.	Opposite Drive End Bearing Condition	good	P120
			
45.	Drive End Seal		
46.	Opposite Drive End Seal		
Rotor Inspection			
47.	Rotor Type/Material	(Squirrel Aluminum) Squirrel Cage Aluminum Die Cast	




Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

48.	Growler Test	(Pass) Pass	
49.	Number of Rotor Bars	29	
50.	Rotor Condition		
51.	List the Parts needed for the Repair Below 6309zz 6206zz Shaft sleeve Rewind		
52.	Signature of Technician that Disassembled Motor	Donny Spears	
			
Mechanical Fits- Rotor			
53.	Shaft Runout	0 inches	
54.	Rotor Runout		
	Drive End Bearing Fit	Rotor Body	Opposite Drive End Bearing
	0	0	0
55.	Coupling Fit Closest to Bearing Housing		
	0 Degrees	90 Degrees	120 Degrees
56.	Coupling Fit Closest to the end of the Shaft		
	0 Degrees	60 Degrees	120 Degrees
57.	Drive End Bearing Shaft Fit		
	0 Degrees	60 Degrees	120 Degrees
	1.7720		
58.	Drive End Bearing Shaft Fit Condition	(P) Pass	
59.	Opposite Drive End Bearing Shaft Fit		
	0 Degrees	60 Degrees	120 Degrees
	1.1813		
60.	Opposite Drive End Bearing Shaft Fit Condition	(P) Pass	
61.	Shaft Air Seal Fits		
	Drive End Air Seal	Opposite Drive End Air Seal	
Mechanical Fits- Bearing Housings			
62.	Drive End - Endbell Bearing Fit		
	0 Degrees	60 Degrees	120 Degrees
	3.9383		
63.	Drive End - Endbell Bearing Fit Condition	(F) Fail	
64.	Opposite Drive End - Endbell Bearing Fit		
	0 Degrees	60 Degrees	120 Degrees
	2.4420		
65.	Opposite Drive End - Endbell Bearing Fit Condition	(F) Fail	

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

66. Bearing Cap Condition	Drive End Bearing Cap	Opposite Drive End Bearing Cap
67. End Bell Air Seal Fits	Drive End Air Seal	Opposite Drive End Air Seal
68. List Machine Work Needed Below SE-Endbell OE Endbell Shaft sleeve Rewind		
69. Technician	Donny Spears	
		
		
Root Cause of Failure		
70. Failure locations	Winding Shorted	
71. Root cause of failure	Phase to phase short	
Dynamic Balance Report		
72. Rotor Weight and Balance Grade		
Rotor Weight	Balance Grade	
73. Initial Balance Readings		
Drive End	Opposite Drive End	
		
74. Final Balance Readings	P28	
Drive End	Opposite Drive End	
.34	.13	
		
75. Technician		
Rewind		

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

76.	Core Test Results - Watts loss per Pound		
	Pre-Burnout	Post Burnout	
77.	Core Hot Spot Test		
	Pre-Burnout	Post-Burnout	
78.	Post Rewind Electrical Test- Insulation Resistance		
79.	Post Rewind Polarization Index		
80.	Post Rewind Winding Resistance		
	1-2	1-3	2-3
81.	Post Rewind Surge Test		
82.	THERMAL DETECTION EQUIPMENT FINAL TESTING - RTD'S/KLIXONS/THERMISTORS		
83.	Post Rewind Hi-Pot		
84.	Technician		
Mechanical Fits- Bearing Housings - Post Repair			
85.	Drive End - Endbell Bearing Fit Post Repair		
	0 Degrees	60 Degrees	120 Degrees
	3.9376	3.9376	3.9376
			
86.	Opposite Drive End - Endbell Bearing Fit Post Repair		
	0 Degrees	60 Degrees	120 Degrees
	2.4412	2.4412	2.4412
			

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

87. Bearing Cap Condition Post Repair

Drive End Bearing Cap

Opposite Drive End Bearing Cap

88. End Bell Air Seal Fits Post Repair

Drive End Air Seal

Opposite Drive End Air Seal

P43



89. End Bell Repair Sign-off

RW

A handwritten signature in black ink, consisting of the letters 'RW'.

Assembly



90. QC Check All Parts for Cleanliness Prior to Assembly

Terrence Holland

A handwritten signature in black ink, appearing to be 'L' followed by a stylized signature.

91. Photograph All Major Components prior to assembly

P20







92. Was a Insulated bearing or end bell tested?

(NA) Not Applicable

93. Final Insulation Resistance Test

Megohms

P37



94. Assembled Shaft Endplay

0 inches

95. Assembled Shaft Runout

0.001 inches

96. Test Run Voltage

P69

Volts

Volts

Volts



97. Test Run Amperage

Amps

Amps

Amps

3

2.8

3

98. Motor RPM

3594

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

99. Drive End Vibration Readings - Inches Per Second

Horizontal	Vertical	Axial
0.04	0.05	0.02

100. Opposite Drive End Vibration Readings - Inches Per Second

Horizontal	Vertical	Axial
0.04	0.02	0.02

101. Ambient Temperature - Fahrenheit

102. Drive End Bearing Temps - Fahrenheit

5 Minutes	10 Minutes	15 Minutes
-----------	------------	------------

103. Opposite Drive End Bearing Temps - Fahrenheit

5 Minutes	10 Minutes	15 Minutes
-----------	------------	------------

104. Document Final Condition with Pictures after paint

P139



105. Final Pics and QC Review

Terrence Holland

[Handwritten signature]

Co sign: TLH