



Hi-Speed Industrial Service
7030 Ryburn Dr
Millington, Tn 38053
901-873-5300

AC Inspection as Found

REMURIAE

2044 EAST COUNTY RD 876
OSCEOLA, AR 72730

FolderID: 156022
FormID: 25210882



AC Inspection - Rev. 2

Location: MLMR
Serial Number: LSFT322U039
Description: 500 HP AC

Hi-Speed Job Number:	156022
Manufacturer:	GE
Product Number:	Q8124
Spec/ID #:	5KS511XAA161C
Serial Number:	LSFT322U039
HP/kW:	500 (HP)
RPM:	3570 (RPM)
Frame:	5011LS
Voltage:	460
Current:	517 (Amps)
Phase:	Three
Hz:	60 (Hz)
Service Factor:	1.15
Enclosure:	TEFC
# of Leads:	6
J-box Included:	None
Coupling/Sheave:	None
Date Received:	07/16/2025
Bearing RTDs:	Yes
Stator RTDs:	Yes
Repair Stage:	Teardown Inspection
Heaters:	Yes
Winding Type :	Random Wound
Bearing Type:	Rolling Element

Priorities Found: ● 4 - High ● 7 - Good

Overall Condition



1. Report Date

07/22/2025

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.


2. Nameplate Picture


P2



3. Photos of all six sides of the machine.

P3





4. Describe the Overall Condition of the Equipment as Received

Passed all electrical tests. Shaft is bent and requires repair. Stator passed all electrical tests. Shaft is bent and requires repair as well as machine work to both end bells. Drive end bearing shows electrical fluting.? Recommend adding aegis ring to drive end and insulated bearing on opposite drive end.

- | | |
|---|---------|
| 5. Is this a UL Listed Motor | (NO) NO |
| 6. Is the motor water cooled or can be pressure checked before teardown | (NO) NO |

Initial Mechanical/Electrical



- | | |
|--|-------------------------------|
| 7. Does Shaft Turn Freely? | (Y) Yes |
| 8. Does the shaft require T.I.R in Lathe to identify additional repairs? | (YES) YES |
| 9. Does Shaft Have Visible Damage? | (No) No |
| 10. Assembled Shaft Runout | 0.008 Inches |
| 11. Assembled Shaft End Play | 0.001 inches |
| 12. Air Gap Variation <10% | No Provisions for measurement |



14. Lead Length

24 Inches

15. Does it have Lugs?, If so what is the Stud Size?

P15



16. Lead Numbers

1-3/7-9

17. Are the Leads insulated with Chico or other material

(NO) NO

18. Stator Temperature Detector Rating and Function

Quantity

Rating

Quantity Passed

8

100

8

19. Bearing Temperature Detector Rating and Function

Quantity

Rating

Quantity Passed

2

100

2

20. Frame Condition

Pass

21. Fan Condition

(P) Pass

22. Does motor have internal fan?

(YES) YES

23. Heater Quantity, Ratings

Quantity

Volts/Watts

Pass/Fail

1

Pass

24. Broken or Missing Components

None

Initial Electrical Inspection





26. Winding Resistance

1-2


1-3

2-3

.005844


.005822

.005854



27. Perform Surge Test

(P) Pass



28. Number of Stator Slots

48

29. Stator Condition

Pass

30. Stator Thermistors/Ohms

M/A

31. Stator Overloads/Ohms

N/A

Mechanical Inspection










33. Drive End Bearing Number-	6315 zC3
34. Drive End Bearing Qty.	1
35. Drive End Bearing Type	(Ball) Ball Bearing
36. Drive End Lubrication Type	(Grease) Grease Lubricated
37. Drive End Bearing Insulation or Grounding Device?	None
38. Drive End Wavy Washer/Snap-Ring Other Retention Device?	None
39. Drive End Bearing Condition	fluted





41. Opposite Drive End Bearing Number-	6315 zC3
42. Opposite Drive End Bearing Qty.	1

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

43.	Opposite Drive End Bearing Type	(Ball) Ball Bearing	
44.	Opposite Drive End Lubrication Type	(Grease) Grease Lubricated	
45.	Opposite Drive End Bearing Insulation or Grounding Device?	None	
46.	Opposite Drive End Wavy Washer/Snap-Ring Other Retention Device?	Wavy Washer	
47.	Opposite Drive End Bearing Condition	Fluting	P47
			
48.	Drive End Seal	Labyrinth	
49.	Opposite Drive End Seal	Labyrinth	
Rotor Inspection			
50.	Rotor Type/Material	(Squirrel Aluminum) Squirrel Cage Aluminum Die Cast	
51.	Growler Test	(Pass) Pass	
52.	Number of Rotor Bars	40	
53.	Rotor Condition	Pass	
54.	List the Parts needed for the Repair Below		P54
<i>Aegis ring see picture for part #</i> 6315 C3 6315 C3 insulated			
			
55.	Signature of Technician that Disassembled Motor	Brandon Woodard	
			
Mechanical Fits- Rotor			

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

56.	Shaft Runout	0.008 inches		
57.	Rotor Runout			
	Drive End Bearing Fit	Rotor Body	Opposite Drive End Bearing	
	0.001	0.001	0.001	
58.	Coupling Fit Closest to Bearing Housing	P58		
	0 Degrees	90 Degrees	120 Degrees	
	2.625	2.625	2.625	
				
59.	Coupling Fit Closest to the end of the Shaft			
	0 Degrees	60 Degrees	120 Degrees	
	2.625	2.625	2.625	
60.	Drive End Bearing Shaft Fit	P60		
	0 Degrees	60 Degrees	120 Degrees	
	2.9529	2.9529	2.9529	
	Tolerance is 2.9529-2.9534			
				
61.	Drive End Bearing Shaft Fit Condition	(P) Pass		
62.	Opposite Drive End Bearing Shaft Fit			
	0 Degrees	60 Degrees	120 Degrees	
	2.9528	2.9528	2.9528	
	Tolerance is 2.9529-2.9534			
63.	Opposite Drive End Bearing Shaft Fit Condition	(P) Pass		

Drive End Air Seal
Needs Repaired

Opposite Drive End Air Seal
Pass



Mechanical Fits- Bearing Housings



65. Drive End - Endbell Bearing Fit

P65

0 Degrees

60 Degrees

120 Degrees

6.3021

6.3021

6.3021



Tolerance is 6.2992-6.3002



66. Drive End - Endbell Bearing Fit Condition

(F) Fail

67. Opposite Drive End - Endbell Bearing Fit

0 Degrees

60 Degrees

120 Degrees

6.3018

6.3018

6.3018



Tolerance is 6.2992-6.3002



69. Bearing Cap Condition

Drive End Bearing Cap

Opposite Drive End Bearing Cap

Pass**Pass**

70. End Bell Air Seal Fits

Drive End Air Seal

Opposite Drive End Air Seal

needs repaired**Pass**

71. List Machine Work Needed Below

*Bore and install bushings in both end bells.**Clean up shaft at seal fit.**Shaft is bend from seal fit to end of shaft .008". Shaft material needs to be tested to see if it can be weld repaired. Is so, shaft needs turned, welded, turned and new keyway milled.*

72. Technician

Brandon Woodard
Root Cause of Failure

73. Failure locations

74. Root cause of failure

Rewind75. THERMAL DETECTION EQUIPMENT FINAL TESTING -
RTD'S/KLIXONS/THERMISTORS**Assembly**

76. Was a Insulated bearing or end bell tested?

77. Motor RPM