



Hi-Speed Industrial Service
7030 Ryburn Dr
Millington, Tn 38053
901-873-5300

AC Inspection as Found
MOTOR - KTG USA
400 Mahannah
Memphis, TN 38107

FolderID: 154704
FormID: 23298402



AC Inspection - Rev. 2

Location: MLMR
Serial Number: Q2 G14T0326NPI
Description: 100HP AC

Hi-Speed Job Number:	154704
Manufacturer:	Siemens
Serial Number:	Q2 G14T0326NPI
HP/kW:	100 (HP)
RPM:	3570 (RPM)
Frame:	405TS
Voltage:	460
Current:	108 (Amps)
Phase:	Three
Hz:	60 (Hz)
Service Factor:	1.15
Enclosure:	TEFC
# of Leads:	3
J-box Included:	None
Coupling/Sheave:	None
Date Received:	01/29/2025
Bearing RTDs:	No
Stator RTDs:	No
Repair Stage:	Teardown Inspection
Rewind:	No
Shaft Machined Fit Repairs Required:	No
Bearing Housing Machined Fit Repairs Required:	Yes
Heaters:	No
Winding Type :	Random Wound
Bearing Type:	Rolling Element

Priorities Found: ● **4 - High** ● **8 - Good**

Overall Condition



1. Report Date

02/05/2025

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

2. Nameplate Picture


P2



3. Photos of all six sides of the machine.

P3





4. Describe the Overall Condition of the Equipment as Received
Passed all electrical tests. Requires bore and bushing installed in both end bells.

Initial Mechanical/Electrical

5. Does Shaft Turn Freely?	(Y) Yes
6. Does the shaft require T.I.R in Lathe to identify additional repairs?	(No) No
7. Does Shaft Have Visible Damage?	(No) No
8. Assembled Shaft Runout	0.003 Inches
9. Assembled Shaft End Play	0.001 inches
10. Air Gap Variation <10%	No Provisions for measurement
11. Lead Condition	(P) Pass
12. Lead Length	18 Inches
13. Does it have Lugs?, If so what is the Stud Size?	(Yes) Yes
5/16 2A eggs	
14. Lead Numbers	1-3
15. Frame Condition	Pass
16. Fan Condition	(P) Pass
17. Does motor have internal fan?	(No) No
18. Broken or Missing Components	None





Initial Electrical Inspection



19. Insulation Resistance/Megger 92000 Megohms

P19



20. Winding Resistance			P20
1-2	1-3	2-3	
.05948	.05956	.05946	
			
21. Perform Surge Test	(P) Pass	P21	
			
22. Number of Stator Slots	36		
23. Stator Condition		P23	
			
24. Stator Thermistors/Ohms	N/A		
25. Stator Overloads/Ohms	N/A		
Mechanical Inspection			

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.



27. Drive End Bearing Number-	6316 C3
28. Drive End Bearing Qty.	1
29. Drive End Bearing Type	(Ball) Ball Bearing
30. Drive End Lubrication Type	(Grease) Grease Lubricated
31. Drive End Bearing Insulation or Grounding Device?	None
32. Drive End Wavy Washer/Snap-Ring Other Retention Device?	None
33. Drive End Bearing Condition	Destroyed from old grease and heat
34. Opposite Drive End Bearing Brand	ORS





35. Opposite Drive End Bearing Number-	6316 C3
36. Opposite Drive End Bearing Qty.	1
37. Opposite Drive End Bearing Type	(Ball) Ball Bearing
38. Opposite Drive End Lubrication Type	(Grease) Grease Lubricated
39. Opposite Drive End Bearing Insulation or Grounding Device?	None
40. Opposite Drive End Wavy Washer/Snap-Ring Other Retention Device?	Wavy Washer
41. Opposite Drive End Bearing Condition	Destroyed from old grease and heat
42. Drive End Seal	VA75
43. Opposite Drive End Seal	VA75

Rotor Inspection

44. Rotor Type/Material	(Squirrel Aluminum) Squirrel Cage Aluminum Die Cast
45. Growler Test	(Pass) Pass

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

46.	Number of Rotor Bars	28	
47.	Rotor Condition	Pass	
48.	List the Parts needed for the Repair Below Va75 x2 2-6316		
49.	Signature of Technician that Disassembled Motor	Brandon Woodard	
			
Mechanical Fits- Rotor			
50.	Shaft Runout	0.001 inches	
51.	Rotor Runout		
	Drive End Bearing Fit	Rotor Body	Opposite Drive End Bearing
	0.001	0.001	0.001
52.	Coupling Fit Closest to Bearing Housing		
	0 Degrees	90 Degrees	120 Degrees
	2.125	2.125	2.125
			
53.	Coupling Fit Closest to the end of the Shaft		
	0 Degrees	60 Degrees	120 Degrees
	2.125	2.125	2.125

54. Drive End Bearing Shaft Fit

P54

0 Degrees	60 Degrees	120 Degrees
3.1501	3.1501	3.1501

Tolerance is 3.1497-3.1502



55. Drive End Bearing Shaft Fit Condition


(P) Pass

56. Opposite Drive End Bearing Shaft Fit

P56

0 Degrees	60 Degrees	120 Degrees
3.15	3.15	3.15

Tolerance is 3.1497-3.1502



57. Opposite Drive End Bearing Shaft Fit Condition



(P) Pass

58. Shaft Air Seal Fits

Drive End Air Seal	Opposite Drive End Air Seal
Pass	Pass

Mechanical Fits- Bearing Housings



59.	Drive End - Endbell Bearing Fit			P59
	0 Degrees	60 Degrees	120 Degrees	
	6.6948	6.6947	6.6948	
	Tolerance is 6.6929-6.6939			
				
60.	Drive End - Endbell Bearing Fit Condition			(F) Fail
61.	Opposite Drive End - Endbell Bearing Fit			P61
	0 Degrees	60 Degrees	120 Degrees	
	6.6947	6.6948	6.6947	
	Tolerance is 6.6929-6.6939			
				
62.	Opposite Drive End - Endbell Bearing Fit Condition			(F) Fail
63.	Bearing Cap Condition			
	Drive End Bearing Cap	Opposite Drive End Bearing Cap		
	Pass	Pass		
64.	End Bell Air Seal Fits			
	Drive End Air Seal	Opposite Drive End Air Seal		
	Pass	Pass		
65.	List Machine Work Needed Below			
	Bore and bush both end bells.			
66.	Technician			Brandon Woodard



Root Cause of Failure

67. Failure locations

Bearings

68. Root cause of failure

Old grease and heat