



Hi-Speed Industrial Service
7030 Ryburn Dr
Millington, Tn 38053
901-873-5300

AC Inspection as Found
GEORGIA PACIFIC GYPSUM
150 TEMPLE DR
CUMBERLAND, TN 37050

FolderID: 155808
FormID: 24797960



AC Inspection - Rev. 2

Completed by: Brandon Woodard on
06/16/2025

Location: Motor Shop

Serial Number: 200901200

Description: 300 HP AC

Hi-Speed Job Number:	155808
Manufacturer:	Toshiba
Product Number:	SD-10033947
Serial Number:	200901200
HP/kW:	300 (HP)
RPM:	1785 (RPM)
Frame:	S449TS
Voltage:	460
Current:	345 (Amps)
Phase:	Three
Hz:	60 (Hz)
Service Factor:	1.15
Enclosure:	TEFC
# of Leads:	6
J-box Included:	None
Coupling/Sheave:	None
Date Received:	06/12/2025
Bearing RTDs:	No
Stator RTDs:	No
Repair Stage:	Teardown Inspection
Rewind:	Yes
Shaft Machined Fit Repairs Required:	No
Bearing Housing Machined Fit Repairs Required:	No
Heaters:	No
Winding Type :	Random Wound
Bearing Type:	Rolling Element

Priorities Found: ● 4 - High ● 11 - Good

Overall Condition



1. Report Date

06/13/2025

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

2. Nameplate Picture

P2



3. Photos of all six sides of the machine.

P3





4. Describe the Overall Condition of the Equipment as Received

Windings grounded. No machine work. Bearings were heavily fluted . Recommend adding aegis ring and insulated bearing.

5. Is this a UL Listed Motor (No) No

6. Is the motor water cooled or can be pressure checked before teardown (No) No

Initial Mechanical/Electrical



7. Does Shaft Turn Freely? (Y) Yes

8. Does the shaft require T.I.R in Lathe to identify additional repairs? (No) No

9. Does Shaft Have Visible Damage? (No) No

10. Assembled Shaft Runout 0.001 Inches

11. Assembled Shaft End Play 0.001 inches





12. Air Gap Variation <10% No provisions for measurement

13. Lead Condition (P) Pass





P13



14. Lead Length 24 Inches

●	15. Does it have Lugs?, If so what is the Stud Size?	(Yes) Yes	P15
	3/8"DAG		
			
	16. Lead Numbers	1-6	
●	17. Are the Leads insulated with Chico or other material	(No) No	
	18. Frame Condition	Pass	
●	19. Fan Condition	(P) Pass	P19
			
●	20. Does motor have internal fan?	(No) No	
	21. Broken or Missing Components	None	
Initial Electrical Inspection			
	22. Insulation Resistance/Megger	0 Megohms	P22
			

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

23. Winding Resistance	P23	
1-2	1-3	2-3
		
24. Perform Surge Test	(F) Fail	P24
		
25. Number of Stator Slots	72	
26. Stator Condition	Requires rewind	P26
		
27. Stator Thermistors/Ohms	N/A	
28. Stator Overloads/Ohms	N/A	
Mechanical Inspection		

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.



30. Drive End Bearing Number-	6318 C3	
31. Drive End Bearing Qty.	1	
32. Drive End Bearing Type	(Ball) Ball Bearing	
33. Drive End Lubrication Type	(Grease) Grease Lubricated	
34. Drive End Bearing Insulation or Grounding Device?	None	
35. Drive End Wavy Washer/Snap-Ring Other Retention Device?	Snap Ring	
36. Drive End Bearing Condition	heavy electrical fluting!	P36



37. Opposite Drive End Bearing Brand

P37



38. Opposite Drive End Bearing Number-	6318 C3
39. Opposite Drive End Bearing Qty.	1

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

40. Opposite Drive End Bearing Type	(Ball) Ball Bearing	
41. Opposite Drive End Lubrication Type	(Grease) Grease Lubricated	
42. Opposite Drive End Bearing Insulation or Grounding Device?	None	
43. Opposite Drive End Wavy Washer/Snap-Ring Other Retention Device?	Snap Ring	
44. Opposite Drive End Bearing Condition	heavy electrical fluting!	P44

45. Drive End Seal	VA90	P45
--------------------	------	-----

46. Opposite Drive End Seal	None	
-----------------------------	------	--

Rotor Inspection

47. Rotor Type/Material	(Squirrel Aluminum) Squirrel Cage Aluminum Die Cast	
48. Growler Test	(Pass) Pass	
49. Number of Rotor Bars	58	
50. Rotor Condition	Pass	
51. List the Parts needed for the Repair Below 6318 C3 6318 C3 insulated Aegis ring SGR-100.1-3FH [Mfr# SGR-100.1-129.5-3FH] VA90		
52. Signature of Technician that Disassembled Motor	Brandon Woodard	

Mechanical Fits- Rotor



53. Shaft Runout **0.001 inches**

54. Rotor Runout

Drive End Bearing Fit	Rotor Body	Opposite Drive End Bearing
0.002	0.002	0.002

55. Coupling Fit Closest to Bearing Housing

P55

0 Degrees	90 Degrees	120 Degrees
2.375	2.375	2.375



56. Coupling Fit Closest to the end of the Shaft

0 Degrees	60 Degrees	120 Degrees
2.375	2.375	2.375

57. Drive End Bearing Shaft Fit

P57

0 Degrees	60 Degrees	120 Degrees
3.5438	3.5438	3.5438

Tolerance is 3.5434-3.5440



58. Drive End Bearing Shaft Fit Condition

(P) Pass

59. Opposite Drive End Bearing Shaft Fit

0 Degrees	60 Degrees	120 Degrees
3.5435	3.5435	3.5435

Tolerance is 3.5434-3.5440



60. Opposite Drive End Bearing Shaft Fit Condition

(P) Pass

61. Shaft Air Seal Fits

Drive End Air Seal	Opposite Drive End Air Seal
Pass	Pass

Mechanical Fits- Bearing Housings



62. Drive End - Endbell Bearing Fit

P62

0 Degrees	60 Degrees	120 Degrees
7.4816	7.4816	7.4816

Tolerance is 7.4803-7.4814. .0002 over tolerance recommend no machine work.



63. Drive End - Endbell Bearing Fit Condition

(P) Pass

64. Opposite Drive End - Endbell Bearing Fit

0 Degrees	60 Degrees	120 Degrees
7.4813	7.4813	7.4813

Tolerance is 7.4803-7.4814



66. Bearing Cap Condition

Drive End Bearing Cap

Opposite Drive End Bearing Cap

Pass**Pass**

67. End Bell Air Seal Fits

Drive End Air Seal

Opposite Drive End Air Seal

Pass**Pass**

68. List Machine Work Needed Below

None recommend!

69. Technician

Brandon Woodard**Root Cause of Failure**

70. Failure locations

Windings blown

71. Root cause of failure

N/A