

LR Field Services

Prepared for West coffee

480 Exchange Ave
Conway AR 72032

Table of Contents

Field Service Ticket	1.0
AC Recondition Repair Report - <i>MOTOR SHOP LR</i>	2.0
Field Service Ticket	3.0



Hi-Speed Industrial Service
7030 Ryburn Dr
Millington, Tn 38053
901-873-5300

Field Service Ticket

FolderID: 104651
FormID: 24516628

West coffee
480 Exchange Ave
Conway, AR 72032

Job Information

- | | |
|------------------------|---------------|
| 1. Hi-Speed Job Number | 104651 |
| 2. Asset Type | Siemens motor |
| 3. Make | |




- | | |
|---------------------------------|--|
| 4. Model | |
| 5. Serial Number | |
| 6. Customer Asset ID/Asset Name | |

Service Call Details

- | | |
|-----------------------|----------------------------|
| 7. Service Objectives | To assist in pulling motor |
|-----------------------|----------------------------|

- | | |
|-----------------------|--|
| 8. Services Performed | |
|-----------------------|--|



- | | |
|---------------------------------------|--|
| 9. Service Technician Recommendations | |
|---------------------------------------|--|

Approval Signatures

- | | |
|----------------------------------|-------------------------|
| 10. Service Technician Signature | Trevor Hall Chris Wiley |
|----------------------------------|-------------------------|

- | | |
|------------------------|----------------|
| 11. Customer Signature | Philip Patrick |
|------------------------|----------------|

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

A handwritten signature in black ink, appearing to read "John R. [unclear]", enclosed within a thin black rectangular border.



Hi-Speed Industrial Service
7030 Ryburn Dr
Millington, Tn 38053
901-873-5300

AC Recondition Repair Report

FolderID: 104651
FormID: 24518605

West coffee
480 Exchange Ave
Conway, AR 72032
MOTOR SHOP LR

General

1. Job Number	104651
2. Report Date	05/21/2025
3. Customer	West Coffee

Name Plate Information

4. Manufacturer	Siemens
5. Model	1LE15232DB234AB4-7
6. Serial Number	1CV3282B
7. Horsepower	125 HP
8. KW	90 KW
9. Volts	460 Volts
10. Amps	136 Amps
11. RPM	1788 RPM
12. Frame	IP55
13. Enclosure	TEFC
14. Cycles	60 HZ
15. Phase	3 PH
16. Service Factor	0.87
17. Motor Mount Position	horizontal

Initial Inspection

18. Number of Leads
19. Lead Length
20. Lead Size
21. Lead Condition
22. Lead Markings
23. Lug Size, Condition, and Type
24. Winding RTD's
25. Winding Rtd's Condition
26. Shaft Run Out
27. Does Shaft Turn Freely
28. Does Shaft Have Visible Damage
29. Bearing Rtd's
30. Bearing Rtd's Condition
31. Contamination
32. Frame Condition
33. Fan Condition
34. Broken or missing components

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

Printed on 05/27/2025

Powered by [INSPECTALL](#)

2.0

Initial Electric Test

- 35. Resistance to Ground
- 36. Winding Resistance 1-2
- 37. Winding Resistance 2-3
- 38. Winding Resistance 1-3
- 39. Resistive Imbalance
- 40. Hi-Pot
- 41. Surge Test
- 42. Stator Condition
- 43. Failure Location

Initial Rotor Inspection

- 44. Rotor Type
- 45. Air Gap <10% Variation
- 46. Number of Rotor Bars
- 47. Number of Broken Rotor Bars
- 48. Growler Test
- 49. Rotor Condition

Mechanical Inspection

- 50. Bearing Manufacture
- 51. Bearing DE Size
- 52. Bearing DE Type
- 53. DE Bearing Qty.
- 54. Bearing ODE Size
- 55. Bearing ODE Type
- 56. ODE Bearing Qty.
- 57. Insulated Bearing
- 58. Lubrication Type
- 59. Grease Condition
- 60. Bearing Retainers
- 61. Shaft Grounding Device
- 62. DE Seal
- 63. DE Seal Type/Size
- 64. ODE Seal
- 65. ODE Seal Type/Size

Root Cause of Failure

- 66. Component Failure
- 67. Cause of Failure
- 68. Comments
- 69. Service Technician

Machine Fit Inspection Report

- 70. Shaft Run Out
- 71. Initial Shaft Run Out
- 72. Final Shaft Run Out
- 73. DE Bearing Shaft Fit
- 74. DE Initial Shaft Bearing Fit Size 1
- 75. DE Initial Shaft Bearing Fit Size 2
- 76. DE Initial Shaft Bearing Fit Size 3
- 77. DE Final Shaft Bearing Fit Size 1

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

78.	DE Finial Shaft Bearing Fit Size 2
79.	DE Finial Shaft Bearing Fit Size 3
80.	ODE Bearing Shaft Fit
81.	ODE Initial Shaft Bearing Fit Size 1
82.	ODE Initial Shaft Bearing Fit Size 2
83.	ODE Initial Shaft Bearing Fit Size 3
84.	ODE Finial Shaft Bearing Fit Size 1
85.	ODE Finial Shaft Bearing Fit Size 2
86.	ODE Finial Shaft Bearing Fit Size 3
87.	DE Air Seal Shaft Fit
88.	DE Initial Air Seal Shaft Size
89.	DE Final Air Seal Shaft Size
90.	ODE Air Seal Shaft Fit
91.	ODE Initial Air Seal Shaft Size
92.	ODE Final Air Seal Shaft Size
93.	DE Endbell Fit
94.	DE Initial Endbell Fit Size 1
95.	DE Initial Endbell Fit Size 2
96.	DE Initial Endbell Fit Size 3
97.	DE Final Endbell Fit Size 1
98.	DE Finial Endbell Fit Size 2
99.	DE Final Endbell Fit Size 3
100.	DE Endbell Fit Insulated
101.	DE Endbell Air Seal Fit
102.	Initial Endbell Air Seal Fit Size
103.	Finial Endbell Air Seal Fit Size
104.	ODE Endbell Fit
105.	ODE Initial Endbell Fit Size 1
106.	ODE Initial Endbell Fit Size 2
107.	ODE Initial Endbell Fit Size 3
108.	ODE Final Endbell Fit Size 1
109.	ODE Final Endbell Fit Size 2
110.	ODE Final Endbell Fit Size 3
111.	ODE Endbell Fit Insulated
112.	ODE Endbell Air Seal Fit
113.	ODE Initial Endbell Seal Fit Size
114.	ODE Finial Endbell Seal Fit Size
115.	Foot Flatness
116.	Foot Condition
117.	Flange Condition
118.	Service Technician
Balancing Report	
119.	Balance Type
120.	Balance Operating Speed
121.	Start Left End
122.	Start Right End
123.	Balancing Specification
124.	Finish Left End

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

125. Finish Right End
126. Service Technician
Assembly and Final Test
127. Meggar Testing Reading
128. Surge Test
129. Hi-Pot
130. Winding Resistance 1-2
131. Winding Resistance 2-3
132. Winding Resistance 1-3
133. Test Run Voltage Phase A
134. Test Run Amps A
135. Test Run Voltage Phase B
136. Test Run Amps B
137. Test Run Voltage Phase C
138. Test Run Amps C
139. DE Horizontal Vibration Reading
140. DE Vertical Vibration Reading
141. DE Axial Vibration Reading
142. ODE Horizontal Vibration Reading
143. ODE Vertical Vibration Reading
144. ODE Axial Vibration Reading
145. Ambient Temp at start of Test Run
146. Temp at 5 minutes
147. Temp at 10 minutes
148. Temp at 15 minutes
149. Temp at 20 minutes
150. Temp at 25 minutes
151. Temp at 30 minutes
152. Temp at 35 minutes
153. Temp at 40 minutes
154. Temp at 45 minutes
155. Temp at 50 minutes
156. Temp at 55 minutes
157. Temp at 60 minutes
158. Motor Paint
159. Service Technician



Hi-Speed Industrial Service
7030 Ryburn Dr
Millington, Tn 38053
901-873-5300

Field Service Ticket

FolderID: 104651
FormID: 24556528

West coffee
480 Exchange Ave
Conway, AR 72032

Job Information

1. Hi-Speed Job Number	104651
2. Asset Type	Siemens motor
3. Make	
4. Model	
5. Serial Number	
6. Customer Asset ID/Asset Name	

Service Call Details

7. Service Objectives

To install and test run motor.

8. Services Performed

We installed the motor, wired it up and laser aligned the pulleys. When we went to test run it there was an issue with it not starting. I then went to look at the vfd in another part of the plant and noticed that it had blown the bottom of an IGBT out and blown the breaker when the motor initially blew up. Customer need both pieces replaced.



Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

Printed on 05/27/2025

Powered by [INSPECTALL](#)

3.0



9. Service Technician Recommendations

Replace vfd and breaker. Check motor rotation. Install belts and test run. Check amperage.

Approval Signatures

10. Service Technician Signature

Trevor Hall

11. Customer Signature

Michael Cody