



Hi-Speed Industrial Service
7030 Ryburn Dr
Millington, Tn 38053
901-873-5300

AC Recondition Repair Report

FolderID: 98173
FormID: 10572705

Arauco-Malvern MDF (10298)
1275 Willamette Rd
Malvern, AR 72104

Priorities Found: ● 4 - High ● 6 - Good

General

1. Job Number	98173
2. Report Date	05/01/2021
3. Customer	ARAUCO

Name Plate Information

4. Manufacturer	SIEMENS	P5
-----------------	---------	----




Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.





5. Model	1LA04454SD42
6. Serial Number	7K516623210836
7. Horsepower	150
8. KW	
9. Volts	460
10. Amps	170
11. RPM	1780
12. Frame	445TS
13. Enclosure	TEFC
14. Cycles	60
15. Phase	3

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.





16.	Service Factor	1.15
17.	Motor Mount Position	
Initial Inspection		
18.	Number of Leads	6
19.	Lead Length	16 Inches
20.	Lead Size	1
21.	Lead Condition	(P) Pass
22.	Lead Markings	tape numbers 1-3
23.	Lug Size, Condition, and Type	3/8 good
24.	Winding RTD's	(NA) Not Applicable
25.	Winding Rtd's Condition	
26.	Shaft Run Out	
27.	Does Shaft Turn Freely	yes
28.	Does Shaft Have Visible Damage	no
29.	Bearing Rtd's	(NA) Not Applicable
30.	Bearing Rtd's Condition	
31.	Contamination	
32.	Frame Condition	
33.	Fan Condition	(F) Fail
34.	Broken or missing components	Fan shattered fan cover bolts broken off in ODE end bell
Initial Electric Test		
35.	Resistance to Ground	Mohm
		
36.	Winding Resistance 1-2	
37.	Winding Resistance 2-3	
38.	Winding Resistance 1-3	
39.	Resistive Imbalance	
40.	Hi-Pot	
41.	Surge Test	
42.	Stator Condition	
43.	Failure Location	
Initial Rotor Inspection		
44.	Rotor Type	cast aluminum
45.	Air Gap <10% Variation	

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.



46.	Number of Rotor Bars	36
47.	Number of Broken Rotor Bars	0
● 48.	Growler Test	(P) Pass
● 49.	Rotor Condition	(P) Pass
Mechanical Inspection		
50.	Bearing Manufacture	P1
		
51.	Bearing DE Size	6316 2Z
52.	Bearing DE Type	ball
53.	DE Bearing Qty.	1
54.	Bearing ODE Size	6316
55.	Bearing ODE Type	ball
56.	ODE Bearing Qty.	1
57.	Insulated Bearing	
58.	Lubrication Type	polyrex
● 59.	Grease Condition	(F) Fail
60.	Bearing Retainers	
61.	Shaft Grounding Device	(NA) Not Applicable
62.	DE Seal	(NA) Not Applicable
63.	DE Seal Type/Size	
64.	ODE Seal	(NA) Not Applicable
65.	ODE Seal Type/Size	
Root Cause of Failure		
66.	Component Failure	end bell fits
67.	Cause of Failure <i>Moisture</i>	
68.	Comments <i>Sleeve Both end bells, 2x 63162Z, extract broken bolts for fan cover, replace fan (Aluminum 2.55"/64mm shaft size)</i>	
69.	Service Technician	David Maclin
		

Machine Fit Inspection Report


Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

70.	Shaft Run Out	
71.	Initial Shaft Run Out	
72.	Final Shaft Run Out	
	73. DE Bearing Shaft Fit	(P) Pass
74.	DE Initial Shaft Bearing Fit Size 1	3.1499 "
75.	DE Initial Shaft Bearing Fit Size 2	3.1497 "
76.	DE Initial Shaft Bearing Fit Size 3	3.1499 "
77.	DE Finial Shaft Bearing Fit Size 1	
78.	DE Finial Shaft Bearing Fit Size 2	
79.	DE Finial Shaft Bearing Fit Size 3	
	80. ODE Bearing Shaft Fit	(P) Pass
81.	ODE Initial Shaft Bearing Fit Size 1	3.1499 "
82.	ODE Initial Shaft Bearing Fit Size 2	3.15 "
83.	ODE Initial Shaft Bearing Fit Size 3	3.1501 "
84.	ODE Finial Shaft Bearing Fit Size 1	
85.	ODE Finial Shaft Bearing Fit Size 2	
86.	ODE Finial Shaft Bearing Fit Size 3	
87.	DE Air Seal Shaft Fit	
88.	DE Initial Air Seal Shaft Size	
89.	DE Final Air Seal Shaft Size	
90.	ODE Air Seal Shaft Fit	
91.	ODE Initial Air Seal Shaft Size	
92.	ODE Final Air Seal Shaft Size	
	93. DE Endbell Fit	(F) Fail
94.	DE Initial Endbell Fit Size 1	
95.	DE Initial Endbell Fit Size 2	
96.	DE Initial Endbell Fit Size 3	
97.	DE Final Endbell Fit Size 1	
98.	DE Finial Endbell Fit Size 2	
99.	DE Final Endbell Fit Size 3	
100.	DE Endbell Fit Insulated	
101.	DE Endbell Air Seal Fit	
102.	Initial Endbell Air Seal Fit Size	
103.	Finial Endbell Air Seal Fit Size	
	104. ODE Endbell Fit	(F) Fail
105.	ODE Initial Endbell Fit Size 1	
106.	ODE Initial Endbell Fit Size 2	
107.	ODE Initial Endbell Fit Size 3	
108.	ODE Final Endbell Fit Size 1	
109.	ODE Final Endbell Fit Size 2	
110.	ODE Final Endbell Fit Size 3	
111.	ODE Endbell Fit Insulated	
112.	ODE Endbell Air Seal Fit	
113.	ODE Initial Endbell Seal Fit Size	
114.	ODE Finial Endbell Seal Fit Size	
115.	Foot Flatness	
116.	Foot Condition	
117.	Flange Condition	

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

118.	Service Technician		
Balancing Report			
119.	Balance Type		
120.	Balance Operating Speed		
121.	Start Left End		
122.	Start Right End		
123.	Balancing Specification		
124.	Finish Left End		
125.	Finish Right End		
126.	Service Technician		
Assembly and Final Test			
127.	Megger Testing Reading		
128.	Surge Test		
129.	Hi-Pot		
130.	Winding Resistance 1-2		
131.	Winding Resistance 2-3		
132.	Winding Resistance 1-3		
133.	Test Run Voltage Phase A		
134.	Test Run Amps A		
135.	Test Run Voltage Phase B		
136.	Test Run Amps B		
137.	Test Run Voltage Phase C		
138.	Test Run Amps C		
139.	DE Horizontal Vibration Reading		
140.	DE Vertical Vibration Reading		
141.	DE Axial Vibration Reading		
142.	ODE Horizontal Vibration Reading		
143.	ODE Vertical Vibration Reading		
144.	ODE Axial Vibration Reading		
145.	Ambient Temp at start of Test Run		
146.	Temp at 5 minutes		
147.	Temp at 10 minutes		
148.	Temp at 15 minutes		
149.	Temp at 20 minutes		
150.	Temp at 25 minutes		
151.	Temp at 30 minutes		
152.	Temp at 35 minutes		
153.	Temp at 40 minutes		
154.	Temp at 45 minutes		
155.	Temp at 50 minutes		
156.	Temp at 55 minutes		
157.	Temp at 60 minutes		
	158. Motor Paint	(P) Pass	P136

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.



159. Service Technician

Terrence. Holland

L. Hill