

AC Recondition Repair Report

FolderID: 98243 FormID: 10689435

7030 Ryburn Dr Millington, Tn 38053 901-873-5300

Hi-Speed Industrial Service


Riviana Foods 28 W. White Oak st Brinkley, AR 72021

Priorities Found: 1 - High

8 - Good

3		
General		
1. Job Number	98243	
2. Report Date	05/19/2021	
3. Customer	RIVIANA FOODS	
Name Plate Information		

o **FLYGT** P5 Manufacturer




























































	5.	Model	3102.170-0630034	
	6.	Serial Number	3102.170-0693 263	
	7.	Horsepower	6	
	8.	KW		
	9.	Volts	460	
1	10.	Amps	7.5	
1	11.	RPM	3455	
1	12.	Frame		
1	13.	Enclosure	SUB PUMP	
1	14.	Cycles	60	
1	15.	Phase	3	
1	16.	Service Factor		
1	17.	Motor Mount Position		
Initi	ial lı	nspection		
1	18.	Number of Leads	7	
1	19.	Lead Length	Inches	
2	20.	Lead Size		
• 2	21.	Lead Condition	(F) Fail	
-		Water		
2	22.	Lead Markings	Red lead #2, Black lead #3, and White #1 power.	
-	1	Orange and blue are sensor leads.	Green and white with black stripe are ground.	
2	23.	Lug Size, Condition, and Type		
2	24.	Winding RTD's		
2	25.	Winding Rtd's Condition		
2	26.	Shaft Run Out		
2	27.	Does Shaft Turn Freely	no	
2	28.	Does Shaft Have Visible Damage	no	
2	29.	Bearing Rtd's	(NA) Not Applicable	
• 3	30.	Bearing Rtd's Condition	(NA) Not Applicable	
3	31.	Contamination		
		Water and debris.		
• 3	32.	Frame Condition	(P) Pass	
• 3	33.	Fan Condition	(NA) Not Applicable	
3	34.	Broken or missing components		
		Cutter ring missing		

Initial	Electric Test		
35.	Resistance to Ground	0.11 Mohm	
36.	Winding Resistance 1-2		
37.	Winding Resistance 2-3		
38.	Winding Resistance 1-3		
39.	Resistive Imbalance		
40.	Hi-Pot		
4 1.	Surge Test	(NA) Not Applicable	
42.	Stator Condition	good	
43.	Failure Location	windings	
Initial	Rotor Inspection		
44.	Rotor Type	laminate squirrel cage	
45.	Air Gap <10% Variation		
46.	Number of Rotor Bars		
47.	Number of Broken Rotor Bars	0	
4 8.	Growler Test	(P) Pass	
4 9.	Rotor Condition	(P) Pass	
Mecha	anical Inspection	ō	
50.	Bearing Manufacture	koyo	P′



51.	Bearing DE Size	5305 Z C3	
52.	Bearing DE Type	double wide regular ball bearing	
53.	DE Bearing Qty.	1	
54.	Bearing ODE Size	6305 2Z/C3	



56.	ODE Bearing Qty.	1
57.	Insulated Bearing	no
58.	Lubrication Type	oil
59.	Grease Condition	(NA) Not Applicable
60.	Bearing Retainers	(Y) Yes
61.	Shaft Grounding Device	(NA) Not Applicable
62.	DE Seal	
63.	DE Seal Type/Size	
64.	ODE Seal	
65.	ODE Seal Type/Size	

Root Cause of Failure

66. Component Failure seals failed

67. Cause of Failure

Debris became lodged in between the cutter and the impeller causing motor to lock up. Also both seals failed on D.E. shaft in conjunction the power cord grommet seals, which allowed water to enter inside the stator windings resulting in an electrical short.

68. Comments

Rewind stator, and replace power cord. 28'- 7C / 12 AWG. Replace all o rings and seals. Replace worn impeller.

69. Service Technician Terrence. Hollnd

Luna Holland

Machine Fit Inspection Report

- 70. Shaft Run Out
- 71. Initial Shaft Run Out
- 72. Final Shaft Run Out
- 73. DE Bearing Shaft Fit
- 74. DE Initial Shaft Bearing Fit Size 1
- 75. DE Initial Shaft Bearing Fit Size 2
- 76. DE Initial Shaft Bearing Fit Size 3
- 77. DE Finial Shaft Bearing Fit Size 1
- 78. DE Finial Shaft Bearing Fit Size 2
- 79. DE Finial Shaft Bearing Fit Size 3

80.	ODE Bearing Shaft Fit
81.	ODE Initial Shaft Bearing Fit Size 1
82.	ODE Initial Shaft Bearing Fit Size 2
83.	ODE Initial Shaft Bearing Fit Size 3
84.	ODE Finial Shaft Bearing Fit Size 1
85.	ODE Finial Shaft Bearing Fit Size 2
86.	ODE Finial Shaft Bearing Fit Size 3
87.	DE Air Seal Shaft Fit
88.	DE Initial Air Seal Shaft Size
89.	DE Final Air Seal Shaft Size
90.	ODE Air Seal Shaft Fit
91.	ODE Initial Air Seal Shaft Size
92.	ODE Final Air Seal Shaft Size
93.	DE Endbell Fit
94.	DE Initial Endbell Fit Size 1
95.	DE Initial Endbell Fit Size 2
96.	DE Initial Endbell Fit Size 3
97.	DE Final Endbell Fit Size 1
98.	DE Finial Endbell Fit Size 2
99.	DE Final Endbell Fit Size 3
100.	DE Endbell Fit Insulated
101.	DE Endbell Air Seal Fit
102.	Initial Endbell Air Seal Fit Size
103.	Finial Endbell Air Seal Fit Size
104.	ODE Endbell Fit
105.	ODE Initial Endbell Fit Size 1
106.	ODE Initial Endbell Fit Size 2
107.	ODE Initial Endbell Fit Size 3
108.	ODE Final Endbell Fit Size 1
109.	ODE Final Endbell Fit Size 2
110.	ODE Final Endbell Fit Size 3
111.	ODE Endbell Fit Insulated
112.	ODE Endbell Air Seal Fit
	ODE Initial Endbell Seal Fit Size
114.	ODE Finial Endbell Seal Fit Size
	Foot Flatness
	Foot Condition
	Flange Condition
	Service Technician
	ing Report
	Balance Type
	Balance Operating Speed
	Start Left End
	Start Right End
	Balancing Specification
	Finish Left End
	Finish Right End Mills
	Service Technician
120.	

Assem	bly and Final Test
127.	Meggar Testing Reading
128.	Surge Test
129.	Hi-Pot
130.	Winding Resistance 1-2
131.	Winding Resistance 2-3
132.	Winding Resistance 1-3
133.	Test Run Voltage Phase A
134.	Test Run Amps A
135.	Test Run Voltage Phase B
136.	Test Run Amps B
137.	Test Run Voltage Phase C
138.	Test Run Amps C
139.	DE Horizontal Vibration Reading
140.	DE Vertical Vibration Reading
141.	DE Axial Vibration Reading
142.	ODE Horizontal Vibration Reading
143.	ODE Vertical Vibration Reading
144.	ODE Axial Vibration Reading
145.	Ambient Temp at start of Test Run
146.	Temp at 5 minutes
147.	Temp at 10 minutes
148.	Temp at 15 minutes Degrees F.
149.	Temp at 20 minutes
150.	Temp at 25 minutes
151.	Temp at 30 minutes
152.	Temp at 35 minutes
153.	Temp at 40 minutes
154.	Temp at 45 minutes
155.	Temp at 50 minutes
156.	Temp at 55 minutes
157.	Temp at 60 minutes
158.	Motor Paint
159.	Service Technician

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.