



Hi-Speed Industrial Service
7030 Ryburn Dr
Millington, Tn 38053
901-873-5300

AC Recondition As Found

Sage V Foods

5901 SLOAN DRIVE

LITTLE ROCK, AR 72206

FolderID: 99797
FormID: 13597507

AC Recondition - Rev. 2

Location: MOTOR SHOP LR

Serial Number: C0906200018

Description: 50HP Baldor 1800RPM 326TDZ

Hi-Speed Job Number: 99797

Manufacturer: Baldor

Product Number: 12F654W829G1

Spec/ID #: 12F654W829G1

Serial Number: C0906200018

HP/kW: 50 (HP)

RPM: 1775 (RPM)

Frame: 326TDZ

Voltage: 230 / 460

Current: 114/57

Phase: Three

Hz: 60 (Hz)

Service Factor: 1.00

Enclosure: TEFC

J-box Included: Complete

Coupling/Sheave: None

Date Received: 05/13/2022

Bearing RTDs: No

Stator RTDs: No

Repair Stage: Teardown Inspection

Heaters: No

Winding Type : Random Wound

Bearing Type: Rolling Element

Priorities Found: ● 1 - High ● 8 - Good

Overall Condition



1. Report Date

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

Printed on 5/23/2022

Powered by [INSPECTALL](#)

Page 1 of 7

2. Nameplate Picture

P21



3. Describe the Overall Condition of the Equipment as Received

Shaft excessively bent...greater than 2.987

Initial Mechanical/Electrical



4. Does Shaft Turn Freely?

(Yes) Yes

P1



5. Does Shaft Have Visible Damage?

(Yes) Yes

P12

Bent key way. Chunk missing out of shaft.



6. Assembled Shaft Runout

2.987 Inches

7. Assembled Shaft End Play

0 inches








8. Air Gap Variation <10%

9. Lead Condition

(P) Pass

P31



10.	Lead Length	10.5 Inches											
11.	Frame Condition	good											
12.	Fan Condition	(P) Pass			P52								
<div></div>													
13.	Broken or Missing Components	in pro seals worn			P56								
<div></div>													
Initial Electrical Inspection <div></div>													
14.	Insulation Resistance/Megger	Megohms			P5								
<div></div>													
15.	Winding Resistance	<table><tr><th></th><th>1-2</th><th>1-3</th><th>2-3</th></tr><tr><td></td><td></td><td></td><td></td></tr></table>				1-2	1-3	2-3					
	1-2	1-3	2-3										
16.	Perform Surge Test	(P) Pass			P32								
<div></div>													
17.	Stator Condition	pass			P39								
<div></div>													

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

Mechanical Inspection

18. Drive End Bearing Number-

63122RSR

P8



19. Drive End Bearing Qty.

1

20. Drive End Bearing Type

(Ball) Ball Bearing

P20



21. Drive End Lubrication Type

(Grease) Grease Lubricated

22. Drive End Bearing Insulation or Grounding Device?

none

23. Drive End Wavy Washer/Snap-Ring Other Retention Device?

one

P36



24. Drive End Bearing Condition

fail

P41



25. Opposite Drive End Bearing Number-

P46



26. Opposite Drive End Bearing Qty.

1

P47

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.



27. Opposite Drive End Bearing Type

(Ball) Ball Bearing

28. Opposite Drive End Lubrication Type

(Grease) Grease Lubricated

P51



29. Opposite Drive End Bearing Insulation or Grounding Device?

30. Opposite Drive End Wavy Washer/Snap-Ring Other Retention Device?

P54



31. Opposite Drive End Bearing Condition

P55



32. Drive End Seal

worn/ replace

P57





Rotor Inspection

- | | |
|---|--|
| 34. Rotor Type/Material | (Squirrel Aluminum) Squirrel
Cage Aluminum Die Cast |
| 35. Growler Test | (Pass) Pass |
| 36. Number of Rotor Bars | 40 |
| 37. Rotor Condition | fail. shaftbent |
| 38. List the Parts needed for the Repair Below
<i>In pro seal,</i> | |
| 39. Signature of Technician that Disassembled Motor | Terrence. Holland |

Mechanical Fits- Rotor

- | | | | |
|--|-----------------------------|----------------------------|--|
| 40. Shaft Runout | 2 inches | | |
| 41. Rotor Runout | | | |
| Drive End Bearing Fit | Rotor Body | Opposite Drive End Bearing | |
| 42. Coupling Fit Closest to Bearing Housing | | | |
| 0 Degrees | 90 Degrees | 120 Degrees | |
| 43. Coupling Fit Closest to the end of the Shaft | | | |
| 0 Degrees | 60 Degrees | 120 Degrees | |
| 44. Drive End Bearing Shaft Fit | | | |
| 0 Degrees | 60 Degrees | 120 Degrees | |
| 2.3625 | 2.3626 | 2.3625 | |
| 45. Drive End Bearing Shaft Fit Condition | (P) Pass | | |
| 46. Opposite Drive End Bearing Shaft Fit | | | |
| 0 Degrees | 60 Degrees | 120 Degrees | |
| 2.166 | 2.1659 | 2.166 | |
| 47. Opposite Drive End Bearing Shaft Fit Condition | (P) Pass | | |
| 48. Shaft Air Seal Fits | | | |
| Drive End Air Seal | Opposite Drive End Air Seal | | |

Mechanical Fits- Bearing Housings

49.	Drive End - Endbell Bearing Fit		
	0 Degrees	60 Degrees	120 Degrees
	5.1187	5.1189	5.1188
50.	Drive End - Endbell Bearing Fit Condition		(P) Pass
51.	Opposite Drive End - Endbell Bearing Fit		
	0 Degrees	60 Degrees	120 Degrees
	4.7247	4.7249	4.7249
52.	Opposite Drive End - Endbell Bearing Fit Condition		(P) Pass
53.	Bearing Cap Condition		
	Drive End Bearing Cap	Opposite Drive End Bearing Cap	
	pass	none	
54.	End Bell Air Seal Fits		
	Drive End Air Seal	Opposite Drive End Air Seal	
55.	List Machine Work Needed Below <i>New shaft.</i>		
56.	Technician		Terrence. Holland
			
Root Cause of Failure			
57.	Failure locations <i>D.E. Rotor shaft bent beyond repair</i>		
58.	Root cause of failure <i>Bent shaft</i>		