



Millington, TN • Little Rock, AR • P. 800-713-0103 • www.gohispeed.com

Job Information

Job #: 135055

Date: July 22, 2017

Priority: 2

Authorized OT: No

Authorized by:

Customer Information

Name: Sinclair Foods

Reason:

Contact:

Motor#:

PO#:

Name Plate Information

Manufacturer: SEW Eurodrive

Enclosure : Totally Enclosed
Fan Cooled

Enclosure Type image

Serial#: Dfv100L4

Model#:

Service Factor:

Frame: DT79

Horsepower/kW: 5

Rated RPM: 1680

Rated Amps: 13.2/6.6

Rated Voltage: 230/460



Mechanical Inspection

Does the shaft turn freely?: Yes

Containment Image:

Contaminant(s): Water

Contaminant(s) Amt: Cup



Parts Distribution



Overhead Hoist & Crane



Electric Motors



Predictive Maintenance



Mechanical Solutions

Mechanical inspection continued

Bearings DE: Worn

Bearings DE make: Other

Insulated: No

Bearings ODE: Other

Bearings ODE make: NSK

Bearing Type: Ball

Bearings Retainer: No

Thermal Protection: No

Retainer condition: —

Thermal Protection Type: —

Bearing Type Image



Bearing Make Image



Bearing Retainer Image

Thermal Protection

Lubrication Type: Oil

Thermal Protection device DE: Good

Lubrication brand inbound: Mobile Polyrex EM

Thermal Protection device ODE: Good

Lubrication brand outbound: Mobile Polyrex EM

Grease Amt DE: 0

Grease Cond. DE: Other

Grease Amt ODE: 0

Grease Cond. ODE: Other

Mechanical inspection continued

Seals DE: None

Seals ODE: None

Brg. Seats DE: Good

If DE undersized, amt.:

Brg. Seats ODE: Good

If ODE undersized, amt.:

Shaft damage: OK

Shaft Image:

Shaft damage cause: None



Bushings/sleeves DE: Ok

Bushings/sleeves ODE: Ok

Water jacket: N/A

Fan: Ok

Frame: Good



Mechanical inspection continued

Endbell fits/damage: Bad

Endbell Image:



Endbell DE size:

Endbell ODE size:

Endbell type: Single piece

Air Gap Measurements (N/A on Single Piece Endbell)

Motor Mount Position: Horizontal/Foot mount

DE @ 0

ODE @ 0

Foot/Flange condition: Ok

DE @ 90

ODE @ 90

DE @ 180

ODE @ 180

Foot flatness: Pass

DE @ 270

ODE @ 270

Missing parts?

Does Air Gap Meet Customer or EASA spec(<10% variation)?

☐ J-Box cover ☐ O-rings ☐ J-Box

—

☐ HH cover ☐ Glands ☐ None

Other missing parts

AC Electrical Inspection

Rotor Type: Cast Aluminum

Rotor Image:



Rotor Condition: Ok

Num rotor bars: 28

Num broken bars: 0

AC Electrical Inspection continued

Rotor Test Results

Visual: Pass

Growler: Pass

Single phase: Pass

Stator type: Factory

If other, stator type:

Stator condition: Ground

If other, stator condition:

Failure location: In slot

If other, stator failure:

Stator Image:



Failure Image:



Winding color: Like new

Winding image

Winding Thermal Protection: Yes

Winding condition : Solid



Thermal Protection device
DE: Good

Thermal Protection device
ODE: Good

Stator test results: Rewind

Megs incoming: Bad

Surge incoming: Bad

Hi-pot incoming: Bad

Megs after rewind: Good

Surge after rewind: Good

Hi-pot after rewind: Good

Megs at reassembly: Good

Surge at reassembly: Good

Hi-pot reassembly: Good



Millington, TN • Little Rock, AR • P. 800-713-0103 • www.gohispeed.com

AC Electrical Inspection continued

Core loss:	Good	Thermistors:	None	Thermostat:	None
RTD:	None		ohms at		degrees C
Motor Heater(s) Present:	Yes	Qty:		Voltage:	Wattage:

Winding Resistance Incoming

	Phases A to B	Phases B to C	Phases C to A	Resistive imbalance
Incoming		0.01	179.2	150
Outgoing				

Core Test Data

	Flux	Watts	Watts loss per lb	Condition of iron
Before burnout				
After burnout				

Leads/jumpers: Ok

If other, leads/jumpers:



Parts Distribution



Overhead Hoist & Crane



Electric Motors



Predictive Maintenance



Mechanical Solutions



Millington, TN • Little Rock, AR • P. 800-713-0103 • www.gohispeed.com

Conclusion

Component Failure

Insulation in stator

Cause of Failure

Water in stator

Comments

Test Run Inspection

Date

— I have merged this motor and verified that all electrical tests are complete!

Power Supply

Phase A

Phase B

Phase C

No Load Voltage

No Load Current

Temperatures: (Degrees Fahrenheit)

Test run ball bearing motors for 15 minutes.

Test Ron sleeve bearing motors for one hour.

Temperature rise at the end of test run should be less than 2° every five minutes.



Parts Distribution



Overhead Hoist & Crane



Electric Motors



Predictive Maintenance



Mechanical Solutions



Millington, TN • Little Rock, AR • P. 800-713-0103 • www.gohispeed.com

Test Run Inspection continued

Ambient Temp:

TIME	DE	Degree Change	ODE	Degree Change
START:				
5 MIN:				
10 MIN:				
15 MIN:				
20 MIN:				
25 MIN:				
30 MIN:				
35 MIN:				
40 MIN:				
45 MIN:				
50 MIN:				
55 MIN:				
60 MIN:				



Millington, TN • Little Rock, AR • P. 800-713-0103 • www.gohispeed.com

Test Run Inspection continued

Vibration Data: In./Sec-Peak (Readings should be less than .08 In/Sec Peak)

Horizontal

VDE

Axial

DE

ODE

Magnetic Center Measurements (Only Applies to Sleeve Bearing Motors)

Magnetic Center line distance from shaft shoulder

Magnetic Center line distance from all the way out mark

Magnetic Center line distance from all the way in mark

Total Motor End Float

Additional photos

Service Tech name:

Service Tech signature:



Parts Distribution



Overhead Hoist & Crane



Electric Motors



Predictive Maintenance



Mechanical Solutions